



Project Name: SMP

Project Number: RQ- 2018-04-16-37

Site Location: _____

Sampler Names:

Signature:

Special Instructions:

Samples are ambient water and not suspected to contain chlorine

Relinquished by:	Date	Time	Received by:	Date	Time	Comments
<i>[Signature]</i>	4-26-18	1408	<i>[Signature]</i>	4/26	14:08	Temp Upon Receipt : 3.5°C
Relinquished by:	Date	Time	Received by:	Date	Time	Sample Containers Intact?
						Y N