



Project Name: _____

Project Number: RQ- _____

Site Location: _____

Sampler Names:

Signature: _____

Special Instructions:

Samples are ambient water and not suspected to contain chlorine

Relinquished by:	Date	Time	Received by:	Date	Time	Comments
<i>[Signature]</i>	5-30-18	1535	<i>[Signature]</i>	5/30	15:35	Temp Upon Receipt : 0.7°C
Relinquished by:	Date	Time	Received by:	Date	Time	Sample Containers Intact?
						N