

Benchmark EnviroAnalytical, Inc.
 1001 Corporate Ave. Suite 102
 North Port, FL 34289
 (941) 625-3137 / (941) 240-3071 fax

Client Name: FDEP
Address: 2600 Blair Stone Rd.
 Tallahassee, FL, 32399
Phone: (850) 245-8085
Email: dep-overflowmicro@dep.state.fl.us

Project Name: RQ-2018-08-06-46

Project Run/Location:

Laboratory Submission #:

518060068

Station ID	Surface Water Sample Matrix ² (Fresh / Marine)	Sample Type	Enterococci E.coli (SM9223B Quantitray)		Laboratory Sample #
			E.coli = 250 mL ; Entero = 120 mL ; Fecal Coliform = 120 mL		
G3SD0091 (Philippe Creek @ Proctor Rd)	F / M / Grab	E.coli / Entero / F.coli	08/02/2018 ; 1020		
G3SD0092 (Maiteny Creek @ Geneva Rd)	F / M / Grab	E.coli / Entero / F.coli	08/02/2018 ; 1100		
G3SD0094 (North Creek @ US41)	F / M / Grab	E.coli / Entero / F.coli	08/02/2018 ; 1125		
G3SD0094 (North Creek by Oaks Creek @)	F / M / Grab	E.coli / Entero / F.coli	08/02/2018 ; 1200		
G3SD0090 (South Creek @ Haines Ave)	F / M / Grab	E.coli / Entero / F.coli	08/02/2018 ; 1235		
	F / M / Grab	E.coli / Entero / F.coli	Date & Time:		
	F / M / Grab	E.coli / Entero / F.coli	Date & Time:		
	F / M / Grab	E.coli / Entero / F.coli	Date & Time:		
	F / M / Grab	E.coli / Entero / F.coli	Date & Time:		
	F / M / Grab	E.coli / Entero / F.coli	Date & Time:		
	F / M / Grab	E.coli / Entero / F.coli	Date & Time:		

²Sample Type is used to indicate whether the sample was a grab (G) or whether it was a composite (C).

1. Sample Type: Is used to indicate whether the sample was a grab (G) or whether it was a composite (C).
2. Sample Matrix: Is used to indicate whether the sample is being discharged to drinking water (DW), groundwater (GW), surface water (SW), fresh surface water (FSW), saline surface water (SSW), soil sediment (SDS), or sludge (SLD).
3. Container Type: Is used to indicate whether the container is plastic (P) or glass (G).
4. Sample must be refrigerated or stored in ice after collection. The maximum temperature during storage should be 4°C (41°F). Under "Preservative," list any preservatives that were added to the sample container.

Laboratory Sample Acceptability:
 pH < 2.0 BEAS Temperature: 31°C

1	Collector: Ryan Brown	Date: 08/02/2018	Time: 1330	Received By: Melinda Macchaut	Date: 8/3/18	Time: 1330
2	Relinquished by: Ryan Brown	Date: 08/02/2018	Time: 1330	Received By: Melinda Macchaut	Date: 8/3/18	Time: 1330
3	Relinquished by:	Date:	Time:	Received By:	Date:	Time:
4	Relinquished by:	Date:	Time:	Received By:	Date:	Time:
5	Relinquished by:	Date:	Time:	Received By:	Date:	Time: