

FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-01-15-46
Client Project #: Okeechobee
Date Sampled: Jan 24, 2018
Jan 25, 2018; Invoice: 355456

Invoice


Description	Amount	Units	Extension
EColi-QT	51.00	10	510.00
TOTAL			510.00

This invoice is due upon receipt.

Please remit to: P.O. Box 150597
Altamonte Springs, FL 32715-0597

VISA, MasterCard, and American Express cards will be accepted.

There will be a 1.5% service charge per month on all unpaid balances.



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-01-15-46
Client Project #: Okeechobee
Date Sampled: Jan 24, 2018
Jan 25, 2018; Invoice: 355456

Report Summary

Date Received: Jan 24, 2018

FCL Project Manager: June S. Flowers


Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
355456SW1	G1SE0003	SM9223B	DDB	South Lab	Surface Water
355456SW2	G1SE0009	SM9223B	DDB	South Lab	Surface Water
355456SW3	G1SE0008	SM9223B	DDB	South Lab	Surface Water
355456SW4	G1SE0007	SM9223B	DDB	South Lab	Surface Water
355456SW5	G1SE0004	SM9223B	DDB	South Lab	Surface Water
355456SW6	G1SE0010	SM9223B	DDB	South Lab	Surface Water
355456SW7	G1SE0005	SM9223B	DDB	South Lab	Surface Water
355456SW8	G1SE0002	SM9223B	DDB	South Lab	Surface Water
355456SW9	G1SE0001	SM9223B	DDB	South Lab	Surface Water
355456SW10	G1SE0006	SM9223B	DDB	South Lab	Surface Water

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAP Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050


Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-01-15-46
Client Project #: Okeechobee
Date Sampled: Jan 24, 2018
Jan 25, 2018; Invoice: 355456

Analysis Report

Lab #: 355456SW1		Sampled: 01/24/18 10:00 AM		Desc: G1SE0003						
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	3080	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM
Lab #: 355456SW2		Sampled: 01/24/18 10:15 AM		Desc: G1SE0009						
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	8160	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM
Lab #: 355456SW3		Sampled: 01/24/18 10:40 AM		Desc: G1SE0008						
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	10.0	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM
Lab #: 355456SW4		Sampled: 01/24/18 11:15 AM		Desc: G1SE0007						
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	288	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM
Lab #: 355456SW5		Sampled: 01/24/18 12:15 PM		Desc: G1SE0004						
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	199	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM
Lab #: 355456SW6		Sampled: 01/24/18 12:45 PM		Desc: G1SE0010						
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	932	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM
Lab #: 355456SW7		Sampled: 01/24/18 01:00 PM		Desc: G1SE0005						
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	309	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM



FLOWERS CHEMICAL LABORATORIES INC.


P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-01-15-46
Client Project #: Okeechobee
Date Sampled: Jan 24, 2018
Jan 25, 2018; Invoice: 355456

Lab #: 355456SW8 Sampled: 01/24/18 01:30 PM Desc: G1SE0002										
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	332	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM
Lab #: 355456SW9 Sampled: 01/24/18 02:00 PM Desc: G1SE0001										
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	350	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM
Lab #: 355456SW10 Sampled: 01/24/18 02:20 PM Desc: G1SE0006										
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	712	mpn/100mL	10.0	10.0	10.0	10362210	SM9223B		01/24/18	03:30 PM




FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-01-15-46
Client Project #: Okeechobee
Date Sampled: Jan 24, 2018
Jan 25, 2018; Invoice: 355456



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-01-15-46
Client Project #: Okeechobee
Date Sampled: Jan 24, 2018
Jan 25, 2018; Invoice: 355456

Narrative Report

Sample Handling

Sample handling and holding time criteria were met for all samples. Samples collected by submitter. No unusual events occurred during analysis. Results were read on 1/25/18 at 11:45AM

Quality Control

Enclosed analyses met method or FCL criteria, unless otherwise denoted on the sample results. Applied data qualifiers are defined below.

Attachments

Chain of Custody

Qualifier

Meaning

U	Compound was analyzed for but not detected.
J	Estimated value; one or more QC components associated with this data value exceed current QC limits.
Q	Sample held beyond the accepted holding time.
L	Off-scale high; reported concentration exceeds the highest standard.
V	Analyte was detected in both the sample and the associated method blank.
W	The dissolved oxygen blank was above 0.2 mg/L but less than the MDL.
Z	Too numerous to count colonies on plate.
A	Absent
P	Present
T	Value reported is less than the statistical method detection limit. Reported for informational purposes only.
M	Value reported is greater than the statistical method detection limit, but less than the reported MDL.
G	The greatest of the dilutions performed did not yield sufficient oxygen depletion for valid data.
S	The least of the dilutions performed did not yield sufficient oxygen residual for valid data.
O	Result is greater than (over) the specified value.
I	Reported value is between the laboratory method detection limit and the laboratory practical quantitation limit.
B	Results based upon colony plate count outside ideal range.
Y	The laboratory analysis was from an improperly preserved sample. The data may not be accurate.