

FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-09-24 & 2018-10-80
Client Project #: SMP-South Lakes & SMP-St Johns
Date Sampled: Oct 4, 2018
Oct 5, 2018; Invoice: 380165

Report Summary

Date Received: Oct 4, 2018

FCL Project Manager: Michael D. Conner


Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
380165AQ1	Lab Blank Ecoli	SM9223B	DDB	South Lab	Water
380165SW1	G3SE0015	SM9223B	DDB	South Lab	Surface Water
380165SW2	G3SE0001	SM9223B	DDB	South Lab	Surface Water
380165SW3	G3SE0003	SM9223B	DDB	South Lab	Surface Water
380165SW4	Lab Dup 0003	SM9223B	DDB	South Lab	Surface Water
380165SW5	Blue Cypress	SM9223B	DDB	South Lab	Surface Water
380165SW6	G3SE0026	SM9223B	DDB	South Lab	Surface Water
380165SW7	G3SE0025	SM9223B	DDB	South Lab	Surface Water
380165SW8	G3SE0024	SM9223B	DDB	South Lab	Surface Water

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAP Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050


Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-09-24 & 2018-10-80
Client Project #: SMP-South Lakes & SMP-St Johns
Date Sampled: Oct 4, 2018
Oct 5, 2018; Invoice: 380165

Analysis Report

Lab #: 380165AQ1	Sampled: 10/04/18 02:55 PM	Desc: Lab Blank Ecoli								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	1.00 U	mpn/100mL	1.00	1.00	1.00	10385032	SM9223B		10/04/18	04:35 PM
Lab #: 380165SW1	Sampled: 10/04/18 11:40 AM	Desc: G3SE0015								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	14.8	mpn/100mL	1.00	1.00	1.00	10385032	SM9223B		10/04/18	04:35 PM
Lab #: 380165SW2	Sampled: 10/04/18 12:40 PM	Desc: G3SE0001								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	95.9	mpn/100mL	1.00	1.00	1.00	10385032	SM9223B		10/04/18	04:35 PM
Lab #: 380165SW3	Sampled: 10/04/18 01:30 PM	Desc: G3SE0003								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	345	mpn/100mL	1.00	1.00	1.00	10385032	SM9223B		10/04/18	04:35 PM
Lab #: 380165SW4	Sampled: 10/04/18 02:55 PM	Desc: Lab Dup 0003								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	308	mpn/100mL	1.00	1.00	1.00	10385032	SM9223B		10/04/18	04:35 PM
Lab #: 380165SW5	Sampled: 10/04/18 12:45 PM	Desc: Blue Cypress								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	1.00 U	mpn/100mL	1.00	1.00	1.00	10385032	SM9223B		10/04/18	04:35 PM
Lab #: 380165SW6	Sampled: 10/04/18 01:30 PM	Desc: G3SE0026								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	77.6	mpn/100mL	1.00	1.00	1.00	10385032	SM9223B		10/04/18	04:35 PM



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945


PO #: RQ-2018-09-24 & 2018-10-80
Client Project #: SMP-South Lakes & SMP-St Johns
Date Sampled: Oct 4, 2018
Oct 5, 2018; Invoice: 380165

Lab #: 380165SW7 **Sampled:** 10/04/18 01:50 PM **Desc:** G3SE0025

Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed
E. Coli	140	mpn/100mL	1.00	1.00	1.00	10385032	SM9223B		10/04/18 04:35 PM

Lab #: 380165SW8 **Sampled:** 10/04/18 02:00 PM **Desc:** G3SE0024

Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed
E. Coli	517	mpn/100mL	1.00	1.00	1.00	10385032	SM9223B		10/04/18 04:35 PM




FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-09-24 & 2018-10-80
Client Project #: SMP-South Lakes & SMP-St Johns
Date Sampled: Oct 4, 2018
Oct 5, 2018; Invoice: 380165



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2018-09-24 & 2018-10-80
Client Project #: SMP-South Lakes & SMP-St Johns
Date Sampled: Oct 4, 2018
Oct 5, 2018; Invoice: 380165

Narrative Report

Sample Handling

Sample handling and holding time criteria were met for all samples. Samples collected by submitter. No unusual events occurred during analysis. Results WERE READ ON 10/5/18 AT 12:30PM.

Quality Control

Enclosed analyses met method or FCL criteria, unless otherwise denoted on the sample results. Applied data qualifiers are defined below.

Attachments

Chain of Custody

Qualifier	Meaning
U	Compound was analyzed for but not detected.
J	Estimated value; one or more QC components associated with this data value exceed current QC limits.
Q	Sample held beyond the accepted holding time.
L	Off-scale high; reported concentration exceeds the highest standard.
V	Analyte was detected in both the sample and the associated method blank.
W	The dissolved oxygen blank was above 0.2 mg/L but less than the MDL.
Z	Too numerous to count colonies on plate.
A	Absent
P	Present
T	Value reported is less than the statistical method detection limit. Reported for informational purposes only.
M	Value reported is greater than the statistical method detection limit, but less than the reported MDL.
G	The greatest of the dilutions performed did not yield sufficient oxygen depletion for valid data.
S	The least of the dilutions performed did not yield sufficient oxygen residual for valid data.
O	Result is greater than (over) the specified value.
I	Reported value is between the laboratory method detection limit and the laboratory practical quantitation limit.
B	Results based upon colony plate count outside ideal range.
Y	The laboratory analysis was from an improperly preserved sample. The data may not be accurate.