



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run
Date Sampled: Mar 25, 2019
Mar 26, 2019; Invoice: 395623

Report Summary

Date Received: Mar 25, 2019

FCL Project Manager: Michael D. Conner

Laboratory #	Sample Description	Analysis	Chemist	Location	SampleMatrix
395623AQ1	Lab Blk Ecoli	SM9223B	DDB	South Lab	Water
395623SW1	G1SE0028	SM9223B	DDB	South Lab	Surface Water
395623SW2	G1SE0022	SM9223B	DDB	South Lab	Surface Water
395623SW3	G1SE0028-Dup	SM9223B	DDB	South Lab	Surface Water
395623SW4	G1SE0023	SM9223B	DDB	South Lab	Surface Water
395623SW5	G1SE0029	SM9223B	DDB	South Lab	Surface Water
395623SW6	G1SE0024	SM9223B	DDB	South Lab	Surface Water
395623SW7	G1SE0011	SM9223B	DDB	South Lab	Surface Water
395623SW8	Lab Dup 0011	SM9223B	DDB	South Lab	Surface Water

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAP Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run
Date Sampled: Mar 25, 2019
Mar 26, 2019; Invoice: 395623

Analysis Report

Lab #: 395623AQ1	Sampled: 03/25/19 04:40 PM	Desc: Lab Blk Ecoli								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	1.00 U	mpn/100mL	1.00	1.00	1.00	10399284	SM9223B		03/25/19	05:30 PM
Lab #: 395623SW1	Sampled: 03/25/19 11:25 AM	Desc: G1SE0028								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	10.0 U	mpn/100mL	10.0	10.0	10.0	10399284	SM9223B		03/25/19	05:30 PM
Lab #: 395623SW2	Sampled: 03/25/19 12:30 PM	Desc: G1SE0022								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	20.0	mpn/100mL	10.0	10.0	10.0	10399284	SM9223B		03/25/19	05:30 PM
Lab #: 395623SW3	Sampled: 03/25/19 11:30 AM	Desc: G1SE0028-Dup								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	10.0 U	mpn/100mL	10.0	10.0	10.0	10399284	SM9223B		03/25/19	05:30 PM
Lab #: 395623SW4	Sampled: 03/25/19 01:40 PM	Desc: G1SE0023								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	10.0	mpn/100mL	10.0	10.0	10.0	10399284	SM9223B		03/25/19	05:30 PM
Lab #: 395623SW5	Sampled: 03/25/19 02:05 PM	Desc: G1SE0029								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	10.0	mpn/100mL	10.0	10.0	10.0	10399284	SM9223B		03/25/19	05:30 PM
Lab #: 395623SW6	Sampled: 03/25/19 02:45 PM	Desc: G1SE0024								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	10.0	mpn/100mL	10.0	10.0	10.0	10399284	SM9223B		03/25/19	05:30 PM



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run
Date Sampled: Mar 25, 2019
Mar 26, 2019; Invoice: 395623

Lab #: 395623SW7 Sampled: 03/25/19 03:15 PM Desc: G1SE0011

Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed
E. Coli	85.0	mpn/100mL	10.0	10.0	10.0	10399284	SM9223B		03/25/19 05:30 PM

Lab #: 395623SW8 Sampled: 03/25/19 04:40 PM Desc: Lab Dup 0011

Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed
E. Coli	63.0	mpn/100mL	10.0	10.0	10.0	10399284	SM9223B		03/25/19 05:30 PM



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run
Date Sampled: Mar 25, 2019
Mar 26, 2019; Invoice: 395623



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run
Date Sampled: Mar 25, 2019
Mar 26, 2019; Invoice: 395623

Narrative Report

Sample Handling

Sample handling and holding time criteria were met for all samples. Samples collected by submitter. No unusual events occurred during analysis. Results WERE READ ON 3/26/19 AT 12:30PM.

Quality Control

Enclosed analyses met method or FCL criteria, unless otherwise denoted on the sample results. Applied data qualifiers are defined below.

Attachments

Chain of Custody

Qualifier	Meaning
U	Compound was analyzed for but not detected.
J	Estimated value; one or more QC components associated with this data value exceed current QC limits.
Q	Sample held beyond the accepted holding time.
L	Off-scale high; reported concentration exceeds the highest standard.
V	Analyte was detected in both the sample and the associated method blank.
W	The dissolved oxygen blank was above 0.2 mg/L but less than the MDL.
Z	Too numerous to count colonies on plate.
A	Absent
P	Present
T	Value reported is less than the statistical method detection limit. Reported for informational purposes only.
M	Value reported is greater than the statistical method detection limit, but less than the reported MDL.
G	The greatest of the dilutions performed did not yield sufficient oxygen depletion for valid data.
S	The least of the dilutions performed did not yield sufficient oxygen residual for valid data.
O	Result is greater than (over) the specified value.
I	Reported value is between the laboratory method detection limit and the laboratory practical quantitation limit.
B	Results based upon colony plate count outside ideal range.
Y	The laboratory analysis was from an improperly preserved sample. The data may not be accurate.