



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run, Revised 4/10/19
Date Sampled: Mar 26, 2019
Mar 29, 2019; Invoice: 395722

Invoice


Description	Amount	Units	Extension
EColi-QT	51.00	6	306.00
TOTAL			306.00

This invoice is due upon receipt.

Please remit to: P.O. Box 150597
Altamonte Springs, FL 32715-0597

VISA, MasterCard, and American Express cards will be accepted.

There will be a 1.5% service charge per month on all unpaid balances.



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run, Revised 4/10/19
Date Sampled: Mar 26, 2019
Mar 29, 2019; Invoice: 395722

Report Summary

Date Received: Mar 26, 2019

FCL Project Manager: Michael D. Conner

Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
395722AQ1	Lab Blank Ecoli	SM9223B	DDB	South Lab	Water
395722SW1	G1SE0001	SM9223B	DDB	South Lab	Surface Water
395722SW2	G1SE0027	SM9223B	DDB	South Lab	Surface Water
395722SW3	G1SE0026	SM9223B	DDB	South Lab	Surface Water
395722SW4	G1SE0025	SM9223B	DDB	South Lab	Surface Water
395722SW5	Lab Dup Ecoli 0025	SM9223B	DDB	South Lab	Surface Water

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAP Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run, Revised 4/10/19
Date Sampled: Mar 26, 2019
Mar 29, 2019; Invoice: 395722

Analysis Report

Lab #: 395722AQ1	Sampled: 03/26/19 03:35 PM	Desc: Lab Blank Ecoli								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	1.00 U	mpn/100mL	1.00	1.00	1.00	10400559	SM9223B		03/26/19	04:55 PM
Lab #: 395722SW1	Sampled: 03/26/19 11:50 AM	Desc: G1SE0001								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	98.0	mpn/100mL	10.0	10.0	10.0	10400559	SM9223B		03/26/19	04:55 PM
Lab #: 395722SW2	Sampled: 03/26/19 12:40 PM	Desc: G1SE0027								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	20.0	mpn/100mL	10.0	10.0	10.0	10400559	SM9223B		03/26/19	04:55 PM
Lab #: 395722SW3	Sampled: 03/26/19 03:20 PM	Desc: G1SE0026								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	41.0	mpn/100mL	10.0	10.0	10.0	10400559	SM9223B		03/26/19	04:55 PM
Lab #: 395722SW4	Sampled: 03/26/19 02:00 PM	Desc: G1SE0025								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	120	mpn/100mL	10.0	10.0	10.0	10400559	SM9223B		03/26/19	04:55 PM
Lab #: 395722SW5	Sampled: 03/26/19 03:55 PM	Desc: Lab Dup Ecoli 0025								
Parameter	Result	Units	DF	MDL	PQL	QC Batch	Method	CAS #	Analyzed	
E. Coli	98.0	mpn/100mL	10.0	10.0	10.0	10400559	SM9223B		03/26/19	04:55 PM



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run, Revised 4/10/19
Date Sampled: Mar 26, 2019
Mar 29, 2019; Invoice: 395722



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

FDEP - Port St. Lucie
2199 S. Rock Rd.
Ft. Pierce, FL 34945

PO #: RQ-2019-03-18-45
Client Project #: SMP-Kevin Run, Revised 4/10/19
Date Sampled: Mar 26, 2019
Mar 29, 2019; Invoice: 395722

Narrative Report

Sample Handling

Sample handling and holding time criteria were met for all samples. Samples collected by submitter. This report is corrected and re-issued to provide the date and time of analysis. The samples were read on 3/27/19 at 1:50PM.

Quality Control

Enclosed analyses met method or FCL criteria, unless otherwise denoted on the sample results. Applied data qualifiers are defined below.

Additional Comments

Report Revised on 4/4/19 to add times read.

Attachments

Chain of Custody

Qualifier	Meaning
U	Compound was analyzed for but not detected.
J	Estimated value; one or more QC components associated with this data value exceed current QC limits.
Q	Sample held beyond the accepted holding time.
L	Off-scale high; reported concentration exceeds the highest standard.
V	Analyte was detected in both the sample and the associated method blank.
W	The dissolved oxygen blank was above 0.2 mg/L but less than the MDL.
Z	Too numerous to count colonies on plate.
A	Absent
P	Present
T	Value reported is less than the statistical method detection limit. Reported for informational purposes only.
M	Value reported is greater than the statistical method detection limit, but less than the reported MDL.
G	The greatest of the dilutions performed did not yield sufficient oxygen depletion for valid data.
S	The least of the dilutions performed did not yield sufficient oxygen residual for valid data.
O	Result is greater than (over) the specified value.
I	Reported value is between the laboratory method detection limit and the laboratory practical quantitation limit.
B	Results based upon colony plate count outside ideal range.
Y	The laboratory analysis was from an improperly preserved sample. The data may not be accurate.