



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION STRATEGIC MONITORING PROGRAM FIELD SHEET

January 2020

Meter Passed End

of Day CCV

Yes / No

WIN Station Name: Red House Br @ Hefferon Rd

Date: 11/23/2020

WIN/Field ID: 27010076

WBID: 2472

ENR:

Latitude: 29.927

County: ST. JOHNS

Org ID: 21FLA

Longitude: -81.3482

Receiving Body of Water: Upper East Coast

RQ- 2020-11-23-34

Sampling Team Members		WQ Measurements	Sample Collection	Documentation	Preservation	Preservation Check
☒	Jeremy Parrish	x		x		
☒	Kimberly Applebee		x		x	x
☐						
☐						

Sampling Equipment	
☒ Sample Container	☐ Carboy
☐ Dipper	☐ Van Dorn
☐ Syringe	☒ Pole
Depth measured with: Meter	
Secchi Equipment ID:	
Collection Method	
☒ Wading	☐ Canoe/Kayak
☐ From Shore	☐ Electric Motor
☐ Other	☐ Gasoline Motor

Water Level: ☒ Normal ☐ Low ☐ High ☐ Dry ☐ Pooled ☐ Flooded		Meter ID# STICH	
Photos: NO	Flow: FLOW	Tide:	Tide Times: High: Low:
Biological Samples Collected: ☐ None ☒ HA ☐ SCI ☒ RPS ☐ Algae ID ☒ LVS ☐ LVI Other:			
SBIO ID Numbers:			
Notes:			

Duplicate Sample

Time Zone: EST	Time: N/A	Field ID: N/A	(WIN ID_DUP)
WIN DMT Activity ID:			

Blank

Time Zone:	Time: N/A	Field ID: N/A	(Blank Type_DDMYYYY)
DI Source: N/A	Location: N/A		
DI Type: N/A	Equipment ID: N/A		

LIMS EVENT ID: WIN Import ID:

Enter Field Parameters, Verify Station ID In LIMS DMT: QC Station ID, Field Parameters In LIMS DMT:

Scan/Save Field Sheets Migrate Data to WIN: Verify Data In WIN:



RQ-2020-11-23-34

Customer: WQAP

Project ID: SMP

Collected By: Jeremy Parrish, Kimberly Applebee

Field Report Prepared By: Jeremy Parrish

Sampling Agency: FDEP

Place Label Here

WIN ID/Field ID:



27010076

Location: Red House Br @ Hefferon Rd

Comments:

Bacteria samples submitted to contract lab

Matrix: Fresh

(Check one)

☒ GRAB☐ COMPOSITE

Date	Time	DO (mg/L)	DO (%SAT)	Temp. (C°)	pH	Sample Depth (m)	Secchi Disk (m)	Total Depth (m)	Sp COND (µmhos/cm)	Salinity (PPTH)
11/23/2020	10:15 EST	6.52	73.3	21	7.19	0.3	0.5 ☒ VOB (S)	0.5	495	0.24

Central Lab please use top row for login purposes

	EST									

Parameter Suite	Parameter Methods	Preservation	pH Check	# Bottles sent to Lab	Bottle Group
Preserved Nutrients (P-500ML)	☒ W-NH3 / W-NO2NO3 / W-TKN / W-TOC / W-S-A-TP	☒ Ice ☒ H2SO4*	☒ <2	1	A
	Lot # Sa9354050 Exp: 12/20/20				
Metals (P-500ML)	☐ W-ICPMS ☐ W-ICP ☐ W-HARD	☐ Ice ☐ HNO3* ☐ <2			
	Lot # Exp:				
Filtered Nutrients (P125ML)	☒ W-PO4-F ☒ Field Filtered 0.45 µm Filter	☒ Ice		1	A
	Filter Lot # Sa1j792h5				
	Syringe Lot #				
Chlorophyll (BP-1L)	☒ CHLSUITE-W	☒ Ice		1	A
Physical/Aggregate (Fresh) (P-1L)	☒ Alkalinity / W-F / W-TSS / TURBIDITY / W-CL-IC / W-COLOR / W-SO4-IC / W-TDS	☒ Ice		1	A
Physical/Aggregate (Marine) (P-1L)	☐ Alkalinity / W-BR-IC / W-F / W-TSS / TURBIDITY	☐ Ice			
Macroinvertebrates (PJ-2L)	☐ MI-FW-QLDC	☐ Formalin			
Periphyton (PT-50ML)	☐ ALGAE-ID	☐ Ice			
Microbiology (Contract Lab Bottle)	☒ E Coli ☐ F Coli ☐ Enterococci ☒ Contract Lab	☒ Ice		1	A
Molecular (QPCR-P-500ML)	☐ PCR-HF183 ☐ PCR-BacR ☐ PCR-DG3 ☐ PCR-GULL2 ☐ PCR-GFD	☐ Ice			
Tracers (BG-500ML)	☐ W-E8321-DI ☐ W-E8321-MS	☐ Ice			
Pesticides (BG-500ML) (BG-1L)	☐ W-E8321-DI ☐ WE8321-MS ☐ W-PSNP-TQ ☐ W-CT-CL-R ☐ W-PCL-SQ-R ☐ W-CARB-AA (5 ml of MCAA** Buffer Solution)	☐ Ice			
		☐ Ice			

Name:
Jeremy Parrish
Kimberly Applebee

Signature:

Jeremy Parrish

Date:

11/23/20

*2.0 ml of Preservative used unless noted otherwise.

**MCAA: Monochloroacetic acid buffer solution

DEP Form FD 9000-5 Stream/River Habitat Assessment Field Sheet

SAMPLING AGENCY: <u>FDER NE ROL</u>		STORET STATION NUMBER: <u>27010076</u>	DATE (MM/DD/YY): <u>11/22/20</u>	RECEIVING BODY OF WATER:
REMARKS:	COUNTY: <u>St Johns</u>	LOCATION: <u>Red house Hoffman Rd</u>	FIELD ID/NAME:	


Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
Primary Habitat Components	Four or more major productive habitats present (snags, tree roots, aquatic vegetation, leaf packs (partially decayed), rock)	Three major productive habitats present. Adequate habitat. Some substrates may be new fall (fresh leaves or snags)	Two major productive habitats present. Less than desirable habitat, frequently disturbed or removed	One or less major productive habitat. Lack of habitat is obvious, substrates unstable or smothered
Substrate Diversity <u>13</u>	20 19 18 17 16	15 14 <u>13</u> 12 11	10 9 8 7 6	5 4 3 2 1
Substrate Availability <u>6</u>	Greater than 30% major productive habitat present at site 20 19 18 17 16	16% to 30% major productive habitat, by aerial extent 15 14 13 12 11	6% to 15% major productive habitat 10 9 8 7 <u>6</u>	Less than 5% major productive habitat 5 4 3 2 1
Water Velocity <u>18</u>	Max. observed at typical transect: > 0.25 m/sec. But < 1 m/sec ≥ 0.33 0.31 0.29 0.27 > 0.25 20 <u>18</u> 17 16	Max. observed at typical transect: > 0.1 to 0.25 m/sec 0.25 0.21 0.17 0.13 > 0.1 15 14 13 12 11	Max. observed at typical transect: 0.05 to 0.1 m/sec 0.1 0.09 0.07 0.06 0.05 10 9 8 7 6	Max. observed at typical transect: < 0.05 m/sec; or spate occurring: > 1 m/sec < 0.05 0.04 0.03 0.01 < 0.01 5 4 3 2 1
Habitat Smothering <u>16</u> Primary Score <u>53</u>	Adequate number of stable pools (1-2 per 12 times width) and < 25% of habitats affected by sand, silt, or algae. 20 19 18 17 <u>16</u>	Adequate number of stable pools (1-2 per 12 times width) and > 25% of habitats affected by sand, silt, or algae. 15 14 13 12 11	Does not have required number of stable pools (1-2 per 12 x width) and/or has shallow pools (< 2 x prevailing depth). 10 9 8 7 6	Stable pools are absent. Most habitats affected by sand, silt, or algae accumulation. 5 4 3 2 1
Secondary Habitat Components	Expected sinuosity given the stream width. No evidence of dredging or artificial straightening. No spoil banks.	Good sinuosity within old channelized area. Evidence of dredging or straightening in the past (> 25 yrs) but mostly recovered.	Straightened with trapezoidal cross section, but has a small degree of sinuosity developed within channelized area.	Straightened or engineered by dredging, has trapezoidal or box cut cross section, lacks required pools. May have spoil banks.
Artificial Channelization <u>20</u>	<u>20</u> 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Bank Stability	Bankfull > 60% of bank height. Slope of bank ≤ 60° from bankfull to top of bank. Bankfull is within or above the woody root zone with few raw, eroded areas.	Only meets 2 of the 3 requirements for optimal bank stability.	Only meets 1 of the 3 requirements for optimal bank stability.	Bankfull < 60% of bank height. Slope of bank > 60°. Bankfull is below the woody root zone with raw, eroded areas.
Right Bank <u>7</u> Left Bank <u>7</u>	10 9	8 <u>7</u> 6	5 4	3 2 1
Riparian Buffer Zone Width	Width of vegetation greater than 18 m	Width of vegetation > 12 to 18 m	Width of vegetation 6 to 12 m. human activities close to system	Less than 6 m of buffer zone due to intensive human activities
Right Bank <u>10</u> Left Bank <u>6</u>	<u>10</u> 9	8 7 <u>6</u>	5 4	3 2 1
Riparian Zone Vegetation Quality	Over 80% of riparian surfaces consist of normal, expected plant community for given sunlight & habitat conditions (e.g., native plants; tree, shrub, and forbs represented, if appropriate). Minimal disturbance.	> 50% to 80% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Some disruption in community observed.	25% to 50% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Disruption obvious.	Less than 25% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions).
Right Bank <u>10</u> Left Bank <u>9</u> Secondary Score <u>69</u>	10 <u>9</u>	8 7 6	5 4	3 2 1

TOTAL SCORE

122

Date: <u>11/23/20</u>	Analyst: <u>Ham</u>	Signature: <u>Ham</u>
-----------------------	---------------------	-----------------------

DEP Form FD 9000-4 Stream/River Habitat Assessment Sketch Sheet



Location: Rothaus Branch @ Hottel

Date: 11/23/20

Sampler: _____

100 m: Latitude _____
Longitude _____

0 m: Latitude _____
Longitude _____

Substrates: Code key, draw proportionate habitat abundance. %

	Snags	2.5
	Roots/undercut banks	1.5
	Leaf Packs (or mats)	1
	Aquatic Macrophytes	1
	Pools	total # observed = _____ # range expected = _____

Average width 0.5 m
Average depth 0.5 m

Velocity measured at _____ meter mark.

WQ & chemistry taken at _____ meter mark.

Habitat Smothering:
Note areas (on map) where sand or silt is smothering substrates, limiting habitability.

Bank Stability:
Note areas (on map) with unstable, eroding banks.

Riparian Buffer Width:
Note areas (on map) where natural vegetation is altered or eliminated.

Plants observed / other notes:

$$X = 0.3 + 0.2 + 0.3 + 0.4 + 0.5 + 0.4 + 0.3 \approx 2.5$$

$$0.2 = 0.5 + 1.5 + 0.2 + 0.5 + 0.3 \approx 3$$

$$0.1 = 0.2 + 0.3 + 0.3 + 0.2 \approx 1$$

$$\Delta = 0.5 + 0.2 + 0.2 + 0.1 + 0.5 + 0.1 \approx 2m$$

0.3 m sec

Length of grid represents 100 m of stream (not linear meters).
(Horizontal scale is double vertical scale, draw proportionately).

DEP Form FD 9000-3 Physical/Chemical Characterization Field Sheet

SAMPLE ID 81671 ORG ID 21FL6 LATITUDE _____
 COUNTY St. Johns STORET # 27010076 LONGITUDE _____
 DATE 11/23/20 TIME 1015 SAMPLING AGENCY EDIP NE Pol
 SITE NAME Redhouse Branch @ Hofferen Rd
 FIELD ID/NAME _____ RECEIVING BODY OF WATER _____

RIPARIAN ZONE / STREAM FEATURES

PREDOMINANT LAND-USE IN WATERSHED (specify relative percent in each category): Forest/Natural ☐ Silviculture ☐ Field/Pasture ☐ Agricultural ☐ Residential ☐ Commercial ☐ Industry ☐ Other (Specify) ☐							Landscape Development Intensity Index (LDI) ☐
Local Watershed Erosion (select one): ☐ None ☒ Slight ☐ Moderate ☐ Heavy Local Watershed NPS Pollution: ☐ No evidence ☐ Slight ☒ Moderate ☐ Heavy							Typical Width (m) Depth (m)/Velocity (m/sec) Transect <u>2.5</u> m wide
Width of Riparian Vegetation (m) on Each Buffer Side Left Bank: <u>12</u> Right Bank: <u>718</u>				Hydrologic Modification Score (per FT 3101) ☐		m/s <u>0.3</u> m/s ☐ m/s	
High Water Mark: <u>1</u> + <u>0.5</u> = <u>1.5</u> (m) (above present water level) (present depth) (above bed)				Artificially Impounded ☐ Yes ☒ No		m deep <u>0.5</u> m deep ☐ m deep	
Artificially ☒ No ☐ Mostly recovered, more sinuous Channelized: ☐ Some recovery ☐ Recent, severe				Canopy Cover % ☐ Open ☐ Lightly Shaded (11-45%) ☒ Heavily Shaded ☐ Moderate Shaded (46-80%)			

SEDIMENT / SUBSTRATE

Sediment Oils ☒ Absent ☐ Slight ☐ Moderate ☐ Profuse		Sediment Odors ☒ Normal ☐ Sewage ☐ Petroleum ☐ Chemical ☐ Anaerobic ☐ Other (Specify): _____		Smothering of Substrates Sand Smothering: None ☒ Slight ☒ Moderate ☐ Severe ☐ Silt Smothering: None ☒ Slight ☐ Moderate ☐ Severe ☐ Algae Smothering: None ☒ Slight ☐ Moderate ☐ Severe ☐																																																																													
SUBSTRATE TYPE Assessment Tool: ☐ SCI ☒ RPS ☒ LVS ☐ LCI ☐ BioRecon <table border="1"> <thead> <tr> <th></th> <th>% Coverage</th> <th>INVERT # Times Sampled</th> <th>PERI # Times Sampled</th> </tr> </thead> <tbody> <tr> <td>Woody Debris (Snags)</td> <td><u>2.5</u></td> <td></td> <td></td> </tr> <tr> <td>Undercut Banks / Roots</td> <td><u>1.5</u></td> <td></td> <td></td> </tr> <tr> <td>Leaf Packs or Mat</td> <td><u>1</u></td> <td></td> <td></td> </tr> <tr> <td>Aquatic Vegetation</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Rock or Shell Rubble</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Sand</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Mud / Muck / Silt</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Other</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Other</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>				% Coverage	INVERT # Times Sampled	PERI # Times Sampled	Woody Debris (Snags)	<u>2.5</u>			Undercut Banks / Roots	<u>1.5</u>			Leaf Packs or Mat	<u>1</u>			Aquatic Vegetation				Rock or Shell Rubble				Sand				Mud / Muck / Silt				Other				Other				WATER QUALITY <table border="1"> <thead> <tr> <th></th> <th>Depth (M)</th> <th>Temp. (°C)</th> <th>pH (SU)</th> <th>D.O. (MG/L)</th> <th>D.O. Sat (%)</th> <th>Cond. (UMHO/CM)</th> <th>Salinity (PPT)</th> <th>SECCHI (M)</th> </tr> </thead> <tbody> <tr> <td>Top</td> <td><u>0.3</u></td> <td><u>21.0</u></td> <td><u>7.19</u></td> <td><u>6.52</u></td> <td><u>73.3</u></td> <td><u>495</u></td> <td><u>0.24</u></td> <td><u>0.5</u></td> </tr> <tr> <td>Mid</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>☒ VOB</td> </tr> <tr> <td>Bottom</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>TOTAL DEPTH <u>0.5</u></td> </tr> </tbody> </table> Meter ID: <u>Sketch</u>				Depth (M)	Temp. (°C)	pH (SU)	D.O. (MG/L)	D.O. Sat (%)	Cond. (UMHO/CM)	Salinity (PPT)	SECCHI (M)	Top	<u>0.3</u>	<u>21.0</u>	<u>7.19</u>	<u>6.52</u>	<u>73.3</u>	<u>495</u>	<u>0.24</u>	<u>0.5</u>	Mid								☒ VOB	Bottom								TOTAL DEPTH <u>0.5</u>
	% Coverage	INVERT # Times Sampled	PERI # Times Sampled																																																																														
Woody Debris (Snags)	<u>2.5</u>																																																																																
Undercut Banks / Roots	<u>1.5</u>																																																																																
Leaf Packs or Mat	<u>1</u>																																																																																
Aquatic Vegetation																																																																																	
Rock or Shell Rubble																																																																																	
Sand																																																																																	
Mud / Muck / Silt																																																																																	
Other																																																																																	
Other																																																																																	
	Depth (M)	Temp. (°C)	pH (SU)	D.O. (MG/L)	D.O. Sat (%)	Cond. (UMHO/CM)	Salinity (PPT)	SECCHI (M)																																																																									
Top	<u>0.3</u>	<u>21.0</u>	<u>7.19</u>	<u>6.52</u>	<u>73.3</u>	<u>495</u>	<u>0.24</u>	<u>0.5</u>																																																																									
Mid								☒ VOB																																																																									
Bottom								TOTAL DEPTH <u>0.5</u>																																																																									
Water Odors Normal ☒ Petroleum ☐ Sewage ☐ Chemical ☐ Other ☐			Water Surface Oils Normal ☒ Sheen ☐ Globbs ☐ Slick ☐ Other ☐																																																																														
Water Sample Taken? ☒ Yes ☐ No Sample Preserved? ☒ Yes ☐ No Lot Number: _____ Exp: _____			Color Tannic ☒ Green (Algae) ☐ Clear ☐ Other (Specify) ☐																																																																														
Algae Sample Taken? ☐ Yes ☒ No Sample Preserved? ☐ Yes ☐ No Lot Number: _____ Exp: _____			Clarity Clear ☒ Slightly Turbid ☐ Turbid ☐ Opaque ☐																																																																														
ABUNDANCE <table border="1"> <thead> <tr> <th></th> <th>Not Obs.</th> <th>Rare</th> <th>Common</th> <th>Abundant</th> </tr> </thead> <tbody> <tr> <td>Periphyton:</td> <td>☒</td> <td>☒</td> <td>☐</td> <td>☐</td> </tr> <tr> <td>Fish:</td> <td>☒</td> <td>☐</td> <td>☐</td> <td>☐</td> </tr> <tr> <td>Aquatic Plants:</td> <td>☐</td> <td>☐</td> <td>☒</td> <td>☐</td> </tr> <tr> <td>Iron/Sulfur Bacteria:</td> <td>☒</td> <td>☐</td> <td>☐</td> <td>☐</td> </tr> </tbody> </table>				Not Obs.	Rare	Common	Abundant	Periphyton:	☒	☒	☐	☐	Fish:	☒	☐	☐	☐	Aquatic Plants:	☐	☐	☒	☐	Iron/Sulfur Bacteria:	☒	☐	☐	☐	System Type: Stream ☒ Lake ☐ Wetland ☐ Estuary ☐ Other(Specify) ☐																																																					
	Not Obs.	Rare	Common	Abundant																																																																													
Periphyton:	☒	☒	☐	☐																																																																													
Fish:	☒	☐	☐	☐																																																																													
Aquatic Plants:	☐	☐	☒	☐																																																																													
Iron/Sulfur Bacteria:	☒	☐	☐	☐																																																																													
AMBIENT FIELD CONDITIONS / NOTES: ☒ The antecedent hydrologic conditions have been met to my best knowledge.																																																																																	
SAMPLING TEAM <u>Kim Appleby + Jeremy Parrish</u>			SIGNATURE: <u>Kg ar</u>		DATE: <u>11/23/20</u>																																																																												

Site: Redhouse Rd. H. K. Rd.					County: St. Johns		Date: 11/23/20		Investigators: Kim Appleby & Jeremy Parrish	
Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	STORET Station Number: 27010076
0	1	N			60	1	N			Secchi depth <u>0.5</u> Estimated? <u>✓</u> # points ranked 4-6 <u>0</u> total points assessed <u>99</u> % points ranked 4-6 <u>0</u>
	2					2				
	3					3				
	4					4				
	5			90		5			96	
	6					6		✓		
	7					7		↓		
	8					8		↓		
	9					9		↓		
10	1	N			70	1	N			Check accompanying data collected at same site/date: Algal mat sample <u>✓</u> Linear Veg Survey <u>✓</u> Habitat Assessment <u>✓</u> SCI/Biorecon <u>✓</u> Water sample <u>✓</u> RQ- 2020-11-23-34
	2					2				
	3					3				
	4					4				
	5			90		5			92	
	6					6				
	7					7				
	8					8				
	9					9				
20	1	N			80	1	N			Algal Thickness Rank N rough, no algae; slimy, algae up to 1mm 3 >1mm - 6mm 4 >6mm - 20mm 5 >20mm - 10cm 6 >10 cm
	2					2				
	3					3		✓		
	4					4		↓		
	5			94		5			95	
	6					6				
	7					7				
	8					8		✓		
	9					9				
30	1	N			90	1	X			rps 9617
	2					2		✓		
	3					3		↓		
	4					4				
	5			96		5			96	
	6					6				
	7					7				
	8					8		↓		
	9					9				
40	1	N			100	1	N			
	2					2				
	3					3		✓		
	4					4		↓		
	5			92		5			96	
	6					6				
	7					7				
	8					8				
	9					9				
50	1	N			Record "N" and check "Estimated" for points deeper than the Secchi depth; algae are presumed absent. Check "Estimated" if thickness estimated for deep points which can be seen but not reached. Record "X" for points shallower than Secchi depth for which substrate cannot be seen or reached with the hand. No estimated rank. Record canopy cover as the number of small densiometer quadrants (out of 96) that HAVE canopy cover. Measure facing upstream at point 4, 5, or 6. Collect algal mat sample following DEP SOP FS 7240 if the percentage of total sampled points with a thickness rank of 4, 5, or 6 is >20%.					
	2									
	3									
	4									
	5			53						
	6			53						
	7									
	8									
	9									

DEP FORM FD 9000-32: LINEAR VEGETATION SURVEY FIELD SHEET

Waterbody: <u>Red River G. & H. River</u>	Date: <u>11/23/20</u>	County: <u>St Johns</u>	Storet Number: <u>2701076</u>																				
Analyst: <u>Jameson</u>	Signature: <u>Jameson</u>																						
Comments:																							
Instructions: Note taxa growing in the water with a checkmark if present, "D" if dominant, and "C" if codominant (dominance only if 1 m ² of taxa present). Note in the boxes below if no dominant are selected, and note total macrophyte abundance rank for each section. Only the most common taxa are listed, so use blank spaces for additional taxa names.																							
HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)	HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)
	0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100			0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100	
<i>Alternanthera philoxeroides</i>												<i>Micranthemum glomeratum</i>											
<i>Bacopa caroliniana</i>												<i>Micranthemum umbrosum</i>											
<i>Bacopa monnieri</i>												<i>Myriophyllum aquaticum</i>											
<i>Bidens mitis</i>												<i>Najas guadelupensis</i>											
<i>Boehmeria cylindrica</i>												<i>Nuphar luteum</i>											
<i>Centella asiatica</i>												<i>Orontium aquaticum</i>											
<i>Ceratophyllum demersum</i>												<i>Panicum hemitomon</i>											
<i>Chara</i>												<i>Panicum repens</i>											
<i>Cicuta maculata</i>												<i>Panicum rigidulum</i>											
<i>Cladium jamaicense</i>												<i>Pistia stratioides</i>											
<i>Colocasia esculenta</i>												<i>Polygonum glabra</i>											
<i>Commelina diffusa</i>												<i>Polygonum hydropiperoides</i>											
<i>Commelina virginica</i>												<i>Polygonum punctatum</i>											
<i>Crinum americanum</i>												<i>Pontedaria cordata</i>											
<i>Diodia virginiana</i>												<i>Potamogeton illinoensis</i>											
<i>Eichhornia crassipes</i>												<i>Ruellia simplex</i>											
<i>Eleocharis (wispy viviparous)</i>												<i>Sacciolepis striata</i>											
<i>Hydrilla verticillata</i>												<i>Sagittaria kurziana</i>											
<i>Hydrocotyle</i>												<i>Sagittaria lancifolia</i>											
<i>Hygrophila polysperma</i>												<i>Sagittaria latifolia</i>											
<i>Hymenocallis</i>												<i>Salvinia minima</i>											
<i>Lachnanthes caroliniana</i>												<i>Samolus parviflora</i>											
<i>Landoltia punctata</i>												<i>Saururus cernuus</i>											
<i>Lemna</i>												<i>Sparganium americanum</i>											
<i>Limnophila sessiflora</i>												<i>Typha</i>											
<i>Ludwigia leptocarpa</i>												<i>Vallisneria americana</i>											
<i>Ludwigia palustris</i>												<i>Zizania aquatica</i>											
<i>Ludwigia peruviana</i>																							
<i>Ludwigia repens</i>																							