



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION STRATEGIC MONITORING PROGRAM FIELD SHEET

January 2020

Meter Passed End
of Day CCV
Yes / No

page 1
of 2

WIN Station Name: See label on page 2

Date: 3 / 10 / 2020
(mm/dd/yyyy)

WIN/ Field ID: See label on page 2

WBID: 1774

Latitude:

(Decimal Degrees)

County:

ORG ID: 21FLTPA

Longitude:

(Decimal Degrees)

Receiving Body of Water:

RQ-2020- 0309-67

Sampling Team Members	WQ Measurements	Sample Collection	Documentation	Preservation	Preservation Check
Judy Ashton	☒	☒	☒	☒	☒
BEN PETERSEN	☒	☒	☒	☒	☒
	☐	☐	☐	☐	☐
	☐	☐	☐	☐	☐
	☐	☐	☐	☐	☐

Sampling Equipment	
☒ Sample Container	☐ Van Dorn
Syringe	Pole
Dipper	Other
Depth Measured with	
Equipment ID Secchi #3	
Collection Method	
☒ Wading	☐ Canoe/Kayak
☐ From Shore	☐ Electric Motor
Other	☐ Gasoline Motor

Water Level: Dry/ Pooled/ <u>Low</u> / Normal / High / Flooded		Meter ID# Chewy	
Photos: <u>Yes</u> / No	Flow: No Flow / <u>Flowing</u> / NA	Tide: Rising/ Falling/ Slack/ <u>NA</u>	Tide Times: High Low
Biological Samples Collected: None <u>HA</u> SCI <u>RPS</u> Algae ID <u>LVS</u> LVI Other:			
S BIO ID Numbers:	S BIO-ID: 80849	HA-ID: 16567	RPS-ID: 9561
Macrophyte-ID: < 2m ²		LIMS#: _____	
Notes:			

Duplicate Sample

Time Zone: EST	Time: _____	Field ID: _____ (WIN ID_DUP)
WIN DMT Activity ID: _____		

Blank

Time Zone: EST	Time: _____	Field ID: _____ (Blank Type_DDMMYYYY)
DI Source: SWDIST DI Machine	Location: _____	
☐ Field Blank	☐ Equipment Blank	☐ Field Cleaned Equipment Blank
Equipment ID: _____		

LIMS EVENT ID: 2020-03-11-03

WIN Import ID: 19647

Enter Field Parameters, Verify Station ID In LIMS DMT: SM 03/25/2020
(Initials/Date)

QC Station ID, Field Parameters In LIMS DMT: SM 04/14/2020 04/28/20
(Initials/Date)

Scan/Save Field Sheets
(Initials/Date)

Migrate Data to WIN: SM 04/28/2020
(Initials/Date)

Verify Data In WIN: SM 09/08/2020
(Initials/Date)



RQ-2020- see page 1

Customer: SWROC

Project ID: SMP

Collected By: SWROC

Field Report Prepared By:

Sampling Agency: DEP SWROC

Field ID/WIN G3SW0089						Comments: <i>E. COLI DROPPED W/ W AKL</i> <i>HA, RPS, LVS (A-KIT + E. COLI)</i>				
Site Name: Little Charlie Creek @ 664										
Matrix: <u>fresh</u> / Marine						(Check one) ☒ GRAB ☐ COMPOSITE				
Date	Time	DO (mg/L)	DO (%SAT)	Temp. (C°)	pH	Sample Depth (m)	Secchi Disk (m)	Total Depth (m)	Sp COND (µmhos/cm)	Salinity (PPTH)
3-10-20	1400	11.42	126.9	20.4	8.29	0.3	0.5	0.5	609	0.30
EST										
Cental Lab please use top row for login purposes										
EST										
Parameter Suite		Parameter Methods				Preservation		pH Check	# Bottles sent to Lab	Bottle Group
Preserved Nutrients (P-500ML)		☒ W-NH3 / ☒ W-NO2NO3 / ☒ W-TKN / ☒ W-TOC / ☒ W-S-A-TP				☒ Ice ☐ H2SO4*		☒ <2	1	A
		Lot #		SA9301030		Exp:		10/28/2020		
Metals (P-500ML) <i>NO</i>		☒ W-As / ☒ W-Cd / ☒ W-Cr / ☒ W-Cu / ☒ W-Hg / ☒ W-Mn / ☒ W-Pb / ☒ W-Sb / ☒ W-Se / ☒ W-Tl / ☒ W-Zn				☒ Ice ☐ HNO3*		☒ <2	+	A-2
		Lot #		NA9189080		Exp:		7/8/2020		
Filtered Nutrients (P125ML)		☒ W-P04-F ☐ Field Filtered 0.45 µm Filter				☒ Ice			1	A
		Filter Lot #		16968882						
		Syringe Lot #		9056849						
Chlorophyll (BP-1L)		☒ CHLSUITE-W				☒ Ice			1	A
Physical/Aggregate (Fresh)(P-1L)		☒ Alkalinity / ☒ W-F / ☒ W-TSS / ☒ TURBIDITY / ☒ W-CHC / ☒ W-COLOR / ☒ W-SO4-IC / ☒ W-TDS				☒ Ice			1	A
Physical/Aggregate (Marine P-1L)		☐ Alkalinity / ☐ W-BR-IC / ☐ W-F / ☐ W-TSS / ☐ TURBIDITY				☐ Ice				
Macroinvertebrates (PJ-2L)		☒ MI-FW-QLDC				☒ Formalin				B-1
Periphyton (PT-50ML)		☐ ALGAE-ID				☐ Ice				
Microbiology (Contract Lab Bottle)		☒ E Coli ☐ F Coli ☐ Enterococci				☒ Ice			1	A B-2
Molecular (QPCR-P-500ML)		☐ PCR-HF183 ☐ PCR-BacR ☐ PCR-DG3 ☐ PCR-GULL2 ☐ PCR-GFD ☐ See Notes				☐ Ice				
Tracers (BG-500ML) <i>NO</i>		☒ W-E8321-DI ☒ W-E8321-MS				☒ Ice			+	A-1
Pesticides (BG-500ML) (BG-1L) <i>NO</i>		☐ W-E8321-DI ☐ WE8321-MS ☒ W-PSNP-TQ ☐ W-CT-CL-R ☐ W-PCL-SQ-R ☐ W-CARB-AA (5 ml of MCAA** Buffer Solution)				☒ Ice			2	A-1
Name: <i>Judy Ashton</i>						Signature: <i>Judy Ashton</i>			Date: 3 / 10 / 2020	

*2.0 ml of Preservative used unless noted otherwise.

**MCAA: Monochloroacetic acid buffer solution

Florida Department of Environmental Protection

Central Laboratory Submittal Form

Little Charlie HA

Customer: SW-DIST

Project ID: SMP

Requester: Judy Ashton

Field Report Prepared By: Judy Ashton

Collected By: J. Ashton

Sampling Agency: FDEP

Location		☐ Comp ☒ Grab		Collection (comp begin or grab) Date 3-10-20 Time 1400		Eastern Central		Composite end Date Time		Bottle Group(s) (See pg 2)	
Field ID/WIN G3SW0089		Matrix (type, e.g., Salt, Fresh, etc)		Diss. Oxygen 1142		☒ mg/L ☐ % sat		Total Res. Chlorine (mg/L)		A	
Site Name: Little Charlie Creek @ 664		Temp (C) 1400		pH 8.29		Sample Depth 0.3		☐ ft ☒ m		Sp. Conductance (umho/cm) 609	
☐ dd ☐ dms		Salinity (ppt) 0.30		Comments E. COLI DROPPES ON 2 AEL							

Location		☐ Comp ☐ Grab		Collection (comp begin or grab) Date Time		Eastern Central		Composite end Date Time		Bottle Group(s)	
Field ID		Matrix (type, e.g., Salt, Fresh, etc)		Diss. Oxygen		☐ mg/L ☐ % sat		Total Res. Chlorine (mg/L)			
WIN/STORET #		Temp (C)		pH		Sample Depth		☐ ft ☐ m		Sp. Conductance (umho/cm)	
Latitude ☐ dd ☐ dms		Longitude ☐ dd ☐ dms		Salinity (ppt) ☐ dd ☐ dms		Comments					

Location		☐ Comp ☐ Grab		Collection (comp begin or grab) Date Time		Eastern Central		Composite end Date Time		Bottle Group(s)	
Field ID		Matrix (type, e.g., Salt, Fresh, etc)		Diss. Oxygen		☐ mg/L ☐ % sat		Total Res. Chlorine (mg/L)			
WIN/STORET #		Temp (C)		pH		Sample Depth		☐ ft ☐ m		Sp. Conductance (umho/cm)	
Latitude ☐ dd ☐ dms		Longitude ☐ dd ☐ dms		Salinity (ppt) ☐ dd ☐ dms		Comments					

Location		☐ Comp ☐ Grab		Collection (comp begin or grab) Date Time		Eastern Central		Composite end Date Time		Bottle Group(s)	
Field ID		Matrix (type, e.g., Salt, Fresh, etc)		Diss. Oxygen		☐ mg/L ☐ % sat		Total Res. Chlorine (mg/L)			
WIN/STORET #		Temp (C)		pH		Sample Depth		☐ ft ☐ m		Sp. Conductance (umho/cm)	
Latitude ☐ dd ☐ dms		Longitude ☐ dd ☐ dms		Salinity (ppt) ☐ dd ☐ dms		Comments					

Relinquished By: J. Ashton	Date/Time 3-10-20 1600	Shipping Method FMS kx	Number of Coolers Shipped: 2	Received By:	Date/Time
-------------------------------	---------------------------	---------------------------	---------------------------------	--------------	-----------

Group: A	Bottle Type:	P-1L	# of Bottles: 1	Preservative:	ICE	Enter Number of Bottles Sent to Lab	<u>1</u>
	ALKALINITY						
	TURBIDITY						
	W-CL-IC						
	W-COLOR						
	W-F						
	W-SO4-IC						
	W-TDS						
	W-TSS						

Group: A	Bottle Type:	BP-1L	# of Bottles: 1	Preservative:	ICE	Enter Number of Bottles Sent to Lab	<u>1</u>
	CHLSUITE-W						

Group: A	Bottle Type:	P-500ML	# of Bottles: 1	Preservative: ICE And H2SO4		Enter Number of Bottles Sent to Lab	<u>1</u>
	W-NH3						
	W-NO2NO3						
	W-S-A-TP						
	W-TKN						
	W-TOC						

Group: A	Bottle Type:	P-125ML	# of Bottles: 1	Preservative: FILTER-ICE		Enter Number of Bottles Sent to Lab	<u>1</u>
	W-PO4-F						

Group A

250ml

SW-AEL-ECQ

ICE

SENT TO AEL

1

G3SW0089

DEP Form FD 9000-5 Stream/River Habitat Assessment Sheet

Site Name: Little Charlie Creek @ 664

STORET STATION
NUMBER: see sticker

DATE (MM/DD/YY):

3-10-20

SAMPLING AGENCY:

FDEP SWROC

FIELD ID/NAME: see sticker

LOCATION: --

COUNTY:

Harder

RECEIVING BODY OF WATER:

Peace River

Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
Primary Habitat Components	Four or more major productive habitats present [snags, tree roots, aquatic vegetation, leaf packs (partially decayed), rock]	Three major productive habitats present. Adequate habitat. Some substrates may be new fall (fresh leaves or snags)	Two major productive habitats present. Less than desirable habitat, frequently disturbed or removed	One or less major productive habitat. Lack of habitat is obvious, substrates unstable or smothered
Substrate Diversity <u>10</u>	20 19 18 17 16	15 14 13 12 11	<u>10</u> 9 8 7 6	5 4 3 2 1
Substrate Availability <u>6</u>	Greater than 30% major productive habitat present at site 20 19 18 17 16	16% to 30% major productive habitat, by aerial extent 15 14 13 12 11	6% to 15% major productive habitat 10 9 8 7 <u>6</u>	Less than 5% major productive habitat 5 4 3 2 1
Water Velocity <u>14</u>	Max. observed at typical transect: > 0.25 m/sec. But < 1 m/sec ≥0.33 0.31 0.29 0.27 >0.25 20 19 18 17 16	Max. observed at typical transect: >0.1 to 0.25 m/sec 0.25 <u>0.21</u> 0.17 0.13 >0.1 15 <u>14</u> 13 12 11	Max. observed at typical transect: 0.05 to 0.1 m/sec 0.1 0.09 0.07 0.06 0.05 10 9 8 7 6	Max. observed at typical transect: <0.05 m/sec; or spate occurring: > 1 m/sec <0.05 0.04 0.03 0.01 <0.01 5 4 3 2 1
Habitat Smothering <u>17</u> ----- Primary Score <u>47</u>	Adequate number of stable pools (1-2 per 12 times width) and <25% of habitats affected by sand, silt, or algae. 20 19 18 <u>17</u> 16	Adequate number of stable pools (1-2 per 12 times width) and >25% of habitats affected by sand, silt, or algae. 15 14 13 12 11	Does not have required number of stable pools (1-2 per 12 x width) and/or has shallow pools (<2 x prevailing depth). 10 9 8 7 6	Stable pools are absent. Most habitats affected by sand, silt, or algae accumulation. 5 4 3 2 1
Secondary Habitat Components	Expected sinuosity given the stream width. No evidence of dredging or artificial straightening. No spoil banks.	Good sinuosity within old channelized area. Evidence of dredging in the past (>25 yrs) but mostly recovered.	Straightened with trapezoidal cross section, but has a small degree of sinuosity developed within channelized area.	Straightened or engineered by dredging, has trapezoidal or box cut cross section, lacks required pools. May have spoil banks.
Artificial Channelization <u>18</u>	20 19 <u>18</u> 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Bank Stability Right Bank <u>9</u> Left Bank <u>9</u>	Bankfull > 60% of bank height. Slope of bank ≤ 60° from bankfull to top of bank. Bankfull is within or above the root zone with few raw, eroded areas. 10 <u>9</u> <u>LR</u>	Only meets 2 of the 3 requirements for optimal bank stability. 8 7 6	Only meets 1 of the 3 requirements for optimal bank stability. 5 4	Bankfull < 60% of bank height. Slope of bank > 60°. Bankfull is below the root zone with raw, eroded areas. 3 2 1
Riparian Buffer Zone Width Right Bank <u>10</u> Left Bank <u>10</u>	Width of vegetation greater than 18 m <u>LR</u> <u>10</u> 9	Width of vegetation >12 to 18m 8 7 6	Width of vegetation 6 to 12 m. human activities close to system 5 4	Less than 6 m of buffer zone due to intensive human activities 3 2 1
Riparian Zone Vegetation Quality Right Bank <u>8</u> Left Bank <u>8</u> ----- Secondary Score <u>70</u> 72	Over 80% of riparian surfaces consist of normal, expected plant community for given sunlight & habitat conditions (e.g., native plants; tree, shrub, and forbs represented, if appropriate). Minimal disturbance. 10 9	>50% to 80% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Some disruption in community observed. <u>LR</u> <u>8</u> 7 6	25% to 50% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Disruption obvious. 5 4	Less than 25% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). 3 2 1

119

TOTAL SCORE

Date: 3/10/20

Analyst:

Ben Paswater


Signature:

Ben Paswater

2020-03-09-67

DEP Form FD 9000-4 Stream/River Habitat Assessment Sketch Sheet

Site Name: Little Charlie Creek @ 664



Length of grid represents 100 m of stream (not linear meters).
(Horizontal scale is double vertical scale, draw proportionately).

Location: _____

Date: 3-10-20

Sampler: _____

100 m: Latitude _____

Longitude _____

0 m: Latitude _____

Longitude _____

Substrates: Code key, draw proportionate habitat abundance. %

☒ S	Snags	3.1
---------------------------------------	-------	-----

☒ R	Roots/undercut banks	1.9
---------------------------------------	----------------------	-----

☐	Leaf Packs (or mats)	
--------------------------	----------------------	--

☒ V	Aquatic Macrophytes	few
---------------------------------------	---------------------	-----

☐	ROCKS	
--------------------------	-------	--

☐		
--------------------------	--	--

☒ 4	Pools	total # observed = 4 # range expected = 4
---------------------------------------	-------	--

Average width 2.0 m

Average depth 0.5 m

Velocity measured at _____ meter mark.

WQ & chemistry taken at _____ meter mark.

Habitat Smothering:
Note areas (on map) where sand or silt is smothering substrates, limiting habitability.

Bank Stability:
Note areas (on map) with unstable, eroding banks.

Riparian Buffer Width:
Note areas (on map) where natural vegetation is altered or eliminated.

Plants observed / other notes:

S	62
R	38

Site Name: Little Charlie Creek @ 664

21FLTPA

LATITUDE

LONGITUDE

SAMPLING AGENCY FDEP SW ROC

RECEIVING BODY OF WATER

Peace River

RIPARIAN ZONE / STREAM FEATURES

PREDOMINANT LAND-USE IN WATERSHED (specify relative percent in each category): Forest/Natural ☐ 50 ☐ Silviculture ☐ Field/Pasture ☐ 30 ☐ Agricultural ☐ 15 ☐ Residential ☐ 5 ☐ Commercial ☐ Industry ☐ Other (Specify) ☐							Landscape Development Intensity Index (LDI) ☐
Local Watershed Erosion (select one): ☐ None ☒ Slight ☐ Moderate ☐ Heavy Local Watershed NPS Pollution: ☒ No evidence ☐ Slight ☐ Moderate ☐ Heavy							Typical Width (m) Depth (m)/Velocity (m/sec) Transect ☐ 2 m wide ☐ .25 m/s ☐ .25 m/s ☐ .21 m/s ☐ .5 m deep ☐ .6 m deep ☐ .5 m deep
Width of Riparian Vegetation (m) on Each Buffer Side Left Bank: ☐ >18 Right Bank: ☐ >18				Hydrologic Modification Score (per FT 3101) ☐			
High Water Mark: ☐ 1.5 + ☐ 2.5 = ☐ 3.0 (m) (above present water level) (present depth) (above bed)				Artificially Impounded ☐ Yes ☒ No			
Artificially ☒ No ☐ Mostly recovered, more sinuous Channelized: ☐ Some recovery ☐ Recent, severe				Canopy Cover % ☐ Open ☐ Lightly Shaded (11-45%) ☒ Heavily Shaded ☐ Moderate Shaded (46-80%)			

SEDIMENT / SUBSTRATE

Sediment Oils ☒ Absent ☐ Slight ☐ Moderate ☐ Profuse		Sediment Odors ☒ Normal ☐ Sewage ☐ Petroleum ☐ Chemical ☐ Anaerobic ☐ Other (Specify):		Smothering of Substrates Sand Smothering: None ☐ Slight ☒ Moderate ☐ Severe ☐ Silt Smothering: None ☐ Slight ☒ Moderate ☐ Severe ☐ Algae Smothering: None ☐ Slight ☒ Moderate ☐ Severe ☐	
SUBSTRATE TYPE Assessment Tool: ☐ SCI ☒ RPS ☒ LVS ☐ LCI ☐ BioRecon % Coverage Woody Debris (Snags) ☐ 3.1 ☐ Invert ☐ Peri Undercut Banks / Roots ☐ 1.9 ☐ # Times Sampled Leaf Packs or Mat Aquatic Vegetation Rock or Shell Rubble..... Sand..... Mud / Muck / Silt Other Other		WATER QUALITY Depth (M) Temp. (°C) pH (SU) D.O. (MG/L) D.O. Sat (%) Cond. (UMHO/CM) Salinity (PPT) SECCHI (M) Top: ☐ 0.3 ☐ 20.4 ☐ 8.29 ☐ 11.42 ☐ 126.9 ☐ 609 ☐ 0.30 ☐ 0.5 Mid: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☒ VOB Bottom: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ TOTAL DEPTH Meter ID: ☐ Cherry ☐ 0.5			
ABUNDANCE Not Obs. Rare Common Abundant Periphyton: ☐ ☐ ☒ ☐ Fish: ☐ ☐ ☒ ☐ Aquatic Plants: ☐ ☒ ☐ ☐ Iron/Sulfur Bacteria: ☒ ☐ ☐ ☐		Water Odors Normal ☒ Petroleum ☐ Sewage ☐ Chemical ☐ Other ☐ Water Sample Taken? ☒ Yes ☐ No Sample Preserved? ☒ Yes ☐ No Lot Number: see Water Datasheet Algae Sample Taken? ☐ Yes ☒ No Sample Preserved? ☐ Yes ☐ No Lot Number: Exp:			
		Water Surface Oils Normal ☒ Sheen ☐ Globbs ☐ Slick ☐ Other ☐ Color Tannic ☐ Green (Algae) ☐ Clear ☒ Other (Specify) ☐ Clarity Clear ☒ Slightly Turbid ☐ Turbid ☐ Opaque ☐			
System Type: Stream ☒ Lake ☐ Wetland ☐ Estuary ☐ Other (Specify) ☐		AMBIENT FIELD CONDITIONS / NOTES: ☒ The antecedent hydrologic conditions have been met to my best knowledge.			
SAMPLING TEAM Paswater, Ashton		SIGNATURE: Bonham		DATE: 3/10/20	



DEP FORM FD 9000-32: LINEAR VEGETATION SURVEY FIELD

Site Name: Little Charlie Creek @ 664

County:

Waterbody: See Sticker

Date: 3-10-20

Signature: [Signature]

Analyst: [Signature]

Comments: 22m 2

Instructions: Note taxa growing in the water with a checkmark if present, "D" if dominant, and "C" if codominant (dominance only if 1 m² of taxa present). Note in the boxes below if no dominant are selected, and note total macrophyte abundance rank for each section. Only the most common taxa are listed, so use blank spaces for additional taxa names. **BOLD is exotic invasive**

HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)	HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)	
	0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100			0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100		
Alternanthera philoxeroides												Micranthemum glomeratum												
Bacopa caroliniana (Lemon)												Micranthemum umbrosum												
Bacopa monnieri												Myriophyllum aquaticum												
Bidens mitis												Najas guadelupensis												
Boehmeria cylindrica												Nitella sp.												
Centella asiatica												Nuphar luteum												
Ceratophyllum demersum												Orontium aquaticum												
Chara sp.												Panicum hemitomon												
Cicuta maculata												Panicum repens												
Cladium jamaicense												Panicum rigidulum												
Colocasia esculenta												Pistia stratioides												
Commelina diffusa												Polygonum glabra												
Commelina virginica												Polygonum hydropiperoides												
Crinum americanum												Polygonum punctatum												
Cyperus												Pontedaria cordata												
Diodia virginiana												Potamogeton illinoensis												
Eichhornia crassipes												Ruellia simplex (Mex Petunia)												
Eleocharis (wispy viviparous)												Sacciolepis striata												
Fontinalis sp. (Aquatic Moss)												Sagittaria kurziana												
Fraxinus caroliniana												Sagittaria lancifolia												
Hydrilla verticillata												Sagittaria latifolia												
Hydrocotyle sp.												Salvinia minima												
Hygrophila polysperma												Samolus parviflora												
Hymenachne amplexicaulis												Saururus cernuus												
Hymenocallis												Sparganium americanum												
Lachnanthes caroliniana												Schoenoplectus americanus												
Landoltia punctata												Sphagneticola trilobata (Wedelia)												
Lemna sp.												Typha sp.												
Limnophila sessiflora												Urochloa mutica (Brachiaria)												
Ludwigia leptocarpa												Vallisneria americana												
Ludwigia palustris												Zizania aquatica												
Ludwigia peruviana																								
Ludwigia repens																								
Luziola fluitans																								
If no Dominant or Co-Dominant were selected, indicate with "X"																								
Indicate % cover macrophytes per section																								
0-5% Macrophyte Coverage																								
>5 and ≤10% Macrophyte Coverage																								
>10 and ≤25% Macrophyte Coverage																								
>25 and ≤50% Macrophyte Coverage																								
> 50% Macrophyte Coverage																								

635W0089 DEP FORM FD 9000-25 Rapid Periphyton Survey Field Sheet										
Site: LITTLE CHARLIE CREEK 2664					County:		Date: 3-10-20		Investigators:	
Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	STORET Station Number: 635W0089
0	1	N		90	60	1	N		94	
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
10	1	N		90	70	1	N		60	
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
20	1	N		90	80	1	N		80	
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
30	1	N		90	90	1	N		92	
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
40	1	N		90	100	1	N		94	
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
50	1	N		90	Record "N" and check "Estimated" for points deeper than the Secchi depth; algae are presumed absent. Check "Estimated" if thickness estimated for deep points which can be seen but not reached. *Record "X" for points shallower than Secchi depth for which substrate cannot be seen or reached with the hand. No estimated rank. Record canopy cover as the number of small densiometer quadrants (out of 96) that HAVE canopy cover. Measure facing upstream at point 4, 5, or 6. Collect algal mat sample following DEP SOP FS 7240 if the percentage of total sampled points with a thickness rank of 4, 5, or 6 is >20%.					
	2									
	3									
	4									
	5									
	6									
	7									
	8									
	9									

Secchi depth	0.5
Estimated?	NO

# points ranked 4-6	3
total points assessed	99
% points ranked 4-6	3

Check accompanying data collected at same site/date.	
Algal mat sample	
Linear Veg Survey	✓
Habitat Assessment	✓
SCI/Biorecon	
Water sample	✓
RQ-2020-03-09-67	

Algal Thickness Rank	
N	rough, no algae, slimy, algae up to 1mm
3	>1mm - 6mm
4	>6mm - 20mm
5	>20mm - 10 cm
6	>10 cm

*If you can see the secchi on the bottom, but you cannot see or reach surrounding substrate use "X"

0.21 m/s
2.5 H1 4502