

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
CHAIN OF CUSTODY FORM

Date:	12/8/2020	Collected By:	Ben Paswater, Judy Ashton
Customer:	SW-DIST	Sampling Agency:	FDEP
RQ:	RQ-2020-10-26-02	Project ID:	SMP

PLEASE RETURN THE ORIGINAL OF THIS FORM WITH SAMPLE SUBMITTAL
FORMS AND THE COOLER PACKING WORKSHEET TO THE LAB**Number of Coolers Shipped: 1****FIELD ID (Labels) submitted under this RQ for this collection date.**

Site Location	Field ID/WIN ID
Wildcat Slough @ Mosaic S2	 G3SW0055

RELINQUISHED BY(SIGNATURE):



DATE/TIME:

12/08/2020

THIS SECTION TO BE COMPLETED BY LABORATORY

Rec'd/Inspected By:

Rec'd/Inspected Date:



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION STRATEGIC MONITORING PROGRAM FIELD SHEET

January 2020

Meter Passed End
of Day CCV
Yes

WIN Station Name: Wildcat Slough @ Mosaic S2 **Date:** 12/8/2020
WIN/Field ID: G3SW0055 **WBID:** 1955 **ENR:** **Latitude:** 27.2362
County: MANATEE **Org ID:** 21FLTPA **Longitude:** -82.1067
Receiving Body of Water: Sarasota Bay - Peace - Myakka **RQ:** 2020-10-26-02

Sampling Team Members		WQ Measurements	Sample Collection	Documentation	Preservation	Preservation Check
☒	Ben Paswater	x		x		
☒	Judy Ashton		x		x	x
☐						
☐						

Sampling Equipment	
☒ Sample Container	☐ Carboy
☐ Dipper	☐ Van Dorn
☐ Syringe	☐ Pole
Depth measured with: Secchi	
Secchi Equipment ID: Secchi #3	
Collection Method	
☒ Wading	☐ Canoe/Kayak
☐ From Shore	☐ Electric Motor
☐ Other _____	☐ Gasoline Motor

Water Level: ☒ Normal ☐ Low ☐ High ☐ Dry ☐ Pooled ☐ Flooded						Meter ID# SWD							
Photos: YES		Flow: FLOW		Tide:		Tide Times: High: Low:							
Biological Samples Collected: ☒ None ☒ HA ☐ SCI ☒ RPS ☐ Algae ID ☒ LVS ☐ LVI Other:													
SBIO ID Numbers:													
Notes:													

Duplicate Sample

Time Zone: EST	Time: N/A	Field ID: N/A	(WIN ID_DUP)
WIN DMT Activity ID: _____			

Blank

Time Zone: _____	Time: N/A	Field ID: N/A	(Blank Type_DDMYYYY)
DI Source: N/A		Location: N/A	
DI Type: N/A		Equipment ID: N/A	

LIMS EVENT ID: _____ **WIN Import ID:** _____
Enter Field Parameters, Verify Station ID In LIMS DMT: _____ **QC Station ID, Field Parameters In LIMS DMT:** _____
(Initials/Date) (Initials/Date)
Scan/Save Field Sheets _____ **Migrate Data to WIN:** _____ **Verify Data In WIN:** _____
(Initials/Date) (Initials/Date) (Initials/Date)



RQ-2020-10-26-02

Customer: WQAP

Project ID: SMP

Collected By: Ben Paswater, Judy Ashton

Field Report Prepared By: Ben Paswater

Sampling Agency: FDEP

Place Label Here

WIN ID/Field ID:



G3SW0055

Location: Wildcat Slough @ Mosaic S2

Comments:

Matrix: Fresh

(Check one)

☒ GRAB☐ COMPOSITE

Date	Time	DO (mg/L)	DO (%SAT)	Temp. (C°)	pH	Sample Depth (m)	Secchi Disk (m)	Total Depth (m)	Sp COND (µmhos/cm)	Salinity (PPTH)
12/8/2020	EST	7.93	80.4	16	5.88	0.3	0.5 ☒ VOB (S)	0.5	402.8	0.19

Central Lab please use top row for login purposes

EST										
-----	--	--	--	--	--	--	--	--	--	--

Parameter Suite	Parameter Methods	Preservation	pH Check	# Bottles sent to Lab	Bottle Group
Preserved Nutrients (P-500ML)	☒ W-NH3 / W-NO2NO3 / W-TKN / W-TOC / W-S-A-TP Lot # _____ Exp: _____	☒ Ice ☐ H2SO4*	☒ <2	1	A
Metals (P-500ML)	☐ W-ICPMS ☐ W-ICP ☐ W-HARD Lot # _____ Exp: _____	☐ Ice ☐ HNO3*	☐ <2		
Filtered Nutrients (P125ML)	☒ W-PO4-F ☒ Field Filtered 0.45 µm Filter Filter Lot # _____ Syringe Lot # _____	☒ Ice		1	A
Chlorophyll (BP-1L)	☒ CHLSUITE-W	☒ Ice		1	A
Physical/Aggregate (Fresh) (P-1L)	☒ Alkalinity / W-F / W-TSS / TURBIDITY / W-CL-IC / W-COLOR / W-SO4-IC / W-TDS	☒ Ice		1	A
Physical/Aggregate (Marine) (P-1L)	☐ Alkalinity / W-BR-IC / W-F / W-TSS / TURBIDITY	☐ Ice			
Macroinvertebrates (PJ-2L)	☐ MI-FW-QLDC	☐ Formalin			
Periphyton (PT-50ML)	☐ ALGAE-ID	☐ Ice			
Microbiology (Contract Lab Bottle)	☒ E Coli ☐ F Coli ☐ Enterococci ☒ Contract Lab	☒ Ice		1	A
Molecular (QPCR-P-500ML)	☐ PCR-HF183 ☐ PCR-BacR ☐ PCR-DG3 ☐ PCR-GULL2 ☐ PCR-GFD	☐ Ice			
Tracers (BG-500ML)	☐ W-E8321-DI ☐ W-E8321-MS	☐ Ice			
Pesticides (BG-500ML) (BG-1L)	☐ W-E8321-DI ☐ WE8321-MS ☐ W-PSNP-TQ ☐ W-CT-CL-R ☐ W-PCL-SQ-R ☐ W-CARB-AA (5 ml of MCAA** Buffer Solution)	☐ Ice			
		☐ Ice			

Name:
Ben Paswater
Judy Ashton

Signature:

Date:

12/08/2020

*2.0 ml of Preservative used unless noted otherwise.

**MCAA: Monochloroacetic acid buffer solution

Site Name:

Wildcat Slough

STORET STATION
NUMBER: see sticker

DATE (MM/DD/YYYY):

12/8/2020

SAMPLING AGENCY:

FDEP SWROC

COUNTY:

Manatee

RECEIVING BODY OF WATER:

Myakka

Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
Primary Habitat Components	Four or more major productive habitats present (snags, tree roots, aquatic vegetation, leaf packs (partially decayed), rock)	Three major productive habitats present. Adequate habitat. Some substrates may be new fall (fresh leaves or snags)	Two major productive habitats present. Less than desirable habitat, frequently disturbed or removed	One or less major productive habitat. Lack of habitat is obvious, substrates unstable or smothered
Substrate Diversity <u>8</u>	20 19 18 17 16	15 14 13 12 11	10 9 <u>8</u> 7 6	5 4 3 2 1
Substrate Availability <u>6</u>	Greater than 30% major productive habitat present at site 20 19 18 17 16	16% to 30% major productive habitat, by aerial extent 15 14 13 12 11	6% to 15% major productive habitat 10 9 8 7 <u>6</u>	Less than 5% major productive habitat 5 4 3 2 1
Water Velocity <u>18</u>	Max. observed at typical transect: > 0.25 m/sec. But < 1 m/sec ≥0.33 0.31 0.29 0.27 >0.25 20 19 <u>18</u> 17 16	Max. observed at typical transect: >0.1 to 0.25 m/sec 0.25 0.21 0.17 0.13 >0.1 15 14 13 12 11	Max. observed at typical transect: 0.05 to 0.1 m/sec 0.1 0.09 0.07 0.06 0.05 10 9 8 7 6	Max. observed at typical transect: <0.05 m/sec; or spate occurring: > 1 m/sec <0.05 0.04 0.03 0.01 <0.01 5 4 3 2 1
Habitat Smothering <u>8</u> ----- Primary Score <u>40</u>	Adequate number of stable pools (1-2 per 12 times width) and <25% of habitats affected by sand, silt, or algae. 20 19 18 17 16	Adequate number of stable pools (1-2 per 12 times width) and >25% of habitats affected by sand, silt, or algae. 15 14 13 12 11	Does not have required number of stable pools (1-2 per 12 x width) and/or has shallow pools (<2 x prevailing depth). 10 9 <u>8</u> 7 6	Stable pools are absent. Most habitats affected by sand, silt, or algae accumulation. 5 4 3 2 1
Secondary Habitat Components	Expected sinuosity given the stream width. No evidence of dredging or artificial straightening. No spoil banks.	Good sinuosity within old channelized area. Evidence of dredging in the past (>25 yrs) but mostly recovered.	Straightened with trapezoidal cross section, but has a small degree of sinuosity developed within channelized area.	Straightened or engineered by dredging, has trapezoidal or box cut cross section, lacks required pools. May have spoil banks.
Artificial Channelization <u>18</u>	20 19 <u>18</u> 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Bank Stability	Bankfull > 60% of bank height. Slope of bank ≤ 60° from bankfull to top of bank. Bankfull is within or above the root zone with few raw, eroded areas.	Only meets 2 of the 3 requirements for optimal bank stability.	Only meets 1 of the 3 requirements for optimal bank stability.	Bankfull < 60% of bank height. Slope of bank > 60°. Bankfull is below the root zone with raw, eroded areas.
Right Bank <u>7</u> Left Bank <u>7</u>	10 9	<u>8</u> <u>7</u> 6 LR	5 4	3 2 1
Riparian Buffer Zone Width	Width of vegetation greater than 18 m	Width of vegetation >12 to 18m	Width of vegetation 6 to 12 m. human activities close to system	Less than 6 m of buffer zone due to intensive human activities
Right Bank <u>7</u> Left Bank <u>6</u>	10 9	<u>8</u> <u>7</u> <u>6</u> LR	5 4	3 2 1
Riparian Zone Vegetation Quality	Over 80% of riparian surfaces consist of normal, expected plant community for given sunlight & habitat conditions (e.g., native plants; tree, shrub, and forbs represented, if appropriate). Minimal disturbance.	>50% to 80% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Some disruption in community observed.	25% to 50% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Disruption obvious.	Less than 25% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions).
Right Bank <u>8</u> Left Bank <u>8</u> ----- Secondary Score <u>61</u>	10 9	<u>8</u> 7 6 LR	5 4	3 2 1

TOTAL SCORE

101

Date:

12/8/2020

Analyst:

Ben Paswater

Signature:

Ben Paswater



2020-10-26-02

12-8-20

Site Name:

Wildcat Slough

EP FORM FD 9000-25 Rapid Periphyton Survey Field Sh

Investigators: J. Ashton

County: DeSoto

STORET Station Number: see label MANATEE

Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	
0	1	N			60	1	N			
	2					2				
	3					3				
	4					4				
	5			52		5				96
	6					6				
	7					7				
	8					8				
	9					9				
10	1	N			70	1	N			
	2					2				
	3					3				
	4					4				
	5			96		5				63
	6					6				
	7					7				
	8					8				
	9					9				
20	1	N			80	1	N			
	2					2				
	3					3				
	4					4				
	5			24		5				80
	6					6				
	7					7				
	8					8				
	9					9				
30	1	N			90	1	N			
	2					2				
	3					3				
	4					4				
	5			30		5				96
	6					6				
	7					7				
	8					8				
	9					9				
40	1	N			100	1	N			
	2					2				
	3					3				
	4					4				
	5			22		5				90
	6					6				
	7					7				
	8					8				
	9					9				
50	1	N				1	N			
	2					2				
	3					3				
	4					4				
	5			68		5				
	6					6				
	7					7				
	8					8				
	9					9				

Secchi depth

Estimated?

No

points ranked 4-6

total points assessed

% points ranked 4-6

Check accompanying data collected at same site/date.

Algal mat sample

Linear Veg Survey

Habitat Assessment

SCI/Biorecon

Water sample

RQ-2020-10-26-02

Algal Thickness Rank

N

rough, no algae, slimy, algae up to 1mm

3

>1mm - 6mm

4

>6mm - 20mm

5

>20mm - 10 cm

6

>10 cm

Record "N" and check "Estimated" for points deeper than the Secchi depth; algae are presumed absent. Check "Estimated" if thickness estimated for deep points which can be seen but not reached.

Record "X" for points shallower than Secchi depth for which substrate cannot be seen or reached with the hand. No estimated rank.

Record canopy cover as the number of small densiometer quadrants (out of 96) that HAVE canopy cover. Measure facing upstream at point 4, 5, or 6.

Collect algal mat sample following DEP SOP FS 7240 if the percentage of total sampled points with a thickness rank of 4, 5, or 6 is >20%.

Date	11-8-20	Time	1417
------	---------	------	------

Site Name:

Wildcat Slough

County:

Alameda

Waterbody: See Sticker

Date:

12-8-20

Signature:

J. Ashman

Analyst:

J. Ashman

Instructions: Note taxa growing in the water with a checkmark if present, "D" if dominant, and "C" if codominant (dominance only if 1 m² of taxa present). Note in the boxes below if no dominant are selected, and note total macrophyte abundance rank for each section. Only the most common taxa are listed, so use blank spaces for additional taxa names. **BOLD is exotic invasive**


HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)	HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)
	0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100			0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100	
Alternanthera philoxeroides										X		Micranthemum glomeratum											
Bacopa caroliniana (Lemon)										X		Micranthemum umbrosum											
Bacopa monnieri												Myriophyllum aquaticum											
Bidens mitis												Najas guadelupensis											
Boehmeria cylindrica												Nitella sp.											
Centella asiatica												Nuphar luteum											
Ceratophyllum demersum												Orontium aquaticum											
Chara sp.												Panicum hemitomon											
Cicuta maculata												Panicum repens											
Cladium jamaicense												Panicum rigidulum											
Colocasia esculenta												Pistia stratioides											
Commelina diffusa												Polygonum glabra											
Commelina virginica												Polygonum hydropiperoides											
Crinum americanum												Polygonum punctatum											
Cyperus												Pontedaria cordata											
Diodia virginiana												Potamogeton illinoensis											
Eichhornia crassipes												Ruellia simplex											
Eleocharis (wispy viviparous)												Sacciolepis striata											
Fontinalis sp. (Aquatic Moss)												Sagittaria kurziana											
Fraxinus caroliniana												Sagittaria lancifolia											
Hydrilla verticillata												Sagittaria latifolia											
Hydrocotyle sp.												Salvinia minima											
Hygrophila polysperma												Samolus parviflora											
Hymenachne amplexicaulis												Saururus cernuus											
Hymenocallis												Sparganium americanum											
Lachnanthes caroliniana												Schoenoplectus americanus											
Landoltia punctata												Sphagneticola trilobata (Wedelia)											
Lemna sp.												Typha sp.											
Limnophila sessiflora												Urochloa mutica (Brachiaria)									X		
Ludwigia leptocarpa												Vallisneria americana											
Ludwigia palustris												Zizania aquatica											
Ludwigia peruviana																							
Ludwigia repens	X	X	X	X	X	X	X	X	X	X													
Luziola fluitans																							
If no Dominant or Co-Dominant were selected, indicate with "X"																							
Indicate % cover macrophytes per section																							
0-5% Macrophyte Coverage	X	X	X	X	X	X	X	X	X	X											X		
>5 and ≤10% Macrophyte Coverage	X	X	X	X	X	X	X	X	X	X													
>10 and ≤25% Macrophyte Coverage																							
>25 and ≤50% Macrophyte Coverage																							
> 50% Macrophyte Coverage																							



Site Name:

Wildcat Slough

DEP Form FD 9000-4 Stream/River Habitat Assessment Sketch Sheet

Left
Bank

Length of grid represents 100 m of stream (not linear meters).
(Horizontal scale is double vertical scale, draw proportionately).

Location:

Date:

Sampler:

100 m: Latitude

Longitude

0 m: Latitude

Longitude

Substrates: Code key, draw
proportionate habitat abundance. %



Snags

1.9



Roots/undercut banks

few



Leaf Packs (or mats)



Aquatic Macrophytes

4.4



ROCKS



Pools

total # observed = 1

range expected =

Average width _____ m

Average depth _____ m

Velocity measured at 0.50, 1.00 meter mark.

WQ & chemistry taken at _____ meter mark.

Habitat Smothering:

Note areas (on map) where sand or silt is
smothering substrates, limiting habitability.

Bank Stability:

Note areas (on map) with unstable, eroding
banks.

Riparian Buffer Width:

Note areas (on map) where natural vegetation
is altered or eliminated.

Plants observed / other notes:

S = 38/2000 1.9
V = 88/2000 4.4
Handwritten notes and sketches are present below the grid.