

Document Reference # 05.1.0

Laboratory: Wetlands Research Laboratory

MM

Page 1 of 1

Date/Time: 1/20/21 1:1244

Date/Time: 1/20/21 1:12:49

CS

[illegible]

Surface water, no chlorine expected

Contact name

Phone:

Sampler's name:

2r = rain water, FV = Fresh water, GV = Ground water, FVW = Freshwater, MVW = Marine water, BW = Blackish Water, S = soil/sediment, Other X =

³ Recorded using IRT-2