



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION STRATEGIC MONITORING PROGRAM FIELD SHEET

January 2020

Meter Passed End

of Day CCV

Yes / No

WIN Station Name: Mizelle Creek In Park

Date: 1/6/2021

WIN/Field ID: G2SW0131

WBID: 1665A

ENR:

Latitude: 27.846

County: HILLSBOROUGH

Org ID: 21FLTPA

Longitude: -82.1098

Receiving Body of Water:

Alafia River

RQ: 2021-01-04-46

Sampling Team Members		WQ Measurements	Sample Collection	Documentation	Preservation	Preservation Check
☒	Ben Paswater	x	x	x	x	x
☒	Sarah Meyer		x	x		
☐						
☐						

Sampling Equipment	
☒ Sample Container	☐ Carboy
☐ Dipper	☐ Van Dorn
☐ Syringe	☐ Pole
Depth measured with: Secchi	
Secchi Equipment ID: Secchi #3	
Collection Method	
☒ Wading	☐ Canoe/Kayak
☐ From Shore	☐ Electric Motor
☐ Other	☐ Gasoline Motor

Water Level: ☒ Normal ☐ Low ☐ High ☐ Dry ☐ Pooled ☐ Flooded						Meter ID# SWD							
Photos: YES		Flow: FLOW		Tide: N/A		Tide Times: High: Low:							
Biological Samples Collected: ☐ None ☒ HA ☒ SCI ☒ RPS ☐ Algae ID ☒ LVS ☐ LVI Other:													
SBIO ID Numbers: SBIO ID 81830 HA 16747 RPS 9657 BenthID: 45328													
Notes:													

Duplicate Sample

Time Zone: EST	Time:	Field ID: N/A	(WIN ID_DUP)
WIN DMT Activity ID:			

Blank

Time Zone:	Time:	Field ID:	(Blank Type_DDDMMYY)
DI Source:		Location:	
DI Type:		Equipment ID:	
DI Container (Name/ID):		DI Container Type:	

LIMS EVENT ID: SW_DIST_01-07-01

WIN Import ID: 25469

Enter Field Parameters, Verify Station ID In LIMS DMT: 04/07/2021 SM

(Initials/Date)

QC Station ID, Field Parameters In LIMS DMT: 05/17/2021 SM

(Initials/Date)

Scan/Save Field Sheets 8/11/2022 BP

(Initials/Date)

Migrate Data to WIN: 05/17/2021 SM

(Initials/Date)

Verify Data In WIN: 05/17/2021 SM

(Initials/Date)



RQ-2021-01-04-46

Customer: SWDST

Project ID: SMP

Collected By: Ben Paswater, Sarah Meyer

Field Report Prepared By: Ben Paswater

Sampling Agency: SWROC (FDEP)

Place Label Here

WIN ID/Field ID:



G2SW0131

Location: Mizelle Creek In Park

Comments:

Matrix: Fresh

(Check one)

☒ GRAB☐ COMPOSITE

Date	Time	DO (mg/L)	DO (%SAT)	Temp. (C°)	pH	Sample Depth (m)	Secchi Disk (m)	Total Depth (m)	Sp COND (µmhos/cm)	Salinity (PPT _h)
1/6/2021	1150 EST	10.11	96.1	13	7.45	0.3	0.5 ☒ VOB (S)	0.5	220.6	0.11
	EST						Central Lab please use top row for login purposes			

Parameter Suite	Parameter Methods	Preservation	pH Check	# Bottles sent to Lab	Bottle Group
Preserved Nutrients (P-500ML)	☒ W-NH3 / W-NO2NO3 / W-TKN / W-TOC / W-S-A-TP	☒ Ice ☒ H2SO4*	☒ <2	1	A
	Lot # Not Recorded Exp: Not Recorded				
Metals (P-500ML)	☒ W-ICPMS ☒ W-ICP ☒ W-HARD	☒ Ice ☒ HNO3*	☒ <2	1	A
	Lot # Not Recorded Exp: Not Recorded				
Filtered Nutrients (P125ML)	☒ W-PO4-F ☒ Field Filtered 0.45 µm Filter	☒ Ice		1	A
	Filter Lot # Not Recorded				
	Syringe Lot # Not Recorded				
Chlorophyll (BP-1L)	☒ CHLSUITE-W	☒ Ice		1	A
Physical/Aggregate (Fresh) (P-1L)	☒ Alkalinity / W-F / W-TSS / TURBIDITY / W-CL-IC / W-COLOR / W-SO4-IC / W-TDS	☒ Ice		1	A
Physical/Aggregate (Marine) (P-1L)	☐ Alkalinity / W-BR-IC / W-F / W-TSS / TURBIDITY	☐ Ice			
Macroinvertebrates (PJ-2L)	☒ MI-FW-QLDC	☒ Formalin		2	B
Periphyton (PT-50ML)	☐ ALGAE-ID	☐ Ice			
Microbiology (Contract Lab Bottle)	☐ E Coli ☐ F Coli ☐ Enterococci ☐ Contract Lab	☐ Ice			
Molecular (QPCR-P-500ML)	☐ PCR-HF183 ☐ PCR-BacR ☐ PCR-DG3 ☐ PCR-GULL2 ☐ PCR-GFD ☐	☐ Ice			
Tracers (BG-500ML)	☐ W-E8321-DI ☐ W-E8321-MS	☐ Ice			
Pesticides (BG-500ML) (BG-1L)	☐ W-E8321-DI ☐ WE8321-MS ☐ W-PSNP-TQ ☐ W-CT-CL-R	☐ Ice			
	☐ W-PCL-SQ-R ☐ W-CARB-AA (5 ml of MCAA** Buffer Solution) ☐ W-DIELDRIN				
Phytoplankton/Periphyton	☐ DTM-QL-C ☐ PEN-QL-C ☐ DTY-QN-C ☐ PKD-QN-C	☐ Ice			
	☐ DTM-QN-C ☐ PRN-QN-C ☐ PKD-QN-BV ☐				

Name:
Ben Paswater
Sarah Meyer

Signature:

Benjamin Paswater

Date:

1/6/2021

*2.0 ml of Preservative used unless noted otherwise.

**MCAA: Monochloroacetic acid buffer solution

G2SW0131

DEP Form FD 9000-5 Stream/River Habitat Assessment Sheet

Site Name:

Mizelle Creek in Park

STORET STATION
NUMBER: see sticker

DATE (MM/DD/YYYY):

10/6/21 1150

SAMPLING AGENCY:

FDEP SWROC

COUNTY:

Hillsborough

RECEIVING BODY OF WATER:

Alafia

Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
Primary Habitat Components	Four or more major productive habitats present (snags, tree roots, aquatic vegetation, leaf packs (partially decayed), rock)	Three major productive habitats present. Adequate habitat. Some substrates may be new fall (fresh leaves or snags)	Two major productive habitats present. Less than desirable habitat, frequently disturbed or removed	One or less major productive habitat. Lack of habitat is obvious, substrates unstable or smothered
Substrate Diversity <u>11</u>	20 19 18 17 16	15 14 13 12 <u>11</u>	10 9 8 7 6	5 4 3 2 1
Substrate Availability <u>5</u>	Greater than 30% major productive habitat present at site 20 19 18 17 16	16% to 30% major productive habitat, by aerial extent 15 14 13 12 11	6% to 15% major productive habitat 10 9 8 7 6	Less than 5% major productive habitat <u>5</u> 4 3 2 1
Water Velocity <u>15</u>	Max. observed at typical transect: > 0.25 m/sec. But < 1 m/sec ≥0.33 0.31 0.29 0.27 >0.25 20 19 18 17 16	Max. observed at typical transect: >0.1 to 0.25 m/sec 0.25 0.21 0.17 0.13 >0.1 <u>15</u> 14 13 12 11	Max. observed at typical transect: 0.05 to 0.1 m/sec 0.1 0.09 0.07 0.06 0.05 10 9 8 7 6	Max. observed at typical transect: <0.05 m/sec; or spate occurring: > 1 m/sec <0.05 0.04 0.03 0.01 <0.01 5 4 3 2 1
Habitat Smothering <u>12</u> ----- Primary Score <u>43</u>	Adequate number of stable pools (1-2 per 12 times width) and <25% of habitats affected by sand, silt, or algae. 20 19 18 17 16	Adequate number of stable pools (1-2 per 12 times width) and >25% of habitats affected by sand, silt, or algae. 15 14 13 <u>12</u> 11	Does not have required number of stable pools (1-2 per 12 x width) and/or has shallow pools (<2 x prevailing depth). 10 9 8 7 6	Stable pools are absent. Most habitats affected by sand, silt, or algae accumulation. 5 4 3 2 1
Secondary Habitat Components	Expected sinuosity given the stream width. No evidence of dredging or artificial straightening. No spoil banks.	Good sinuosity within old channelized area. Evidence of dredging in the past (>25 yrs) but mostly recovered.	Straightened with trapezoidal cross section, but has a small degree of sinuosity developed within channelized area.	Straightened or engineered by dredging, has trapezoidal or box cut cross section, lacks required pools. May have spoil banks.
Artificial Channelization <u>19</u>	20 <u>19</u> 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Bank Stability	Bankfull > 60% of bank height. Slope of bank ≤ 60° from bankfull to top of bank. Bankfull is within or above the root zone with few raw, eroded areas.	Only meets 2 of the 3 requirements for optimal bank stability.	Only meets 1 of the 3 requirements for optimal bank stability.	Bankfull < 60% of bank height. Slope of bank > 60°. Bankfull is below the root zone with raw, eroded areas.
Right Bank <u>7</u> Left Bank <u>7</u>	10 9	8 <u>7</u> 6	5 4	3 2 1
Riparian Buffer Zone Width	Width of vegetation greater than 18 m	Width of vegetation >12 to 18m	Width of vegetation 6 to 12 m. human activities close to system	Less than 6 m of buffer zone due to intensive human activities
Right Bank <u>10</u> Left Bank <u>10</u>	<u>10</u> 9	8 7 6	5 4	3 2 1
Riparian Zone Vegetation Quality	Over 80% of riparian surfaces consist of normal, expected plant community for given sunlight & habitat conditions (e.g., native plants; tree, shrub, and forbs represented, if appropriate). Minimal disturbance.	>50% to 80% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Some disruption in community observed.	25% to 50% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Disruption obvious.	Less than 25% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions).
Right Bank <u>8</u> Left Bank <u>8</u>	10 9	<u>8</u> 7 6	5 4	3 2 1
Secondary Score <u>69</u>				

TOTAL SCORE

Date: 1/6/2021

Analyst:

Ben Aswate

Sarah Meyer

Signature:

Ben Aswate

ID

81830

HA

RAS 9657

16747



Site Name:

Mizelle Creek in Park

DEP FORM FD 9000-25 Rapid Periphyton Survey Field Sheet

Investigators:

BP Sm

County:

Hills.

STORET Station Number: see label

Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	Transect (m)	Point 1=right 9=left	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	
0	1	N			60	1	N			
	2					2				
	3					3				
	4					4				
	5			52		5			83	
	6					6				
	7					7				
	8					8				
	9					9				
10	1	N			70	1	N			
	2					2				
	3					3				
	4					4				
	5			56		5			61	
	6					6				
	7					7				
	8					8				
	9					9				
20	1	N			80	1	N			
	2					2				
	3					3				
	4					4				
	5			24		5			38	
	6					6				
	7					7				
	8					8				
	9					9				
30	1	N			90	1	N			
	2					2				
	3					3				
	4					4				
	5			92		5			48	
	6					6				
	7					7				
	8					8				
	9					9				
40	1	N			100	1	N			
	2					2				
	3					3				
	4					4				
	5			96		5			28	
	6					6				
	7					7				
	8					8				
	9					9				
50	1	N				1	N			
	2					2				
	3					3				
	4					4				
	5			96		5				
	6					6				
	7					7				
	8					8				
	9					9				

Secchi depth 0.5
Estimated? No

points ranked 4-6 0
total points assessed 99
% points ranked 4-6 0

Check accompanying data collected at same site/date.

Algal mat sample

Linear Veg Survey

Habitat Assessment

SCI/Biorecon

Water sample

RQ- 2021-01-04-46

Algal Thickness Rank

N	rough, no algae, slimy, algae up to 1mm
3	>1mm - 6mm
4	>6mm - 20mm
5	>20mm - 10 cm
6	>10 cm

Record "N" and check "Estimated" for points deeper than the Secchi depth; algae are presumed absent. Check "Estimated" if thickness estimated for deep points which can be seen but not reached.

Record "X" for points shallower than Secchi depth for which substrate cannot be seen or reached with the hand. No estimated rank.

Record canopy cover as the number of small densiometer quadrants (out of 96) that HAVE canopy cover. Measure facing upstream at point 4, 5, or 6.

Collect algal mat sample following DEP SOP FS 7240 if the percentage of total sampled points with a thickness rank of 4, 5, or 6 is >20%.



1FLTPA

LATITUDE 27.84599

LONGITUDE -82.10980

Site Name:

Mizelle Creek in Park

SAMPLING AGENCY FDEP SW ROC

WATER

RIPARIAN ZONE / STREAM FEATURES

PREDOMINANT LAND-USE IN WATERSHED (specify relative percent in each category):

Forest/Natural ☐ 30 ☐ Silviculture ☐ Field/Pasture ☐ 40 ☐ Agricultural ☐ 5 ☐ Residential ☐ Commercial ☐ 25 ☐ Industry ☐ Other (Specify) ☐

Landscape Development Intensity Index (LDI)

Local Watershed Erosion (select one): ☐ None ☐ Slight ☒ Moderate ☐ HeavyLocal Watershed NPS Pollution: ☐ No evidence ☒ Slight ☐ Moderate ☐ Heavy

Width of Riparian Vegetation (m) on Each Buffer Side

Left Bank: 218 Right Bank: 218

Hydrologic Modification Score (per FT 3101)

4

High Water Mark: 2 + .5 = 2.5
(m) (above present water level) (present depth) (above bed)

Artificially Impounded

☐ Yes ☒ NoArtificially ☒ No☐ Mostly recovered, more sinuousChannelized: ☐ Some recovery☐ Recent, severe

Canopy Cover %

☐ Open☐ Lightly Shaded (11-45%)☐ Heavily Shaded☒ Moderate Shaded (46-80%)

Typical Width (m) Depth (m)/Velocity (m/sec) Transect

5 m wide

.25 m/s .25 m/s .25 m/s

.3 m deep .6 m deep .3 m deep

SEDIMENT / SUBSTRATE

Sediment Oils

☒ Absent ☐ Slight
☐ Moderate ☐ Profuse

Sediment Odors

☒ Normal ☐ Sewage ☐ Petroleum
☐ Chemical ☐ Anaerobic
☐ Other (Specify):

Smothering of Substrates

Sand Smothering: None ☐ Slight ☐ Moderate ☒ Severe ☐
Silt Smothering: None ☐ Slight ☒ Moderate ☐ Severe ☐
Algae Smothering: None ☒ Slight ☐ Moderate ☐ Severe ☐

SUBSTRATE TYPE

Assessment Tool: ☒ SCI ☒ RPS ☒ LVS☐ LCI ☐ BioRecon

INVERT PERI
% # Times # Times
Coverage Sampled Sampled

Woody Debris (Snags) ☐ 5 ☐Undercut Banks / Roots ☐ 5 ☐Leaf Packs or Mat ☐ 5 ☐Aquatic Vegetation ☐ ☐Rock or Shell Rubble.. ☐ ☐Sand..... ☐ ☐Mud / Muck / Silt ☐ ☐Other ☐ 5 ☐Other ☐ ☐

WATER QUALITY

Depth (M) Temp. (°C) pH (SU) D.O. (MG/L) D.O. Sat (%) Cond. (UMHO/CM) Salinity (PPT) SECCHI (M)
Top: .3 13 7.45 10.11 96.1 220.6 .11 .5
Mid: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☒ VOB
Bottom: ☐ ☐ ☐ ☐ ☐ ☐ ☐ TOTAL DEPTH
Meter ID: SWD .5

Water Odors Normal ☒ Petroleum ☐
Sewage ☐ Chemical ☐ Other ☐

Water Sample Taken? ☒ Yes ☐ NoSample Preserved? ☒ Yes ☐ No

Lot Number: Exp:

Algae Sample Taken? ☐ Yes ☒ NoSample Preserved? ☐ Yes ☐ No

Lot Number: Exp:

Water Surface Oils Normal ☒ Sheen ☐
Globs ☐ Slick ☐ Other ☐

Color Tannic ☐ Green (Algae) ☐
Clear ☒ Other (Specify) ☐

Clarity Clear ☒ Slightly Turbid ☐
Turbid ☐ Opaque ☐

ABUNDANCE

Not Obs. Rare Common Abundant

Periphyton: ☐ ☒ ☐ ☐Fish: ☐ ☐ ☒ ☐Aquatic Plants: ☐ ☒ ☐ ☐Iron/Sulfur Bacteria: ☒ ☐ ☐ ☐System Type: Stream ☒ Lake ☐ Wetland ☐ Estuary ☐ Other(Specify) ☐

AMBIENT FIELD CONDITIONS / NOTES:

☒ The antecedent hydrologic conditions have been met to my best knowledge.

SAMPLING TEAM

Ben Paswater, Sarah Meyer

SIGNATURE:

Ben Paswater

DATE:

1/6/2021



DEP FORM FD 9000-32: LINEAR VEGETATION SURVEY FIELD

Site Name:

Mizelle Creek in Park

County: Hillsborough

Waterbody: See Sticker

Date: 01/06/2021

Signature: Benjamin Paswater

Analyst: Ben Paswater

Comments:

Instructions: Note taxa growing in the water with a checkmark if present, "D" if dominant, and "C" if codominant (dominance only if 1 m² of taxa present). Note in the boxes below if no dominant are selected, and note total macrophyte abundance rank for each section. Only the most common taxa are listed, so use blank spaces for additional taxa names. **BOLD is exotic invasive**

HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)	HERBACEOUS SPECIES	Meter Mark										Specimen collected (check)
	0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100			0-10	10-20	20-30	30-40	40-50	50-60	60-70	70-80	80-90	90-100	
Alternanthera philoxeroides												Micranthemum glomeratum											
Bacopa caroliniana (Lemon)												Micranthemum umbrosum											
Bacopa monnieri												Myriophyllum aquaticum											
Bidens mitis												Najas guadelupensis											
Boehmeria cylindrica												Nitella sp.											
Centella asiatica												Nuphar luteum											
Ceratophyllum demersum												Orontium aquaticum											
Chara sp.												Panicum hemitomon											
Cicuta maculata												Panicum repens											
Cladium jamaicense												Panicum rigidulum											
Colocasia esculenta												Pistia stratioides											
Commelina diffusa												Polygonum glabra											
Commelina virginica												Polygonum hydropiperoides											
Crinum americanum												Polygonum punctatum											
Cyperus												Pontedaria cordata											
Diodia virginiana												Potamogeton illinoensis											
Eichhornia crassipes												Ruellia simplex (Mex Petunia)											
Eleocharis (wispy viviparous)												Sacciolepis striata											
Fontinalis sp. (Aquatic Moss)												Sagittaria kurziana											
Fraxinus caroliniana												Sagittaria lancifolia											
Hydrilla verticillata												Sagittaria latifolia											
Hydrocotyle sp.												Salvinia minima											
Hygrophila polysperma												Samolus parviflora											
Hymenachne amplexicaulis												Saururus cernuus											
Hymenocallis												Sparganium americanum											
Lachnanthes caroliniana												Schoenoplectus americanus											
Landoltia punctata												Sphagneticola trilobata(Wedelia)											
Lemna sp.												Typha sp.											
Limnophila sessiflora												Urochloa mutica (Brachiaria)											
Ludwigia leptocarpa												Vallisneria americana											
Ludwigia palustris												Zizania aquatica											
Ludwigia peruviana																							
Ludwigia repens																							
Luziola fluitans																							
If no Dominant or Co-Dominant were selected, indicate with "X"																							
Indicate % cover macrophytes per section																							
0-5% Macrophyte Coverage																							
>5 and ≤10% Macrophyte Coverage																							
>10 and ≤25% Macrophyte Coverage																							
>25 and ≤50% Macrophyte Coverage																							
> 50% Macrophyte Coverage																							


259/m

G2SW0131

Assessment Sketch Sheet

Site Name:

Mizelle Creek in Park

Left
Bank

Length of grid represents 100 m of stream (not linear meters).
(Horizontal scale is double vertical scale, draw proportionately).

Location: Mizelle Crk in ParkDate: 01/06/2021Sampler: B Paswater & S Meyer

100 m: Latitude _____
Longitude _____

0 m: Latitude _____
Longitude _____

Substrates: Code key, draw proportionate habitat abundance. %

Snags _{10m} 2

Roots/undercut banks _{5m} 2

Leaf Packs (or mats) _{2m} 0.5

Aquatic Macrophytes _____

Shell rubble _____

Pools total # observed = _____
range expected = _____

Average width 5 m
Average depth 5 m

Velocity measured at 0 meter mark.

WQ & chemistry taken at 0 meter mark.

Habitat Smothering:
Note areas (on map) where sand or silt is smothering substrates, limiting habitability.

Bank Stability:
Note areas (on map) with unstable, eroding banks.

Riparian Buffer Width:
Note areas (on map) where natural vegetation is altered or eliminated.

Plants observed / other notes:

UCB = Under Cut Bank