



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

STRATEGIC MONITORING PLAN FIELD SHEET

January 2022

Meter Passed End
of Day CCV
Yes / No

WIN Station Name: Inter-Coastal 450m d-stream Pine Log Boat Ramp **Date:** 6/7/2022

WIN/Field ID: G2TLHR0034 **WBID:** 375B **ENR:** - **Latitude:** 29.7669

County: Gulf **Org ID:** 21FLTLHR **Longitude:** -85.0388

Receiving Body of Water: Apalachicola Bay **RQ:** 2022-05-02-73

Sampling Team Members		WQ Measurements	Sample Collection	Documentation	Preservation	Preservation Check
☒	Jonathan Woods	x		x		
☒	Jade Burtchett					
☐						
☐						

Sampling Equipment	
☒ Sample Container	☐ Carboy
☐ Dipper	☐ Van Dorn
☐ Syringe	☐ Pole
Depth measured with: Sonar	
Secchi Equipment ID:	
Collection Method	
☐ Wading	☐ Canoe/Kayak
☐ From Shore	☐ Electric Motor
☐ Other	☒ Gasoline Motor

Water Level: ☒ Normal ☐ Low ☐ High ☐ Dry ☐ Pooled ☐ Flooded						Meter ID# 154177	
Photos: No		Flow:		Tide: RISING		Tide Times: High: 1143 Low: 0433	
Biological Samples Collected:		☒ None	☐ HA	☐ SCI	☐ RPS	☐ Algae ID	☐ LVS ☐ LVI Other:
SBIO ID Numbers:							
Notes:							

Duplicate Sample

Time Zone: EST	Time:	Field ID: N/A	(WIN ID_DUP)
WIN DMT Activity ID:			

Blank

Time Zone:	Time:	Field ID:	(Blank Type_DDMMYYYY)
DI Source:	Location:		
DI Type:	Equipment ID:		
DI Container (Name/ID):		DI Container Type:	

LIMS EVENT ID: WIN Import ID:

Enter Field Parameters, Verify Station ID In LIMS DMT: QC Station ID, Field Parameters In LIMS DMT:

Scan/Save Field Sheets Migrate Data to WIN: Verify Data In WIN:



RQ-2022-05-02-73
Customer: TLH-DIST
Project ID: STRATEGIC MONITORING PLAN

Collected By: Jonathan Woods, Jade Burtchett
Field Report Prepared By: Jonathan Woods
Sampling Agency: FDEP

Place Label Here WIN ID/Field ID: G2TLHR0034 Location: Inter-Coastal 450m d-stream Pine Log Boat Ramp						Comments:				
Matrix: Fresh						(Check one) ☒ GRAB ☐ COMPOSITE				
Date	Time	DO (mg/L)	DO (%SAT)	Temp. (C°)	pH	Sample Depth (m)	Secchi Disk (m)	Total Depth (m)	Sp COND (µmhos/cm)	Salinity (PPTH)
6/7/2022	1115 EST	5.67	72.3	27.9	7.55	0.3	1.1 ☐ VOB (S)	3.6	121.5	0.06
	1118 EST	5.45	68.8	27.8	7.52	3.1	Central Lab please use top row for login purposes		121.6	0.06
Parameter Suite		Parameter Methods				Preservation		pH Check	# Bottles sent to Lab	Bottle Group
Preserved Nutrients (P-500ML)		☒ W-NH3 / W-NO2NO3 / W-TKN / W-TOC / W-S-A-TP				☒ Ice ☒ H2SO4*		☐ <2	1	B
		Lot #	131394		Exp:	11/7/22				
Metals (P-500ML)		☒ W-ICPMS ☒ W-ICP ☒ W-HARD				☒ Ice ☐ HNO3*		☒ <2	1	B
		Lot #	1266110		Exp:	11/16/22				
Filtered Nutrients (P125ML)		☐ W-PO4-F ☐ Field Filtered 0.45 µm Filter				☐ Ice				
		Filter Lot #				Syringe Lot #				
BOD (BP-1L)		☐ OV-BODUNIN				☐ Ice				
Chlorophyll (BP-1L)		☒ CHLSUITE-W				☒ Ice			1	B
Physical/Aggregate (Fresh) (P-1L)		☒ Alkalinity / W-F / W-TSS / TURBIDITY / W-CL-IC / W-COLOR / W-SO4-IC / W-TDS				☒ Ice			1	B1
Physical/Aggregate (Marine) (P-1L)		☐ Alkalinity / W-F / W-TSS / TURBIDITY				☐ Ice				
Macroinvertebrates (PJ-2L)		☐ MI-FW-QLDC				☐ Formalin				
Periphyton (PT-50ML)		☐ ALGAE-ID				☐ Ice				
Microbiology (Contract Lab Bottle)		☐ E Coli ☐ F Coli ☐ Enterococci ☐ Contract Lab				☐ Ice				
Molecular (QPCR-P-500ML)		☐ PCR-HF183 ☐ PCR-BacR ☐ PCR-DG3 ☐ PCR-GULL2 ☐ PCR-GFD ☐				☐ Ice				
Tracers (BG-500ML)		☐ W-E8321-DI ☐ W-E8321-MS				☐ Ice		MCAA Exp.		
Pesticides (BG-500ML) (BG-1L)		W-E8321-DI		WE8321-MS		W-PSNP-TQ		W-CT-CL-R		MCAA Lot#
		W-PCL-TQ-R		W-CARB-AA (5 ml of MCAA** Buffer Solution)		W-TR-SQ-R		☐ Ice		
		W-PCB-TQ-R								
Phytoplankton/Periphyton				DTY-QN-C		PKD-QN-C		☐ Ice		
Name: Jonathan Woods Jade Burtchett				Signature:				Date: 06/07/2022		

*2.0 ml of Preservative used unless noted otherwise.

**MCAA: Monochloroacetic acid buffer solution

DEP Form FD 9000-3 Physical/Chemical Characterization Field Sheet

SAMPLE ID WTR H20034 ORG ID 21FCHLR LATITUDE _____
 COUNTY Gulf STORET # _____ LONGITUDE _____
 DATE 6/7/22 TIME 1115 SAMPLING AGENCY 21FCHLR0034
 SITE NAME Apalachicola River
 FIELD ID/NAME InterCoastal RECEIVING BODY OF WATER Gulf of Mexico

RIPARIAN ZONE / STREAM FEATURES


PREDOMINANT LAND-USE IN WATERSHED (specify relative percent in each category): Forest/Natural <u>40</u> Silviculture <u>50</u> Field/Pasture _____ Agricultural _____ Residential <u>10</u> Commercial _____ Industry _____ Other (Specify) _____							Landscape Development Intensity Index (LDI) _____
Local Watershed Erosion (select one): ☒ None ☐ Slight ☐ Moderate ☐ Heavy Local Watershed NPS Pollution: ☒ No evidence ☐ Slight ☐ Moderate ☐ Heavy				Typical Width (m) Depth (m)/Velocity (m/sec) Transect <u>110</u> m wide <u>0.1</u> m/s <u>0.1</u> m/s <u>0.1</u> m/s <u>1.0</u> m deep <u>3.6</u> m deep <u>2.0</u> m deep			
Width of Riparian Vegetation (m) on Each Buffer Side Left Bank: <u>0-6</u> Right Bank: <u>718</u>		Hydrologic Modification Score (per FT 3101) _____					
High Water Mark: <u>0.3</u> + <u>3.6</u> = <u>3.9</u> (m) (above present water level) (present depth) (above bed)		Artificially Impounded ☐ Yes ☒ No					
Artificially ☒ No ☐ Mostly recovered, more sinuous Channelized: ☐ Some recovery ☐ Recent, severe		Canopy Cover % ☒ Open ☐ Lightly Shaded (11-45%) ☐ Heavily Shaded ☐ Moderate Shaded (46-80%)					

SEDIMENT / SUBSTRATE

Sediment Oils ☒ Absent ☐ Slight ☐ Moderate ☐ Profuse		Sediment Odors ☒ Normal ☐ Sewage ☐ Petroleum ☐ Chemical ☐ Anaerobic ☐ Other (Specify): _____		Smothering of Substrates Sand Smothering: None ☒ Slight ☒ Moderate ☐ Severe ☐ Silt Smothering: None ☐ Slight ☒ Moderate ☐ Severe ☐ Algae Smothering: None ☒ Slight ☐ Moderate ☐ Severe ☐																																																																													
SUBSTRATE TYPE Assessment Tool: ☐ SCI ☒ RPS ☒ LVS ☐ LCI ☐ BioRecon <table border="1"> <thead> <tr> <th></th> <th>% Coverage</th> <th>INVERT # Times Sampled</th> <th>PERI # Times Sampled</th> </tr> </thead> <tbody> <tr> <td>Woody Debris (Snags)</td> <td><u>0.1</u></td> <td></td> <td></td> </tr> <tr> <td>Undercut Banks / Roots</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Leaf Packs or Mat</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Aquatic Vegetation</td> <td><u>1.2</u></td> <td></td> <td></td> </tr> <tr> <td>Rock or Shell Rubble..</td> <td><u>0.27</u></td> <td></td> <td></td> </tr> <tr> <td>Sand.....</td> <td><u>98.43</u></td> <td></td> <td></td> </tr> <tr> <td>Mud / Muck / Silt</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Other</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Other</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>				% Coverage	INVERT # Times Sampled	PERI # Times Sampled	Woody Debris (Snags)	<u>0.1</u>			Undercut Banks / Roots				Leaf Packs or Mat				Aquatic Vegetation	<u>1.2</u>			Rock or Shell Rubble..	<u>0.27</u>			Sand.....	<u>98.43</u>			Mud / Muck / Silt				Other				Other				WATER QUALITY <table border="1"> <thead> <tr> <th></th> <th>Depth (M)</th> <th>Temp. (°C)</th> <th>pH (SU)</th> <th>D.O. (MG/L)</th> <th>D.O. Sat (%)</th> <th>Cond. (UMHO/CM)</th> <th>Salinity (PPT)</th> <th>SECCHI (M)</th> </tr> </thead> <tbody> <tr> <td>Top:</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td><u>1.1</u></td> </tr> <tr> <td>Mid:</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>☐ VOB</td> </tr> <tr> <td>Bottom:</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>TOTAL DEPTH</td> </tr> </tbody> </table> Meter ID: <u>154177</u>				Depth (M)	Temp. (°C)	pH (SU)	D.O. (MG/L)	D.O. Sat (%)	Cond. (UMHO/CM)	Salinity (PPT)	SECCHI (M)	Top:								<u>1.1</u>	Mid:								☐ VOB	Bottom:								TOTAL DEPTH
	% Coverage	INVERT # Times Sampled	PERI # Times Sampled																																																																														
Woody Debris (Snags)	<u>0.1</u>																																																																																
Undercut Banks / Roots																																																																																	
Leaf Packs or Mat																																																																																	
Aquatic Vegetation	<u>1.2</u>																																																																																
Rock or Shell Rubble..	<u>0.27</u>																																																																																
Sand.....	<u>98.43</u>																																																																																
Mud / Muck / Silt																																																																																	
Other																																																																																	
Other																																																																																	
	Depth (M)	Temp. (°C)	pH (SU)	D.O. (MG/L)	D.O. Sat (%)	Cond. (UMHO/CM)	Salinity (PPT)	SECCHI (M)																																																																									
Top:								<u>1.1</u>																																																																									
Mid:								☐ VOB																																																																									
Bottom:								TOTAL DEPTH																																																																									
Water Odors Normal ☒ Petroleum ☐ Sewage ☐ Chemical ☐ Other ☐			Water Surface Oils Normal ☒ Sheen ☐ Globbs ☐ Slick ☐ Other ☐																																																																														
Water Sample Taken? ☒ Yes ☐ No Sample Preserved? ☒ Yes ☐ No Lot Number: <u>131394</u> Exp: <u>11/7/22</u>			Color Tannic ☒ Green (Algae) ☐ Clear ☐ Other (Specify) ☐																																																																														
Algae Sample Taken? ☐ Yes ☐ No Sample Preserved? ☐ Yes ☐ No Lot Number: _____ Exp: _____			Clarity Clear ☐ Slightly Turbid ☒ Turbid ☐ Opaque ☐																																																																														
ABUNDANCE Not Obs. Rare Common Abundant Periphyton: ☐ ☒ ☐ ☐ Fish: ☐ ☐ ☒ ☐ Aquatic Plants: ☐ ☐ ☒ ☐ Iron/Sulfur Bacteria: ☒ ☐ ☐ ☐			System Type: Stream ☐ Lake ☐ Wetland ☐ Estuary ☐ Other (Specify) ☒ <u>River</u>																																																																														
AMBIENT FIELD CONDITIONS / NOTES: ☒ The antecedent hydrologic conditions have been met to my best knowledge.																																																																																	

SAMPLING TEAM Woods / Butchett SIGNATURE: [Signature] DATE: 6/7/22

DEP Form FD 9000-4 Stream/River Habitat Assessment Sketch Sheet



Location: GATLH20034
 Date: 06/07/22
 Sampler: J. Burckhoff

100 m: Latitude _____
 Longitude _____
 0 m: Latitude _____
 Longitude _____

Substrates: Code key, draw proportionate habitat abundance.		%
☒ S	Snags	0.1
☐	Roots/undercut banks	_____
☐	Leaf Packs (or mats)	_____
☒ A	Aquatic Macrophytes	1.2
☒ K	Rock	0.27
☐	other	98.43
☐	Pools	total # observed = _____ # range expected = _____

Average width 110 m
 Average depth 3.6 m

Velocity measured at 50 meter mark.

WQ & chemistry taken at 0 meter mark.

Habitat Smothering:
 Note areas (on map) where sand or silt is smothering substrates, limiting habitability.

Bank Stability:
 Note areas (on map) with unstable, eroding banks.

Riparian Buffer Width:
 Note areas (on map) where natural vegetation is altered or eliminated.

Plants observed / other notes:

11 S
 137 A
 30 K

Length of grid represents 100 m of stream (not linear meters).
 (Horizontal scale is double vertical scale, draw proportionately).

37 A

Delete 17747
17748
Good 17749

DEP Form FD 9000-5 Stream/River Habitat Assessment Field Sheet

SAMPLING AGENCY: <u>ZIFCLUAR</u>		STORET STATION NUMBER: <u>G2TLHR0034</u>	DATE (MM/DD/YY): <u>6/7/22</u>	RECEIVING BODY OF WATER: <u>Gulf of Mexico</u>
REMARKS:	COUNTY: <u>Guilf</u>	LOCATION: <u>Apalachicola River</u>		FIELD ID/NAME:

Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
Primary Habitat Components	Four or more major productive habitats present (snags, tree roots, aquatic vegetation, leaf packs (partially decayed), rock)	Three major productive habitats present. Adequate habitat. Some substrates may be new fall (fresh leaves or snags)	Two major productive habitats present. Less than desirable habitat, frequently disturbed or removed	One or less major productive habitat. Lack of habitat is obvious, substrates unstable or smothered
Substrate Diversity <u>12</u>	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
Substrate Availability <u>2</u>	Greater than 30% major productive habitat present at site 20 19 18 17 16	16% to 30% major productive habitat, by aerial extent 15 14 13 12 11	6% to 15% major productive habitat 10 9 8 7 6	Less than 5% major productive habitat 5 4 3 2 1
Water Velocity <u>10</u>	Max. observed at typical transect: > 0.25 m/sec. But < 1 m/sec ≥0.33 0.31 0.29 0.27 >0.25 20 19 18 17 16	Max. observed at typical transect: >0.1 to 0.25 m/sec 0.25 0.21 0.17 0.13 >0.1 15 14 13 12 11	Max. observed at typical transect: 0.05 to 0.1 m/sec 0.1 0.09 0.07 0.06 0.05 10 9 8 7 6	Max. observed at typical transect: <0.05 m/sec; or spate occurring: > 1 m/sec <0.05 0.04 0.03 0.01 <0.01 5 4 3 2 1
Habitat Smothering <u>14</u> ----- Primary Score <u>36</u>	Adequate number of stable pools (1-2 per 12 times width) and <25% of habitats affected by sand, silt, or algae. 20 19 18 17 16	Adequate number of stable pools (1-2 per 12 times width) and >25% of habitats affected by sand, silt, or algae. 15 14 13 12 11	Does not have required number of stable pools (1-2 per 12 x width) and/or has shallow pools (<2 x prevailing depth). 10 9 8 7 6	Stable pools are absent. Most habitats affected by sand, silt, or algae accumulation. 5 4 3 2 1
Secondary Habitat Components <u>15</u> Artificial Channelization <u>20</u> <u>2W</u>	Expected sinuosity given the stream width. No evidence of dredging or artificial straightening. No spoil banks. 20 19 18 17 16	Good sinuosity within old channelized area. Evidence of dredging in the past (>25 yrs) but mostly recovered. 15 14 13 12 11	Straightened with trapezoidal cross section, but has a small degree of sinuosity developed within channelized area. 10 9 8 7 6	Straightened or engineered by dredging, has trapezoidal or box cut cross section, lacks required pools. May have spoil banks. 5 4 3 2 1
Bank Stability Right Bank <u>10</u> Left Bank <u>4</u>	Bankfull > 60% of bank height. Slope of bank ≤ 60° from bankfull to top of bank. Bankfull is within or above the root zone with few raw, eroded areas. 10 9	Only meets 2 of the 3 requirements for optimal bank stability. 8 7 6	Only meets 1 of the 3 requirements for optimal bank stability. 5 4	Bankfull < 60% of bank height. Slope of bank > 60°. Bankfull is below the root zone with raw, eroded areas. 3 2 1
Riparian Buffer Zone Width Right Bank <u>10</u> Left Bank <u>3</u>	Width of vegetation greater than 18 m 10 9	Width of vegetation >12 to 18m 8 7 6	Width of vegetation 6 to 12 m. human activities close to system 5 4	Less than 6 m of buffer zone due to intensive human activities 3 2 1
Riparian Zone Vegetation Quality Right Bank <u>9</u> Left Bank <u>3</u> ----- Secondary Score <u>58</u>	Over 80% of riparian surfaces consist of normal, expected plant community for given sunlight & habitat conditions (e.g., native plants; tree, shrub, and forbs represented, if appropriate). Minimal disturbance. 10 9	>50% to 80% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Some disruption in community observed. 8 7 6	25% to 50% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). Disruption obvious. 5 4	Less than 25% of riparian zone is undisturbed (normal, expected plant community for given sunlight & habitat conditions). 3 2 1

96

TOTAL SCORE

Date: <u>6/7/22</u>	Analyst: <u>Don Woods</u>	Signature: <u>[Signature]</u>
---------------------	---------------------------	-------------------------------

9952

DEP FORM FD 9000-25 Rapid Periphyton Survey Field Sheet

Site: 02TUH20034 County: Gulf Date: 6/7/22 Investigators: Woods / Burckett

Transect (m) Point 1=right 9=left Algal Thickness Rank (N-6, X) Estimated Canopy Cover

Transect (m)	Point	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	Transect (m)	Point	Algal Thickness Rank (N-6, X)	Estimated	Canopy Cover	
0	1	N	X		60	1	N	Y		
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
10	1				70	1				
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
20	1				80	1				
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
30	1				90	1				
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
40	1				100	1				
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				
50	1					1				
	2					2				
	3					3				
	4					4				
	5					5				
	6					6				
	7					7				
	8					8				
	9					9				

Record "N" and check "Estimated" for points deeper than the Secchi depth; algae are presumed absent. Check "Estimated" if thickness estimated for deep points which can be seen but not reached.

Record "X" for points shallower than Secchi depth for which substrate cannot be seen or reached with the hand. No estimated rank.

Record canopy cover as the number of small densiometer quadrants (out of 96) that HAVE canopy cover. Measure facing upstream at point 4, 5, or 6.

Collect algal mat sample following DEP SOP FS 7240 if the percentage of total sampled points with a thickness rank of 4, 5, or 6 is >20%.

STORET Station Number:

Secchi depth 1.1
Estimated? N

points ranked 4-6
total points assessed
% points ranked 4-6

Check accompanying data collected at same site/date.

Algal mat sample

Linear Veg Survey ✓

Habitat Assessment ✓

SCI/Biorecon

Water sample ✓

RQ- 2022-05-02-73

Algal Thickness Rank	
N	rough, no algae, slimy, algae up to 1mm
3	>1mm - 6mm
4	>6mm - 20mm
5	>20mm - 10 cm
6	>10 cm

12221

Storet Number: G2TC4R0534

Signature:

Signature: J. H. Wood

[illegible]