

NWFD- 5126

NORTHWEST FLORIDA WATER MANAGEMENT DISTRICT

Dairy Farm, Orenda cows

FILE NO. WS-18

WELL NUMBER BASIN 12A LAT. 30° 48' 56" LONG. 85° 30' 42" COUNTY Wash. DATE 8/22/79 PERMIT NO. B.O.G. NO. W-

LOCATION T 5N R 13W SEC 23 SW 1/4 of SE 1/4 of SW 1/4 MAP OR QUAD CHIPLEY, FLA. 7' 15'

OWNER Martin Vanderweert ADDRESS

WELL DEPTH 144 ft. CASING 74 ft. OPEN HOLE 70 ft. WELL FINISHED: SCREENED 1/2 SCREEN INTERVAL 1/2 OPEN HOLE 1/2
START OF LOG LSD ± 0 ft. TOP OF CASING TO LSD 5' DEPTH LOGGED TOP 0 ft. BOTTOM 144 ft. TOTAL FT. LOGGED 576'CONDITION ~~2~~ Pumps sand DATE DRILLED Feb 78 GROUTED 1/2 DATE ? CAPPED 1/2 TYPE OF CASING Steel

FLOWING 1/2 GPM 1/2 HEAD - IN. TOP OF LS LSD MSL ELEVATION OF LSD TO MSL 105' SIZE 6"

FORMATION FORMATION TOP REFERENCE TO LSD ft. MSL ft.

AQUIFER Floridan WATER LEVEL REFERENCE TO LSD -33 ft. MSL 72 ft. ARTESIAN HEAD 11/4 ft.

TYPE OF LOG	INTERVAL TO	VERT. SCALE	HORZ. SCALE	DIRECTION LOGGED	SPEED FT./MIN.	REMARKS
Gamma w/ccl TC=	5 94	1"=20ft.	0-100PS	UP	25/min	
Caliper-Arms=32"	52 144	1"=20'	6"-36"	UP	25/min	
Temp w/ccl	4 96	1"=20'		down	25/min	
Fluid Resistivity						
Electric -16,64 Rp						
Flow Meter						
Sampler - Depth(s)						
Neutron						

LOCATION:

R 13W

T 5N

23

Chipley

Dairy Farm

273

Pump Test info - Pumped @ 11/2 gpm static pumping level dd specific capacity T = S =
USE OF WELL Anode Drainage Observation Oil-Gas Recharge Test Abandoned Withdrawal Waste Irrigation Public Supply

QUALITY WATER SAMPLE Yes No Date 11/1 Depth(s) pH Salinity Conductivity Temp. Chloride

DRILLER John Brown TYPE OF RIG ? PUMP INTAKE DEPTH ? TYPE OF PUMP Sub hp ? DRILLER SAMPLES 1/2

Start of Logging 10:00 Finished logging 11:00 Total Time 1 hr. Operator/observer Kunden 1 Frank

Well Accessibility good

Lithological Summary

REMARKS: Located on Vanderweert Dairy Farm 2.2 miles north of Chipley city limits on 273

THIS LOG FOR HYDROGEOLOGICAL DATA ONLY - NOT

CONTRACTUAL SATISFACTION

NWFWMD Form No. 42

