


R-52-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-52-T
EST DATE: FEB1980
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-53 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-53
EST DATE: JUL1996
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-54 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-54
EST DATE: JUL1996
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-55 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-55
 EST DATE: JUL1996
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-56 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-56
 EST DATE: JUL1996
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-57 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-57
 EST DATE: JUL1996
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-58 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-58
 EST DATE: JUL1996
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-59 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-59
 EST DATE: JUL1996
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-60 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-60
EST DATE: JUL1996
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-61-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-61-T
EST DATE: FEB1980
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-62 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-62
EST DATE: JUL1996
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-63 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-63
 EST DATE: JUL1996
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-64 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-64
 EST DATE: JUL1996
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-65 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-65
EST DATE: JUL1996
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-66 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-66
EST DATE: JUL1996
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-67 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-67
 EST DATE: JUL1996
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-68 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-68
EST DATE: JUL1996
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-69-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-69-T
EST DATE: FEB1980
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-70-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-70-T
EST DATE: FEB1980
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-71-T PROFILES




- 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-71-T
EST DATE: JUL1996
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-72-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-72-T
EST DATE: FEB1980
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-73 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-73
 EST DATE: JUL1996
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-74 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-74
EST DATE: JUL1996
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-75 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-75
EST DATE: MAY1973
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-76 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-76
EST DATE: NOV1987
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-77 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-77
 EST DATE: NOV1987
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-78-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-78-T
EST DATE: FEB1980
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-79-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-79-T
EST DATE: NOV1987
SURVEY DATE: 16MAY19
AZIMUTH: 150.0

R-80 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-80
 EST DATE: MAY1973
 SURVEY DATE: 16MAY19
 AZIMUTH: 150.0

R-81 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-81
EST DATE: MAY1973
SURVEY DATE: 17MAY19
AZIMUTH: 150.0

R-82-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-82-T
 EST DATE: FEB1980
 SURVEY DATE: 17MAY19
 AZIMUTH: 150.0

R-83-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-83-T
 EST DATE: FEB1980
 SURVEY DATE: 17MAY19
 AZIMUTH: 150.0

R-84 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-84
EST DATE: MAY1973
SURVEY DATE: 17MAY19
AZIMUTH: 150.0

R-85 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-85
EST DATE: JUL1996
SURVEY DATE: 17MAY19
AZIMUTH: 150.0

R-86 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-86
 EST DATE: MAY1973
 SURVEY DATE: 17MAY19
 AZIMUTH: 150.0

R-87 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-87
EST DATE: JUL1996
SURVEY DATE: 17MAY19
AZIMUTH: 160.0

R-88 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-88
EST DATE: MAY1973
SURVEY DATE: 17MAY19
AZIMUTH: 160.0

R-89-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-89-T
EST DATE: FEB1980
SURVEY DATE: 17MAY19
AZIMUTH: 160.0

R-90 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-90
EST DATE: JUL1996
SURVEY DATE: 17MAY19
AZIMUTH: 160.0

R-91 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-91
EST DATE: NOV1987
SURVEY DATE: 17MAY19
AZIMUTH: 160.0

R-92 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-92
EST DATE: MAY1973
SURVEY DATE: 17MAY19
AZIMUTH: 160.0

R-93 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-93
 EST DATE: MAY1973
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-94-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-94-T
 EST DATE: FEB1980
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-95 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-95
EST DATE: MAY1973
SURVEY DATE: 17MAY19
AZIMUTH: 160.0

R-96 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-96
EST DATE: JUL1996
SURVEY DATE: 17MAY19
AZIMUTH: 160.0

R-97-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-97-T
 EST DATE: FEB1980
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-98-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-98-T
 EST DATE: FEB1980
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-99 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-99
EST DATE: JUL1996
SURVEY DATE: 17MAY19
AZIMUTH: 160.0

R-100 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-100
 EST DATE: JUL1996
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-101 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-101
 EST DATE: JUL1996
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-102 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-102
 EST DATE: JUL1996
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-103 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-103
 EST DATE: JUL1996
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-104 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-104
 EST DATE: JUL1996
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-105 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (0.7 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-105
 EST DATE: JAN1988
 SURVEY DATE: 17MAY19
 AZIMUTH: 160.0

R-194A PROFILES




- 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-194A
 EST DATE: APR1983
 SURVEY DATE: 28MAY19
 AZIMUTH: 205.0

R-195A PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-195A
EST DATE: APR1983
SURVEY DATE: 28MAY19
AZIMUTH: 205.0

R-196 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-196
EST DATE: JUL1996
SURVEY DATE: 28MAY19
AZIMUTH: 190.0

R-197 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-197
EST DATE: JUL1996
SURVEY DATE: 28MAY19
AZIMUTH: 190.0

R-198 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-198
EST DATE: JUL1996
SURVEY DATE: 28MAY19
AZIMUTH: 185.0

R-199 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-199
EST DATE: JUL1996
SURVEY DATE: 28MAY19
AZIMUTH: 185.0

R-200 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-200
 EST DATE: JUL1996
 SURVEY DATE: 28MAY19
 AZIMUTH: 190.0

R-201 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-201
EST DATE: JUL1996
SURVEY DATE: 28MAY19
AZIMUTH: 190.0

R-202 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-202
EST DATE: JUL1996
SURVEY DATE: 28MAY19
AZIMUTH: 200.0

R-203 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-203
 EST DATE: MMM1974
 SURVEY DATE: 28MAY19
 AZIMUTH: 200.0

R-204 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-204
 EST DATE: JUL1996
 SURVEY DATE: 28MAY19
 AZIMUTH: 200.0

R-205 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-205
 EST DATE: MMM1974
 SURVEY DATE: 28MAY19
 AZIMUTH: 200.0

R-206 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-206
EST DATE: MMM1974
SURVEY DATE: 28MAY19
AZIMUTH: 200.0

R-207 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-207
EST DATE: MMM1974
SURVEY DATE: 28MAY19
AZIMUTH: 200.0

R-208 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-208
 EST DATE: MMM1974
 SURVEY DATE: 28MAY19
 AZIMUTH: 205.0

R-209 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-209
EST DATE: MMM1974
SURVEY DATE: 28MAY19
AZIMUTH: 205.0

R-210 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-210
 EST DATE: MMM1974
 SURVEY DATE: 28MAY19
 AZIMUTH: 205.0

R-211 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-211
 EST DATE: MMM1974
 SURVEY DATE: 28MAY19
 AZIMUTH: 190.0

R-212 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-212
EST DATE: JUL1996
SURVEY DATE: 28MAY19
AZIMUTH: 170.0

R-213 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-213
 EST DATE: MMM1974
 SURVEY DATE: 28MAY19
 AZIMUTH: 170.0

R-214 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION


RANGE: R-214
EST DATE: MMM1974
SURVEY DATE: 28MAY19
AZIMUTH: 165.0

R-215 PROFILES



2019-MAY CONDITION BY DEP 2018-OCT MONITORING BY USACE-LIDAR 2017-FEB MONITORING BY DEP MHW CONTOUR (1.1 FT)	FRANKLIN PROGRAM SUPPORT GIS DIVISION OF WATER RESOURCE MANAGEMENT FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION	RANGE: R-215 EST DATE: MMM1974 SURVEY DATE: 28MAY19 AZIMUTH: 170.0
--	---	--

R-216 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-216
EST DATE: MMM1974
SURVEY DATE: 28MAY19
AZIMUTH: 170.0

R-217 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-217
 EST DATE: MMM1974
 SURVEY DATE: 28MAY19
 AZIMUTH: 170.0

R-218-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-218-T
EST DATE: FEB1980
SURVEY DATE: 28MAY19
AZIMUTH: 170.0

R-219 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-219
 EST DATE: JUL1996
 SURVEY DATE: 28MAY19
 AZIMUTH: 180.0

R-220 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-220
 EST DATE: JUL1996
 SURVEY DATE: 28MAY19
 AZIMUTH: 165.0

R-221 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-221
 EST DATE: MMM1974
 SURVEY DATE: 29MAY19
 AZIMUTH: 145.0

R-222 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-222
EST DATE: JUL1996
SURVEY DATE: 29MAY19
AZIMUTH: 130.0

R-223 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-223
EST DATE: JUL1996
SURVEY DATE: 29MAY19
AZIMUTH: 125.0

R-224-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-224-T
EST DATE: FEB1980
SURVEY DATE: 29MAY19
AZIMUTH: 120.0

R-225 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-225
EST DATE: JUL1996
SURVEY DATE: 29MAY19
AZIMUTH: 115.0

R-226-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-226-T
EST DATE: FEB1980
SURVEY DATE: 29MAY19
AZIMUTH: 115.0

R-227 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-227
 EST DATE: JUL1996
 SURVEY DATE: 29MAY19
 AZIMUTH: 115.0

R-228 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-228
EST DATE: JUL1996
SURVEY DATE: 29MAY19
AZIMUTH: 105.0

R-229-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-229-T
 EST DATE: MAR1976
 SURVEY DATE: 29MAY19
 AZIMUTH: 105.0

R-230 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-230
EST DATE: MMM1974
SURVEY DATE: 29MAY19
AZIMUTH: 95.0

R-231 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-231
 EST DATE: MMM1974
 SURVEY DATE: 29MAY19
 AZIMUTH: 90.0

R-232 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-232
EST DATE: MMM1974
SURVEY DATE: 29MAY19
AZIMUTH: 85.0

R-233 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-233
EST DATE: MMM1974
SURVEY DATE: 29MAY19
AZIMUTH: 80.0

R-234 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-234
 EST DATE: MMM1974
 SURVEY DATE: 29MAY19
 AZIMUTH: 80.0

R-235-T PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-235-T
EST DATE: OCT1982
SURVEY DATE: 29MAY19
AZIMUTH: 80.0

R-236 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-236
 EST DATE: MMM1974
 SURVEY DATE: 29MAY19
 AZIMUTH: 80.0

R-237 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-237
EST DATE: MMM1974
SURVEY DATE: 29MAY19
AZIMUTH: 70.0

R-238 PROFILES




- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-238
 EST DATE: JUL1996
 SURVEY DATE: 29MAY19
 AZIMUTH: 45.0

R-239-T PROFILES



- ▲ 2019-MAY CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2017-FEB MONITORING BY DEP
- - - MHW CONTOUR (1.1 FT)

FRANKLIN
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-239-T
 EST DATE: FEB1980
 SURVEY DATE: 29MAY19
 AZIMUTH: 30.0