


R-1 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-1
EST DATE: NOV1980
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-2 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-2
EST DATE: OCT1994
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-3 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-3
EST DATE: OCT1994
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-3A PROFILES




▲ 2018-OCT MONITORING BY USACE-LIDAR
 ● 2013-SEP MONITORING BY USACE
 ● 2007-FEB MONITORING BY MAE
 - - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-3A
 EST DATE: OCT1994
 SURVEY DATE: 27OCT18
 AZIMUTH: 190.0

R-4 PROFILES




- 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- 2007-FEB MONITORING BY MAE
- MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-4
EST DATE: OCT1995
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-5 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-5
EST DATE: NOV1980
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-6 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-6
 EST DATE: NOV1980
 SURVEY DATE: 04APR19
 AZIMUTH: 190.0

R-6A PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-6A
EST DATE: OCT1994
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-7 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-7
EST DATE: OCT1994
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-8 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-8
EST DATE: M&E1997
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-9 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-9
 EST DATE: M&E1997
 SURVEY DATE: 04APR19
 AZIMUTH: 190.0

R-10 PROFILES




- 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- 2007-FEB MONITORING BY MAE
- MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-10
EST DATE: M&E1997
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-11 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-11
 EST DATE: JUN1973
 SURVEY DATE: 04APR19
 AZIMUTH: 190.0

R-12 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-12
EST DATE: OCT1995
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-13 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-13
EST DATE: M&E1997
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-14 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-14
EST DATE: OCT1995
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-15 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-15
EST DATE: OCT1994
SURVEY DATE: 04APR19
AZIMUTH: 190.0

R-16 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-16
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-17 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-17
 EST DATE: NOV1980
 SURVEY DATE: 16APR19
 AZIMUTH: 190.0

R-18 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-18
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-19 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-19
EST DATE: JUN1973
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-20 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-20
EST DATE: OCT1994
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-21 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-21
EST DATE: JUN1973
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-22 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-22
 EST DATE: NOV1980
 SURVEY DATE: 16APR19
 AZIMUTH: 190.0

R-23 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-23
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-24 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-24
EST DATE: M&E1997
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-25 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-25
EST DATE: NOV1980
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-26 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-26
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-27 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-27
EST DATE: M&E1997
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-28 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-28
 EST DATE: OCT1994
 SURVEY DATE: 16APR19
 AZIMUTH: 190.0

R-29 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-29
 EST DATE: OCT1995
 SURVEY DATE: 16APR19
 AZIMUTH: 190.0

R-30 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-30
 EST DATE: OCT1995
 SURVEY DATE: 16APR19
 AZIMUTH: 190.0

R-31 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-31
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-32 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-32
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-33 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-33
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-34 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-34
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-35 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-35
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-36 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-36
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-37 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-37
 EST DATE: OCT1995
 SURVEY DATE: 16APR19
 AZIMUTH: 190.0

R-38 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-38
 EST DATE: OCT1995
 SURVEY DATE: 16APR19
 AZIMUTH: 190.0

R-39 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-39
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-40 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-40
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 190.0

R-41 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-41
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 195.0

R-42 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-42
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 195.0

R-43 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-43
 EST DATE: OCT1995
 SURVEY DATE: 16APR19
 AZIMUTH: 195.0

R-44 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-44
EST DATE: OCT1995
SURVEY DATE: 16APR19
AZIMUTH: 195.0

R-45 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-45
 EST DATE: OCT1995
 SURVEY DATE: 16APR19
 AZIMUTH: 195.0

R-46 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-46
EST DATE: NOV1980
SURVEY DATE: 16APR19
AZIMUTH: 195.0

R-47 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-47
EST DATE: NOV1980
SURVEY DATE: 17APR19
AZIMUTH: 195.0

R-48 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-48
 EST DATE: OCT1995
 SURVEY DATE: 17APR19
 AZIMUTH: 195.0

R-49 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-49
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 195.0

R-50 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.8 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-50
EST DATE: JUN1973
SURVEY DATE: 17APR19
AZIMUTH: 195.0

R-51 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-51
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-52 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-52
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-53 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-53
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-54 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-54
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-55 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-55
EST DATE: NOV1980
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-56 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-56
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-57 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-57
EST DATE: JUN1973
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-58 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-58
EST DATE: M&E1997
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-59 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-59
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-60 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-60
EST DATE: JUN1973
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-61 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-61
 EST DATE: OCT1995
 SURVEY DATE: 17APR19
 AZIMUTH: 200.0

R-62 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-62
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-63 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-63
EST DATE: JUN1973
SURVEY DATE: 17APR19
AZIMUTH: 195.0

R-64 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-64
EST DATE: NOV1980
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-65 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-65
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-66 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-66
EST DATE: JUN1973
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-67 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-67
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-68 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-68
EST DATE: OCT1994
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-69 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-69
 EST DATE: OCT1995
 SURVEY DATE: 17APR19
 AZIMUTH: 200.0

R-70 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-70
 EST DATE: OCT1995
 SURVEY DATE: 17APR19
 AZIMUTH: 200.0

R-71 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-71
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-72 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-72
EST DATE: AUG1976
SURVEY DATE: 17APR19
AZIMUTH: 200.0

R-73 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-73
EST DATE: M&E1997
SURVEY DATE: 17APR19
AZIMUTH: 190.0

R-74 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-74
EST DATE: M&E1997
SURVEY DATE: 17APR19
AZIMUTH: 190.0

R-75 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-75
EST DATE: OCT1995
SURVEY DATE: 17APR19
AZIMUTH: 190.0

R-76 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-76
EST DATE: NOV1980
SURVEY DATE: 17APR19
AZIMUTH: 205.0

R-77 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-77
EST DATE: M&E1997
SURVEY DATE: 17APR19
AZIMUTH: 205.0

R-78 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-78
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-79 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-79
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-80 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-80
EST DATE: OCT1994
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-81 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-81
EST DATE: M&E1997
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-82 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-82
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-83 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-83
EST DATE: NOV1980
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-84 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-84
EST DATE: JUN1973
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-85 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-85
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-86 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-86
EST DATE: JUN1973
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-87 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-87
 EST DATE: JUN1973
 SURVEY DATE: 18APR19
 AZIMUTH: 202.0

R-88 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-88
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-89 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-89
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-90 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-90
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-91 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-91
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-92 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-92
EST DATE: NOV1980
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-93 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-93
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-94 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-94
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-95 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-95
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-96 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-96
EST DATE: M&E1997
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-97 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-97
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-98 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-98
 EST DATE: NOV1980
 SURVEY DATE: 18APR19
 AZIMUTH: 202.0

R-99 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-99
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-100 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-100
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-101 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-101
EST DATE: OCT1995
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-102 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-102
EST DATE: JUN1973
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-103 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-103
EST DATE: JUN1973
SURVEY DATE: 18APR19
AZIMUTH: 202.0

R-103A PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-103A
 EST DATE: NOV1980
 SURVEY DATE: 18APR19
 AZIMUTH: 202.0

R-104 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-104
EST DATE: OCT1995
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-105 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-105
EST DATE: M&E1997
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-106 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-106
EST DATE: NOV1980
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-107 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-107
EST DATE: OCT1994
SURVEY DATE: 19APR19
AZIMUTH: 202.0

W-108 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: W-108
EST DATE: AUG1976
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-109 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-109
EST DATE: JUN1973
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-110 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-110
EST DATE: NOV1980
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-111 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-111
EST DATE: OCT1994
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-112 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-112
 EST DATE: JUN1973
 SURVEY DATE: 19APR19
 AZIMUTH: 202.0

R-113 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-113
EST DATE: NOV1980
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-114 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-114
EST DATE: NOV1980
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-115 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-115
EST DATE: OCT1995
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-116 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-116
 EST DATE: NOV1980
 SURVEY DATE: 19APR19
 AZIMUTH: 202.0

R-117 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-117
EST DATE: NOV1980
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-118 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-118
EST DATE: OCT1994
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-119 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-119
EST DATE: M&E1997
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-120 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-120
 EST DATE: OCT1995
 SURVEY DATE: 19APR19
 AZIMUTH: 202.0

R-121 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-121
EST DATE: OCT1995
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-122 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-122
EST DATE: OCT1995
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-123 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-123
EST DATE: OCT1995
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-124 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-124
EST DATE: NOV1980
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-125 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-125
EST DATE: OCT1995
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-126 PROFILES




- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-126
EST DATE: AUG1976
SURVEY DATE: 19APR19
AZIMUTH: 202.0

R-127 PROFILES



- ▲ 2019-APR CONDITION BY DEP
- 2018-OCT MONITORING BY USACE-LIDAR
- 2013-SEP MONITORING BY USACE
- ◆ 2007-FEB MONITORING BY MAE
- - - MHW CONTOUR (0.7 FT)

WALTON
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-127
 EST DATE: NOV1980
 SURVEY DATE: 19APR19
 AZIMUTH: 202.0