



Florida Department of Environmental Protection

WINDSHIELD SURVEY REPORT

Required Signatures: **Adobe Signature**

Hurricane Name:		Survey Date:					Survey Tide Stage (if known):									
County Surveyed (include City, Town, Inlet, etc., if applicable)	From Reference Monument #	To Reference Monument #	Beach/Dune Conditions:					Type of Structural Damage:								
			No Damage	Condition 1	Condition 2	Condition 3	Condition 4	Under Structure	Foundation	Super Structure /Roofs	Armoring	Dune Walkover /Decks	Public Infrastructure	Other		
Gulf County																
St. Joe Beach	R-007		X													
White Sands Drive	R-83		X													
Seashore Drive to Aruba Drive	R-97				X											
Stump Hole	R-104					X										
Money Bayou	R-140				X											
Summary of General County-Wide Conditions (i.e., shoreline and dune bluff erosion, overwash, storm surge and flooding, profile lowering, etc.):																
Site-Specific Conditions (i.e., unauthorized construction/activity, beach debris, vegetation impact, sea turtle nest impact, etc.):																
Inspector's Signature: <u>Keith Davie</u> Date: <u>5/23/2017</u> Please attach photographs (including location and brief description)																



East to west view near R- 140



West to East view near R- 140



South to North view near R- 140



South to North view near R- 104



North to South view near R- 104



North to south view near R- 97



South to North view near R- 97



North to south view near R- 83



South to North view near R- 83



East to west view near R- 007



West to East view near R- 007