


WINDSHIELD SURVEY REPORT

Required Signatures: Adobe Signature

[illegible]



Typical condition from R-01 to R-05. No dry beach and no dune or vegetation.



At R-05 beach contour is about 1.5' below the cap.



Typical condition for R-12 to 15 is condition I. This is at Wilhelm.



The beach at Stump Pass State Park has accretion, looking south.



Looking south across Stump Pass to Knight Island.



Knight Island side of Stump Pass dredging operation ongoing. Looking southwest.



Typical Condition I around R-33. Looking north.



Typical Condition I at R-39. Colony on Don Pedro Island looking north.