

R-46 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-46
 EST DATE: JUN1989
 SURVEY DATE: 29NOV18
 AZIMUTH: 75.0

R-47 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-47
EST DATE: MAR1974
SURVEY DATE: 29NOV18
AZIMUTH: 80.0

R-48 PROFILES



- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-48
EST DATE: JUN1989
SURVEY DATE: 29NOV18
AZIMUTH: 75.0

R-49 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-49
 EST DATE: JUN1989
 SURVEY DATE: 29NOV18
 AZIMUTH: 75.0

R-50 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-50
 EST DATE: FEB1975
 SURVEY DATE: 29NOV18
 AZIMUTH: 75.0

R-51 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-51
EST DATE: MAR1974
SURVEY DATE: 29NOV18
AZIMUTH: 75.0

R-52 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-52
EST DATE: MAR1974
SURVEY DATE: 29NOV18
AZIMUTH: 70.0

R-53 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-53
 EST DATE: MAR1974
 SURVEY DATE: 29NOV18
 AZIMUTH: 75.0

R-54 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-54
EST DATE: MAR1974
SURVEY DATE: 29NOV18
AZIMUTH: 75.0

R-55 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-55
EST DATE: JUN1989
SURVEY DATE: 29NOV18
AZIMUTH: 75.0

R-56 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-56
EST DATE: MAR1974
SURVEY DATE: 29NOV18
AZIMUTH: 75.0

T-57 PROFILES




- 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: T-57
 EST DATE: OCT1977
 SURVEY DATE: 29NOV18
 AZIMUTH: 75.0

R-58 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
 PROGRAM SUPPORT GIS
 DIVISION OF WATER RESOURCE MANAGEMENT
 FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-58
 EST DATE: JUN1989
 SURVEY DATE: 29NOV18
 AZIMUTH: 75.0

R-59 PROFILES




- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-59
EST DATE: MAR1974
SURVEY DATE: 29NOV18
AZIMUTH: 70.0

R-60 PROFILES



- ▲ 2018-NOV CONDITION BY DEP
- 2018-JUN MONITORING BY NGS-LIDAR
- 2016-MAY MONITORING BY DEP
- ◆ 2010-OCT MONITORING BY SDI
- - - MHW CONTOUR (0.5 FT)

PALM BEACH
PROGRAM SUPPORT GIS
DIVISION OF WATER RESOURCE MANAGEMENT
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

RANGE: R-60
EST DATE: M&E2000
SURVEY DATE: 29NOV18
AZIMUTH: 70.0