



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 1 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS			
-157.7	200.0		>10	200.1, 200.3, 200.7, 201.7' - Mechanical break (4), 0-30 deg, rough, undulating		Limestone 200.0-201.9' - yellowish gray, (5Y 7/2), fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), sand to gravel-sized broken fragments, infill in section, trace voids (<1/16") over surface	Boring AD-2 blind drilled to approximately 200 feet below ground surface before beginning sampling/logging. Start Drilling at 08:45 09/08/07, Water level 3.0' below ground surface Logger is J. Burkard R1: 7 minutes
			>10	200.9-201.6' - Fracture zone, angular fragments up to 2" in diameter		201.9-202.5' - yellowish gray, (5Y 7/2), fine to medium grained, moderate to strong HCl reaction, very weak (R1)	
			>10	202.1-202.5' - Mechanical break		No Recovery 202.5-204.0'	
			NR			Limestone 204.0-204.7' - very pale orange, (10Y 8/2), fine to medium grained, moderate to strong HCl reaction, very weak (R1), voids <1/16" over 15-30% of surface	
205			>10	204.0-204.7' - Fracture zone, broken fragments		204.7-205.6' - yellowish gray, (5Y 7/2), fine to medium grained, mild to moderate HCl reaction, very weak to weak (R1 to R2), trace voids less than 1/16" of surface	R2: 9 minutes
-162.7			3	204.9, 205.4, 205.7, 206.0, 206.8, 207.2, 207.6' - Mechanical break (7), 0-20 deg, rough, undulating		Silty Sand (SM) 205.6-206.4' - silty sand sized particles with broken limestone fragments up to 1/2" in diameter	
			>10	207.2-207.8' - Fracture, vertical, rough, undulating, split core in two halves		Limestone 206.4-207.8' - pale greenish yellow, (10Y 8/2), very fine to fine grained, moderate to strong HCl reaction, weak to medium strong (R2 to R3), laminar bedding planes <1/16"	
			NR	207.5' - Mechanical break 207.8-208.0' - Mechanical break		207.8-208.0' - yellowish gray, (5Y 7/2), strong HCl reaction, very weak to extremely weak (R1 to R0)	
210			>10	209.3-210.3' - Fracture zone, angular fragments up to 2" in diameter		No Recovery 208.0-209.0'	R3: 11 minutes
-167.7			>10	210.4-210.8' - Mechanical break		Limestone 209.0-209.7' - yellowish gray, (5Y 7/2), fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), voids (<1/16") over 10-20% of surface	
			NR			209.7-210.3' - pale greenish yellow, (10Y 8/2), very fine to fine grained, strong HCl reaction, very weak (R1), <1/16" horizontal bedding planes	
			NR			210.3-210.8' - very pale orange, (10Y 8/2), fine grained, strong HCl reaction, very weak (R1), silt infill	
215			8	214.0-214.4' - Fracture zone, rough, undulating, broken fragments up to 2" in diameter		No Recovery 210.8-214.0'	SC-1 collected at 217.8-218.9' R4: 9 minutes
-172.7			5	214.6, 214.7, 214.9, 215.2, 216.6, 216.8, 217.0, 217.4, 217.7, 218.8' - Mechanical break (10), 0-30 deg, rough to smooth, undulating, minor black organic staining		Limestone 214.0-219.0' - yellowish gray to pale greenish yellow, (5Y 7/2 to 10Y 8/2), fine to medium grained, moderate to strong HCl reaction, very weak to weak (R1 to R2), fossil casts and molds, voids (<1/16") throughout from 214.0-214.4' and 215.0-216.5'	
			>10	215.7-216.4' - Fracture zone, rough, undulating, rock fragments up to 3" in diameter			
			3	217.5-217.7' - Mechanical break			
			1				
219.0			4				
220							



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 2 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS		ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.
-177.7	R5-HQ 5 ft 82%	22	4	219.3, 219.4, 219.9, 220.0, 200.2, 200.4, 200.5, 200.9, 221.3, 222.5, 222.8, 223.0' - Mechanical break (12), 0-15 deg, rough, undulating		Silty Limestone Fragments 219.0-219.3' - yellowish gray, (5Y 7/2), mild HCl reaction, with broken limestone fragments up to 1/8" in diameter Limestone 219.3-220.0' - yellowish gray, (5Y 7/2), fine grained, mild to moderate HCl reaction, weak to medium strong (R2 to R3), laminar bedding planes 220.0-223.1' - pale greenish yellow, (10Y 8/2), moderate to strong HCl reaction, weak (R2), fossil molds and casts, surface cavities (trace amounts) up to 1/4" wide and 1/4" in height, pitting on surface No Recovery 223.1-224.0' Limestone 224.0-228.9' - pale greenish yellow, (10Y 8/2), very fine to fine grained, moderate to strong HCl reaction, very weak to weak (R1 to R2), wavy bedding plane up to 1/16" in thickness throughout section - some black organic material, surface pitting is present throughout the section No Recovery 228.9-229.0' Limestone 229.0-233.0' - yellowish gray, (5Y 7/2), fine to medium grained, moderate HCl reaction, very weak to weak (R1 to R2), surface pitting throughout sample, 1/16" voids on surface throughout section, fossil casts No Recovery 233.0-234.0' Limestone 234.0-236.7' - yellowish gray, (5Y 7/2), fine to medium grained, moderate HCl reaction, extremely weak to very weak (R0 to R1), surface pitting throughout entire section Silt (ML) 236.7-237.1' - yellowish gray, (5Y 7/2), mild HCl reaction, mottling present	R5: 9 minutes
			>10	219.9, 223.0' - Fractures, 60-90 deg, rough, undulating			
			4	221.5-221.8' - Fracture zone, fragments up to 1/2" in diameter			
			NR				
224.0	R6-HQ 5 ft 98%	43	>10	224.1, 225.1, 225.5, 226.1, 226.7, 227.1, 227.6, 228.3' - Mechanical break (8), rough to smooth, undulating		R6: 9 minutes	
			3	224.4-224.8' - Fracture zone, multiple breaks, angular fragments up to 1" in diameter			
			1				
			>10	227.7-228.0' - Fracture zone, smooth to rough, along bedding planes, horizontal along bedding planes to 40 deg			
	R7-HQ 5 ft 80%	60	>10	228.6' - Bedding plane, horizontal, smooth		R7: 12 minutes	
			NR				
			6				
			1	230.0-230.3' - Fracture zone, rough, angular rock fragments			
	R8-HQ 5 ft 96%	0	1	230.5, 231.8, 232.6, 232.8' - Mechanical break, 0-30 deg, rough, undulating		R8: 8 minutes	
			1	231.5' - Mechanical break			
			2	232.5' - Mechanical break			
			NR				
234.0	R8-HQ 5 ft 96%	0	>10	234.0, 234.6, 235.5-235.8, 236.1-236.7, 237.1-237.5, 237.8-238.8' - Fracture zone (6)			
			>10				
			>10				
			>10				
	R8-HQ 5 ft 96%	0	>10				
			>10				
			>10				
			>10				
239.0	R8-HQ 5 ft 96%	0	NR				
			1				
240							



PROJECT NUMBER: 338884.FL	BORING NUMBER: AD-02	SHEET 3 OF 15
ROCK CORE LOG		

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88) DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07 START : 9/8/2007 END : 9/12/2007 LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

WATER LEVELS : 3.0 ft bgs on 9/6/97				START : 9/6/2007		END : 9/12/2007		LOGGERS : J. Bakard, R. Brely, T. Burton, J. Townes	
DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN, LENGTH, AND RECOVERY (%)	DISCONTINUITIES				SYMBOLIC LOG	LITHOLOGY	COMMENTS	
		R Q D (%)	FRACTURES PER FOOT	DESCRIPTION	ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS		SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.		
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS					
-197.7	R9-HQ 5 ft 88%	53	2	239.5, 240.1, 241.6, 241.8, 242.3, 242.7, 243.0, 243.3' - Mechanical break, 0-10 deg, rough, undulating		Limestone 237.1-238.8' - yellowish gray, (5Y 7/2), fine to medium grained, moderate HCl reaction, extremely weak to very weak (R0 to R1), with 1/4" sections of very fine grain limestone No Recovery 238.8-239.0' Limestone 239.0-243.4' - pale greenish yellow, (10Y 8/2), fine to medium grained, moderate to strong HCl reaction, very weak (R1), surface pitting throughout section, trace voids (1/16") throughout section No Recovery 243.6-244.0' Limestone 244.0-249.0' - pale greenish yellow, (10Y 8/2), fine to medium grained, moderate to strong HCl reaction, very weak (R1), surface pitting throughout section, very brittle rock	R9: 7 minutes		
>10			241.1-241.3' - Fracture zone						
3									
1									
244.0		NR		244.0-244.7' - Fracture zone					
245	R10-HQ 5 ft 100%	22	>10	244.0-244.7' - Fracture zone			R10: 6 minutes		
-202.7			3	245.0, 245.5, 245.9, 246.1, 246.5, 246.8, 246.9, 247.3, 247.5, 247.8, 247.9' - Mechanical break (11), 0-10 deg, rough, undulating					
			4						
			4						
			>10	248.1-248.5, 248.7-250.0' - Fracture zone (2), rough, undulating					
249.0				249.4, 249.6, 250.1, 250.5, 251.6, 252.7' - Mechanical break (6), 0-30 deg, rough, undulating			R11: 9 minutes		
250	23	3	249.4, 249.6, 250.1, 250.5, 251.6, 252.7' - Mechanical break (6), 0-30 deg, rough, undulating						
-207.7		4							
		4	250.8-251.1' - Bedding plane, horizontal, smooth, undulating						
		6	252.3-252.4, 253.1-253.2' - Fracture zone (2), rough, undulating						
			3	253.0' - Bedding plane, horizontal, smooth					
254.0	R12-HQ 5 ft 100%	73	2	254.2, 254.3, 255.1, 255.2, 255.8, 256.3, 256.9, 257.2, 257.4, 257.7, 258.3, 258.8' - Mechanical break (12), smooth to rough, undulating to stepped			R12: 9 minutes		
			3						
			2						
			3						
			7	258.4-258.5' - Fracture zone, angular rock fragments					
259.0									
260			2						



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 4 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS		ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.
-217.7	R13-HQ 5 ft 96%	50	2	259.1, 259.5, 260.1, 260.7, 261.3, 261.4, 261.8, 263.2, 263.6' - Mechanical break (9), 0-10 deg, rough, undulating		259.0-263.8' - pale greenish yellow, (10Y 8/2), fine to medium grained, moderate to strong HCl reaction, very weak to weak (R1 to R2), surface cavity at 259.7 up to 3/4" wide and up to 1/4" in height, wavy bedding planes less than 1/16" in thickness throughout intact sections, voids to 1/16" over 5-10% of surface	R13: 8 minutes
			2				
			>10	262.1-262.2' - Fracture zone, angular rock fragments up to 1/2"			
			8	262.5-263.1' - Fracture zone, rough, undulating, 10 angular rock fragments up to 2" in diameter			
264.0	R14-HQ 5 ft 94%	40	>10	264.3-265.0' - Fracture zone, rough, undulating, up to 1" in length angular rock fragments		No Recovery 263.8-264.0' Limestone 264.0-266.9' - pale greenish yellow, (10Y 8/2), fine to medium grained, moderate to strong HCl reaction, very weak (R1), wavy bedding plane from 265.0-265.5' <1/16" in thickness, 1/16" voids over 0-5% of surface 266.9-267.5' - pale greenish yellow, (10Y 8/2), fine grained, moderate HCl reaction, very weak to weak (R1 to R2), wavy bedding planes 1/16" in thickness 267.6-268.7' - pale greenish yellow, (10Y 8/2), fine to medium grained, moderate to strong HCl reaction, very weak to weak (R1 to R2)	R14: 8 minutes
265			5	265.5, 265.7, 266.0, 266.1, 266.3, 266.6, 267.4, 267.7, 268.4' - Mechanical break (9), 0-20 deg, rough, undulating			
-222.7			4				
			5	267.0-267.2' - Fracture zone, rough, undulating, up to 1" in length angular rock fragments			
			1				
269.0	R15-HQ 5 ft 82%	33	NR	269.0-271.0' - Fracture zone		No Recovery 268.7-269.0' Limestone 269.0-271.9' - light olive gray, (5Y 5/2), fine to medium grained, moderate HCl reaction, very weak to weak (R1 to R2), with angular gravel-sized rock fragments 271.9-272.3' - yellowish gray, (5Y 7/2), fine grained, moderate to strong HCl reaction, very weak to weak (R1 to R2), trace voids 272.3-273.1' - yellowish gray, (5Y 8/1), moderate to strong HCl reaction, very weak to weak (R1 to R2), bedding planes transition from wavy to laminar No Recovery 273.1-274.0' Limestone 274.0-276.3' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, very weak (R1), solution cavities up to 1-3/8" by 3/8" over 1-2% of rock surface, bedding laminations with trace organics from 275.2-275.7' No Recovery 276.3-279.0'	SC-3 collected at 270.95- 272.35'
270			>10	269.8-269.9' - Fracture zone			
-227.7			>10				
			1	271.3, 272.3, 272.7, 273.0' - Mechanical break (4), 0-30 deg, rough, undulating to stepped			
			4				
274.0	R16-HQ 5 ft 46%	13	NR			274.0-276.3' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, very weak (R1), solution cavities up to 1-3/8" by 3/8" over 1-2% of rock surface, bedding laminations with trace organics from 275.2-275.7' No Recovery 276.3-279.0'	R15: 7 minutes End drilling for the day at 16:43, 09/08/07 Continue drilling 09/09/07, Water level 3' below ground surface
275			>10	274.3' - Fracture, horizontal, rough, undulating, tight			
-232.7			>10	274.45' - Fracture, 85 deg, rough, undulating, tight			
			>10	274.55-274.8' - Fracture zone, multiple intersecting fractures with rock fragments up to 1-3/16" in diameter			
			NR	275.0' - Bedding plane, horizontal, smooth, tight			
	NA	NA	NR	275.4' - Fracture, horizontal, rough, undulating, open (3/8"), organic layering		275.4-276.3' - Fracture zone, fragments up to 1-3/16" in diameter	R16: 11 minutes
			NR				
			NR				
279.0	NA	NA	NR	279.25' - Mechanical break, horizontal, rough, undulating			R. Bitely begins logging
280			NR				



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 5 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN, LENGTH, AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		R Q D (%)	FRACTURES PER FOOT	DESCRIPTION		ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS			
-237.7	R17-HQ 5 ft 82%	0	5	279.45' - Fracture, 60 deg, rough, undulating, tight		Sandy Silt (ML) 279.0-280.0' - yellowish gray to light olive gray, (5Y 7/2, 5Y 5/2), fine to medium grained, mild to moderate HCl reaction, trace laminated bedding Limestone 280.0-283.1' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, very weak (R1), voids up to 9/16" diameter over 3-4% of rock surface, poorly fossiliferous, bedding plane laminations from 282.0-283.1' No Recovery 283.1-284.0' Limestone 284.0-289.0' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, extremely weak to very weak (R0 to R1), voids up to 3/8" diameter over 5% of rock surface, solution cavities up to 1-3/16" in diameter over 5% of rock surface, poorly fossiliferous, trace bedding plane laminations, trace organics 289.0-291.6' - yellowish gray, (5Y 7/2), very fine to coarse grained, moderate HCl reaction, extremely weak to very weak (R0 to R1), voids up to 3/32" over 10% of rock surface, poorly fossiliferous, trace organics No Recovery 291.6-294.0' Limestone 294.0-297.9' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, extremely weak to very weak (R0 to R1), 60% carbonate sandy silt No Recovery 297.9-299.0'	R17: 9 minutes
			>10	279.65-280.0' - Fracture zone, multiple intersecting fractures with rock fragments up to 1-3/16" in diameter			
			7	280.3' - Fractures (2), 60 deg, rough, undulating, tight			
			NR	280.5' - Fracture, 30 deg, rough, undulating 280.7-280.8' - Fracture zone, slight brown staining, fragments up to 3/4" in diameter 280.95' - Fracture, 60 deg, rough, undulating, tight			
284.0	R18-HQ 5 ft 100%	46	>10	281.3' - Fracture, horizontal, rough, undulating, slight brown-black staining, open 1-3/16" calcite crystallization			R18: 9 minutes
			>10	281.55-281.8' - Fracture zone, fragments up to 3/4" in diameter			
			3	281.9, 282.05, 282.25, 282.45, 282.8, 282.85' - Bedding plane (6), horizontal, smooth			
			1	282.65' - Fracture, rough, undulating, open 284.25-284.4' - Fracture zone, multiple intersecting fractures with rock fragments up to 3/4" in diameter			
			1	284.75' - Fracture, 60 deg, rough, undulating, open to 3/8"			
			1	285.2' - Fracture, horizontal, rough, undulating, open from 1/2" to 1"			
285 -242.7	R19-HQ 5 ft 52%	22	>10	285.3' - Mechanical break 285.4' - Mechanical break or fracture, horizontal, rough, undulating			SC-4 collected at 289.75-290.55'
			>10	285.7-285.9' - Fracture zone, rock fragments up to 1-3/16"			
			>10	286.4, 286.45, 286.7' - Bedding plane (3), horizontal, smooth			
			NR	287.4' - Mechanical break, horizontal, rough, undulating, open to 3/8"			
			NR	288.1' - Fracture, horizontal, rough, undulating, tight 289.0-289.3' - Fracture zone, multiple intersecting fractures with rock fragments up to 1-3/16" in diameter			
			NR	289.8' - horizontal, rough, undulating, open to 3/8"			
289.0	R20-HQ 5 ft 78%	14	>10	290.6-291.6' - Fracture zone, rock fragments up to 1-9/16" in diameter			R19: 10 minutes
			>10	294.0-294.9' - Fracture zone, rock fragments up to 1-3/16" in diameter			
			>10	295.6-297.0' - Fracture zone, rock fragments up to 1-3/16" in diameter			
			>10	297.3' - Fracture, horizontal, rough, undulating, tight			
			NR				
			NR				
290 -247.7			>10	299.3' - Fracture, 45 deg, smooth, trace black organic staining, tight			R20: 19 minutes
			>10				
			>10				
			NR				
294.0			>10				
			>10				
			>10				
			NR				
295 -252.7			>10				
			>10				
			>10				
			NR				
299.0			>10				
			>10				
			>10				
			NR				
300			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				
			>10				
			>10				
			>10				
			NR				



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 6 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

WATER LEVEL: 30.8 ft bgs on 3/3/07		DISCONTINUITIES		SYMBOLIC LOG		LITHOLOGY		COMMENTS	
DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN, LENGTH, AND RECOVERY (%)	R Q D (%)	FRACTURES PER FOOT	DESCRIPTION		SYMBOLIC LOG	ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.	
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS					
-257.7	R21-HQ 5 ft 74%	11	3	299.5, 299.6, 300.2, 300.3' - Fractures (4), horizontal, rough, undulating, trace black organic staining, tight			Limestone 299.0-300.3' - yellowish gray, (5Y 7/2), very fine to medium grained, moderate HCl reaction, extremely weak (R0), black organic mottling over 20% of rock surface 300.3-300.7' - olive gray to yellowish gray, (5Y 3/2, 5Y 7/2), very fine grained, extremely weak (R0), organic content decreasing with depth from 1-3/16" lens of organic silt at 300.3' below ground surface, faint to mild organic odor, fossiliferous, transition to a carbonate silt with depth	R21: 12 minutes	
NA			301.0' - Fracture zone, rock fragments up to 3/4" in diameter						
NA			301.2' - Mechanical break, 20 deg 301.8-301.9, 302.2-302.7' - Fracture zone (2), rock fragments up to 3/4" in diameter						
NR									
304.0									
305	R22-HQ 5 ft 90%	40	>10	304.65, 305.4, 305.7, 306.35, 306.75' - Bedding plane or mechanical break (5), <10 deg, smooth to rough, planar to undulating			Sandy Silt (ML) 300.7-302.7' - yellowish gray, (5Y 7/2), low to medium plasticity, >50% silt, <50% limestone fragments as sand sized fraction No Recovery 302.7-304.0' Silt (ML) 304.0-304.6' - yellowish gray, (5Y 7/2), low to medium plasticity, mild to moderate HCl reaction, limestone fragments as sand sized fraction >50%	R22: 12 minutes	
10									
>10			305.95-306.35' - Fracture zone, rough, undulating to planar, rock fragments <2" in diameter						
0			306.9-307.0' - Fracture zone, rough, undulating, rock fragments <1" in diameter						
4									
NR			308.3-308.5' - Fracture zone, rough, undulating, rock fragments <1-1/2" in diameter						
309.0									
310	R23-HQ 5 ft 100%	58	>10	309.5-309.75' - Fracture zone, rough, undulating, silt lenses, rock fragments <2" in diameter			Limestone 304.6-305.1' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate to strong HCl reaction, extremely weak to weak (R0 to R2), light gray mottling over 40% of surface, moderately fossiliferous casts and molds (1/8-1/4"), laminated organics Silt (ML) 305.1-305.4' - Same as 304.0-304.6'	R23: 7 minutes	
3			310.25, 310.9' - Fractures or mechanical break (2), rough, undulating						
>10			310.5' - Fracture or mechanical break, 30 deg, rough, undulating						
6			312.0, 312.05, 312.1, 312.2' - Fractures (4), 0-90 deg, rough, undulating						
			312.45, 313.05, 313.45, 313.95' - Fractures or mechanical break (4), <10 deg, rough, undulating						
3									
314.0									
315	R24-HQ 5 ft 98%	30	2	314.9, 315.2' - Fractures or mechanical break (2), 10 deg and 40 deg, rough, undulating			Limestone 305.4-308.5' - Same as 304.6-305.1' No Recovery 308.5-309.0' Limestone 309.0-314.0' - yellowish gray, (5Y 7/2), fine to medium grained, moderate to strong HCl reaction, extremely weak to medium strong (R0 to R3), highly variable trace voids 1/16", poorly fossiliferous, trace organic lamination, laminated silty intervals from 311.35-311.5 and 311.65-311.8'	R24: 9 minutes	
2			315.7-316.75' - Fracture zone, rough, undulating, silt lenses, rock fragments <3" in diameter						
>10			317.1, 317.5' - Fractures or mechanical break (2), 70 deg and 50 deg, rough, undulating						
>10			317.5-317.9' - Fracture zone, rough, undulating, rock fragments <3" in diameter						
>10			318.2' - Fractures or mechanical break, <10 deg, rough, undulating						
NR									
319.0									
320									



PROJECT NUMBER: 338884.FL	BORING NUMBER: AD-02	SHEET 7 OF 15
ROCK CORE LOG		

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88) DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN, LENGTH, AND RECOVERY (%)	DISCONTINUITIES		SYMBOLIC LOG	LITHOLOGY		COMMENTS			
		R Q D (%)	FRACTURES PER FOOT		DESCRIPTION	ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.			
					DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS					
-277.7	R25-HQ 5 ft 100%	27	>10	318.65-318.9' - Fracture zone or mechanical break, rough, undulating, rock fragments <2" in diameter 319.3-319.8, 320.1-320.4, 320.6-320.8, 321.7-322.1, 322.35-322.65, 323.2-323.3' - Fracture zone (6), undulating, rock fragments <1" in diameter, friable 319.9, 321.1, 321.2, 321.3, 322.8, 323.8' - Fractures or mechanical break (6), 20 deg, rough, undulating	314.0-318.9' - yellowish gray, (5Y 7/2), fine to medium grained, moderate to strong HCl reaction, extremely weak to medium strong (R0 to R3), highly variable trace voids <1/16", poorly fossiliferous, trace organic laminations, interlaminated silt lenses and limestone rock fragments at 314.4-314.55' and 315.7-316.75' No Recovery 318.9-319.0' Limestone 319.0-324.0' - yellowish gray, (5Y 7/2), very fine to medium grained, moderate to strong HCl reaction, extremely weak to very weak (R0 to R1), with friable carbonate silts with <50% sand-sized limestone fragments, poorly fossiliferous 324.0-326.7' - yellowish gray, (5Y 7/2), very fine to fine grained, extremely weak to very weak (R0 to R1), trace laminated organics 325.1-325.7' - Same as 324.0-326.7' except mild to moderate HCl reaction, moderately fossiliferous, fossil shells to 1/2"	R25: 9 minutes				
324.0			10							
325 -282.7			R26-HQ 5 ft 100%				42	2	324.45, 324.95, 325.4, 325.8, 326.3' - Fractures or mechanical break (5), <10-30 deg, rough, undulating 326.7-329.0' - Fractures or mechanical break, smooth to rough, undulating	R26: 13 minutes
								2		
	2									
	NA									
330 -287.7	R27-HQ 5 ft 92%	67	NA							
			NA							
			>10	329.0-329.3' - Fracture zone, rough, undulating, rock fragments <1" in diameter 329.4, 329.45' - Fractures or mechanical break (2), 40 deg and 20 deg, rough, undulating 329.7, 330.4, 330.85, 331.9' - Bedding plane or mechanical break (4), <10 deg, rough, undulating 332.15-332.35' - Fracture zone, rough, undulating, rock fragments <2" diameter	SC-5 collected at 330.85-331.9'					
			2							
			1							
			>10							
334.0	0	R27: 8 minutes								
NR										
335 -292.7	R28-HQ 5 ft 88%	8	>10	334.4-334.5, 334.8-334.9, 335.1-335.25, 336.2-336.6, 336.6-337.0, 337.3-338.0, 338.25-338.4' - Fracture zone (7), rough, undulating, sandy silt lenses with rock fragments <2" in diameter 335.45, 335.7, 335.95' - Bedding plane or mechanical break (3), <10 deg, rough, undulating	R28: 12 minutes					
			>10							
			>10							
			>10							
			>10							
			>10							
339.0	NR	J. Townes begins logging								
	2									
340										



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 8 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS			
-297.7	R29-HQ 5 ft 94%	62	>10	339.4' - Mechanical break, horizontal, silt lens with angular rock fragments up to 3/4" in diameter		Limestone 334.0-338.4' - yellowish gray, (5Y 7/2), very fine to medium grained, moderate to strong HCl reaction, extremely weak (R0), silt lenses interbedded with extremely weak rock, 80% of core is sandy silt carbonate material of low to medium plasticity, >50% limestone fragments as sand fraction, trace decomposing organic odor No Recovery 338.4-339.0' Limestone 339.0-339.85' - yellowish gray, (5Y 7/2), very fine to medium grained, moderate HCl reaction, extremely weak to very weak (R0 to R1), limestone fragments up to 3/4" in diameter, calcite crystals, moderate yellow Organic Material (OH) 339.85-340.0' - dark brown to black, mild HCl reaction, organic layer, bedding laminations Limestone 340.0-340.4' - Same as 339.0-339.85' 340.4-343.7' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak (R1), black organic mottling over 20% of rock surface No Recovery 343.7-344.0' Limestone 344.0-349.0' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak to weak (R1 to R2), black and blue mottling over 20% or rock surface, trace laminations 349.0-353.85' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), trace laminated bedding with organics, cavities up to 3/8" in diameter are fossil burrows and over 10% of rock surface from 351.0-352.0' bgs. No Recovery 353.85-354.0' Limestone 354.0-359.0' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), voids up to 3/16" over 50% of rock surface and are fossil molds, cavities up to 2" in diameter over 1-2% of rock surface, fossiliferous	R29: 7 minutes
			2	339.6' - Mechanical break, horizontal, rough, undulating, along bedding plane			
			0	340.25-340.4' - Fracture zone or mechanical break, silt lens			
			1	341.35, 341.7' - Bedding plane (2), horizontal, fractures along contact of silt lens			
	R30-HQ 5 ft 100%	71	NR	343.25' - Fracture, horizontal, rough, undulating, tight		Limestone 340.0-340.4' - Same as 339.0-339.85' 340.4-343.7' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak (R1), black organic mottling over 20% of rock surface No Recovery 343.7-344.0' Limestone 344.0-349.0' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak to weak (R1 to R2), black and blue mottling over 20% or rock surface, trace laminations 349.0-353.85' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), trace laminated bedding with organics, cavities up to 3/8" in diameter are fossil burrows and over 10% of rock surface from 351.0-352.0' bgs. No Recovery 353.85-354.0' Limestone 354.0-359.0' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), voids up to 3/16" over 50% of rock surface and are fossil molds, cavities up to 2" in diameter over 1-2% of rock surface, fossiliferous	SC-6 collected at 347.8-348.8' R30: 7 minutes
345			1	344.8, 345.55, 345.9, 346.4, 346.6, 346.9, 347.45, 348.9' - Bedding plane (8), horizontal, rough, undulating, tight			
-302.7			2				
			3				
	R31-HQ 5 ft 97%	76	1			Limestone 340.0-340.4' - Same as 339.0-339.85' 340.4-343.7' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak (R1), black organic mottling over 20% of rock surface No Recovery 343.7-344.0' Limestone 344.0-349.0' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak to weak (R1 to R2), black and blue mottling over 20% or rock surface, trace laminations 349.0-353.85' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), trace laminated bedding with organics, cavities up to 3/8" in diameter are fossil burrows and over 10% of rock surface from 351.0-352.0' bgs. No Recovery 353.85-354.0' Limestone 354.0-359.0' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), voids up to 3/16" over 50% of rock surface and are fossil molds, cavities up to 2" in diameter over 1-2% of rock surface, fossiliferous	Complete drilling at 17:00 on 09/09/07, water level at surface
			1	350.35, 350.9, 351.85, 352.4' - Bedding plane or mechanical break (4), horizontal, rough, undulating, tight			
			2				
			1	352.9, 353.6' - Mechanical break (2), 0-90 deg, rough, undulating			
	R32-HQ 5 ft 100%	94	NR			Limestone 340.0-340.4' - Same as 339.0-339.85' 340.4-343.7' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak (R1), black organic mottling over 20% of rock surface No Recovery 343.7-344.0' Limestone 344.0-349.0' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak to weak (R1 to R2), black and blue mottling over 20% or rock surface, trace laminations 349.0-353.85' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), trace laminated bedding with organics, cavities up to 3/8" in diameter are fossil burrows and over 10% of rock surface from 351.0-352.0' bgs. No Recovery 353.85-354.0' Limestone 354.0-359.0' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), voids up to 3/16" over 50% of rock surface and are fossil molds, cavities up to 2" in diameter over 1-2% of rock surface, fossiliferous	R31: 10 minutes
			1	354.4, 357.0, 357.9' - Fractures (3), horizontal, rough, undulating, open up to 3/8"			
			0				
			1	356.3, 356.5' - Mechanical break (2)			
			1			Limestone 340.0-340.4' - Same as 339.0-339.85' 340.4-343.7' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak (R1), black organic mottling over 20% of rock surface No Recovery 343.7-344.0' Limestone 344.0-349.0' - light gray, (N7), very fine to medium grained, moderate to strong HCl reaction, very weak to weak (R1 to R2), black and blue mottling over 20% or rock surface, trace laminations 349.0-353.85' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), trace laminated bedding with organics, cavities up to 3/8" in diameter are fossil burrows and over 10% of rock surface from 351.0-352.0' bgs. No Recovery 353.85-354.0' Limestone 354.0-359.0' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), voids up to 3/16" over 50% of rock surface and are fossil molds, cavities up to 2" in diameter over 1-2% of rock surface, fossiliferous	R32: 11 minutes
			0				
			2				
360							



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 9 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS		ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.
-317.7	R33-HQ 5 ft 98%	62	2	359.6' - Mechanical break, horizontal, rough, undulating, 3/4" relief		Limestone 359.0-363.9' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate to strong HCl reaction, weak to medium strong (R2 to R3), voids up to 3/16" over 10% of rock surface and are fossil molds, cavities up to 3/4" in diameter over 1-2% of rock surface, trace organics, moderately fossiliferous	R33: 8 minutes
			1	359.8' - Mechanical break, vertical, rough, undulating			
			2	360.2' - Bedding plane, horizontal, rough, undulating, bedding plane fracture along organic layer			
			1	360.5, 361.3, 362.5, 362.9, 363.55' - Mechanical break, horizontal, rough, undulating			
364.0				361.5' - Mechanical break		No Recovery 363.9-364.0' Limestone 364.0-366.55' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), voids up to 3/16" over 10% of rock surface and are fossil molds, trace organic laminations, fossiliferous 366.55-368.55' - white to very light gray, (N9 to N8), very fine to fine grained, strong HCl reaction, medium strong (R3), voids up to 3/8" over 20% of rock surface and are fossil molds, cavities up to 1-3/16" over 5% of rock surface, fossiliferous 368.55-368.9' - Same as 364.0-366.55' No Recovery 368.9-369.0' Limestone 369.0-373.55' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, medium strong (R3), voids up to 3/8" over 20% of rock surface and are fossil molds, trace organic layering, moderately fossiliferous No Recovery 373.55-374.0' Limestone 374.0-378.5' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, medium strong (R3), voids up to 3/8" over 10% of rock surface and are fossil molds, trace organic layering, fossiliferous, cavities up to 9/16" over 1-2% of rock surface and are dissolution fossil molds No Recovery 378.5-379.0'	SC-7 collected at 367.3-368.3' R34: 9 minutes
365	R34-HQ 5 ft 98%	82	NR				
-322.7			1	364.6, 365.45' - Bedding plane, horizontal, rough, undulating			
			>10	366.5-366.65' - Fracture zone, rock fragments up to 3/4" in diameter			
			1	367.3, 368.3' - Mechanical break (2), horizontal, rough, undulating			
369.0							
370	R35-HQ 5 ft 91%	66	NR				R35: 8 minutes
-327.7			2	369.45, 369.85' - Fractures (2), horizontal, rough, undulating, tight			
			1	370.5' - Bedding plane, horizontal, smooth, tight, fracture along organic layering			
			>10	371.4-371.5' - Fracture zone, rock fragments up to 3/4" in diameter			
	R36-HQ 5 ft 90%	46	>10	372.1' - Fracture, horizontal, rough, undulating, tight			R36: 8 minutes
			0	372.8-373.1' - Fracture zone, rock fragments up to 1-9/16" in diameter			
374.0			NR				
375			4	374.25, 374.4, 374.75, 374.95, 375.3, 375.5, 376.45, 377.7, 378.15' - Mechanical break or bedding plane (9), horizontal, rough, undulating, tight			
-332.7	R36-HQ 5 ft 90%	46	2				R36: 8 minutes
			1				
			3	377.1, 377.35' - Mechanical break or bedding plane (2), horizontal, rough, undulating, tight			
			1				
379.0			NR				
380			>10	379.0-379.3' - Fracture zone, rock fragments up to 1-9/16" in diameter			



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 10 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88) DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS		ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.
-337.7	R37-HQ 5 ft 82%	36	3	379.6, 379.8, 380.0' - Fractures (3), horizontal, smooth, tight		Limestone 379.0-383.1' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, medium strong (R3), voids up to 3/8" over 20% of rock surface and are fossil molds, fossiliferous	R37: 8 minutes
			1	380.2-380.4' - Fracture zone, rock fragments up to 1-9/16" in diameter			
			>10	380.8, 381.4' - Fractures (2), horizontal, rough, undulating, open to 3/4"			
			0	382.7-382.9' - Fracture zone, rock fragments up to 1-9/16" in diameter			
384.0	R38-HQ 5 ft 88%	53	NR			No Recovery 383.1-384.0' 384.0-384.5' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), voids up to 3/16" over 20% of rock surface and are fossil molds, moderately fossiliferous 384.5-385.75' - light gray, (N7), very fine to coarse grained, strong HCl reaction, medium strong to strong (R3 to R4), voids up to 3/32" over 10% of rock surface and are fossil molds, cavities up to 3/8" over 3-5% of rock surface 385.75-385.95' - Same as 384.5-385.75' except organic laminated limestone 385.95-388.4' - Same as 384.0-384.5' No Recovery 388.4-389.0' Limestone 389.0-391.7' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, very weak (R1), voids up to 1/16" over 1-2% of rock surface, poorly fossiliferous, trace organic laminations No Recovery 391.7-394.0'	R38: 8 minutes
385			>10	384.0-384.5' - Fracture zone, rock fragments up to 1-9/16" in diameter			
-342.7			>10	384.7, 384.95' - Fractures (2), horizontal, rough, undulating, 3/4" relief			
			2	385.6-385.75' - Fracture zone, rock fragments up to 3/4" in diameter			
			1	386.2, 386.55, 387.15' - Fractures (3), horizontal, rough, undulating, 3/8" relief			
			0	386.4-386.8' - Mechanical break			
389.0	R39-HQ 5 ft 54%	9	NR			Limestone 394.0-399.0' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, very weak to weak (R1 to R2), voids up to 3/16" over 10% of rock surface and are fossil molds, moderately fossiliferous, trace laminations	R39: 8 minutes
			>10	389.0-389.9' - Fracture zone, rock fragments up to 1-9/16" in diameter			
390			>10	390.0' - Fracture, vertical, rough, undulating, tight			
-347.7			>10	390.1, 390.3' - Fractures (2), horizontal, rough, undulating, tight			
			>10	390.5-390.6' - Fracture zone, rock fragments up to 3/4" in diameter			
			NR	390.8, 391.95, 391.2' - Fractures (3), horizontal, rough, undulating, tight 391.5' - Mechanical break			
394.0	R40-HQ 5 ft 100%	46	1				R40: 6 minutes
395			3	395.0, 395.4, 395.75, 396.0, 396.4' - Fractures (5), horizontal, rough, undulating, tight to open			
-352.7			>10	396.7-397.1' - Fracture zone, rock fragments up to 1-3/16" in diameter			
			4	397.45, 397.65, 397.9' - Fractures (3), horizontal, rough, undulating, tight			
			>10	398.3-399.0' - Fracture zone, rock fragments up to 1-9/16" in diameter			
399.0			4				
400							



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 11 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DISCONTINUITIES						SYMBOLIC LOG		LITHOLOGY		COMMENTS	
DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN, LENGTH, AND RECOVERY (%)	R Q D (%)	FRACTURES PER FOOT	DESCRIPTION					ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.	
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS							
-357.7	R41-HQ 5 ft 69%	31	4	399.2, 399.6, 399.8, 400.0, 400.2, 400.4, 400.6, 400.9, 401.05, 401.45, 402.05' - Fractures (11), horizontal, rough, undulating, tight, to 3/8" relief					Limestone 399.0-402.45' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak (R2), voids up to 3/32" over 20% of rock surface and are fossil molds, moderately fossiliferous No Recovery 402.45-404.0'	R41: 6 minutes	
			2								
			1								
			NR								
404.0											
405	R42-HQ 5 ft 86%	25	3	404.5, 404.75, 404.9, 405.15, 405.35, 405.95, 406.1, 406.2, 406.4, 406.7, 406.85, 407.1' - Fractures (12), horizontal, rough, undulating, tight, open 406.0' - Fracture zone, fragments up to 1-9/16" in diameter 407.4-408.3' - Fracture zone, fragments up to 1-9/16" in diameter, quartz grains up to 3/8" found as infill material					Limestone 404.0-408.3' - yellowish gray, (5Y 7/2), very fine to fine grained, moderate HCl reaction, weak to medium strong (R2 to R3), voids up to 3/8" over 10% of rock surface and are fossil molds, secondary quartz mineralization found in fractured material near bottom of run, trace organic laminations near top of run No Recovery 408.3-409.0'	R42: 8 minutes	
-362.7			3								
			>10								
			>10								
			2								
			NR								
409.0											
410	R43-HQ 5 ft 100%	58	>10	409.1, 409.25, 409.45, 410.85, 411.35, 412.85, 413.2, 413.7, 413.9' - Bedding plane or mechanical break (9), <10 deg, rough, undulating, tight to open 1/2" 409.7-410.05' - Fracture zone, rough, undulating, rock fragments with carbonate silt matrix, fragments <1" in diameter					Limestone 409.0-414.0' - yellowish gray, (5Y 7/2), very fine to medium grained, strong HCl reaction, extremely weak to very weak (R0 to R1), laminated organics over 20% of rock surface, voids <1/16" over <10% of rock surface especially along bedding planes, trace cavities up to 1" diameter, carbonate silt and limestone fragments at 409.7-410.5', carbonate clay/silt with limestone fragments at 412.8-413.0'	Complete drilling at 15:15 on 09/10/07 due to proximal lighting, water level at surface R. Bitely begins logging R43: 8 minutes	
-367.7			1								
			1								
			1								
			3								
414.0											
415	R44-HQ 5 ft 94%	26	>10	414.5-415.0' - Fracture zone, rough, undulating, rock fragments <2" in diameter 415.2, 415.4, 416.35, 416.5, 418.35, 418.45, 418.55' - Bedding plane or mechanical break, <10 deg, rough, undulating, tight to open 1/2" 415.6-415.85' - Fracture zone, rough, undulating, rock fragments <2" in diameter 416.55-416.7, 417.1-417.15, 417.4-417.45, 417.65-418.05' - Fracture zone (4), rough, undulating, organic silt and rock fragments <2" in diameter with carbonate silt lenses interbedded.					414.0-416.6' - yellowish gray, (5Y 7/2), very fine to medium grained, moderate to strong HCl reaction, extremely weak to very weak (R0 to R1), voids <1/16" over 30% of surface, few cavities 1/2" in diameter, moderately fossiliferous Organic Elastic Silt To Organic Fat Clay (MH-CH) 416.6-417.4' - dark greenish gray, (5G 4/1), no HCl reaction, extremely weak (R0), laminated, poorly fossiliferous, moderate hydrogen sulfide odor	R44: 10 minutes	
-372.7			10								
			NA								
			NA								
			3								
			NR								
419.0											
420			>10								



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 12 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS		ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.
-377.7	R45-HQ 5 ft 88%	13	>10	419.0-419.4, 419.6-419.7, 419.8-420.4, 421.75-422.4, 422.65-423.4' - Fracture zone (5), silt infilling, rock fragments <2" in diameter		Limestone 417.4-418.7' - yellowish gray, (5Y 7/2), very fine to medium grained, moderate to strong HCl reaction, extremely weak to very weak (R0 to R1), voids <1/16" over 30% of surface, few cavities 1/2" in diameter, moderately fossiliferous No Recovery 418.7-419.0' Limestone 419.0-423.4' - yellowish gray, (5Y 7/2), very fine to medium grained, moderate HCl reaction, extremely weak to very weak (R0 to R1), interbedded carbonate silt lenses, voids <1/16" over 10% of surface, cavity up to 0.5' long from 421.75-422.25' with crystalline quartz growth, laminated bedding over 10% of surface No Recovery 423.4-424.0' Limestone 424.0-428.0' - yellowish gray, (5Y 7/2), very fine to medium grained, moderate HCl reaction, extremely weak to medium strong (R0 to R3), variable voids <1/16" over 30% of rock surface from 424.0-424.5', trace voids, <1/16" of remaining core, laminated organics from 424.5-424.8' over 20%, trace grayish blue (5PB 5/2) mottling over core from 425.6-427.0', all poorly fossiliferous No Recovery 428.0-429.0' Limestone 429.0-433.6' - yellowish gray to grayish black, (5Y 7/2 to N2), strong HCl reaction, extremely weak to medium strong (R0 to R3), organic lenses, organics as laminae and lenses up to 1" thick comprising 20% of core especially 432.0-432.6', mottled coloration along bedding planes, especially in stronger limestone, poorly fossiliferous, trace voids <1/16" No Recovery 433.6-434.0' Limestone 434.0-434.3' - light gray, (N7), very fine grained, mild HCl reaction, strong (R4) Organic Carbonate To Coal Seam 434.3-434.6' - black to greenish black, (N1 to 5GY 2/1), no HCl reaction, laminated, friable	R45: 8 minutes
424.0			>10	419.5, 420.6, 420.9, 421.65' - Bedding plane or mechanical break (4), <10 deg, rough, undulating, tight, open <1/2"			
425			>10				
-382.7			>10				
	R46-HQ 5 ft 80%	16	NR	424.5' - Bedding plane or mechanical break, horizontal, rough, undulating			R46: 12 minutes
425			>10	424.8-424.9, 425.1-425.6, 426.2-426.3, 427.1-428.0' - Fracture zone (4), rough, undulating, rock fragments <2" in diameter			
			>10	425.9, 426.75' - Fractures or mechanical break (2), <10 deg, rough, undulating, tight, open <1/2"			
429.0			NR				
430	R47-HQ 5 ft 92%	8	>10	429.3, 429.6' - Mechanical break (2), 50 deg and 60 deg		429.0-433.6' - yellowish gray to grayish black, (5Y 7/2 to N2), strong HCl reaction, extremely weak to medium strong (R0 to R3), organic lenses, organics as laminae and lenses up to 1" thick comprising 20% of core especially 432.0-432.6', mottled coloration along bedding planes, especially in stronger limestone, poorly fossiliferous, trace voids <1/16" No Recovery 433.6-434.0' Limestone 434.0-434.3' - light gray, (N7), very fine grained, mild HCl reaction, strong (R4) Organic Carbonate To Coal Seam 434.3-434.6' - black to greenish black, (N1 to 5GY 2/1), no HCl reaction, laminated, friable	R47: 15 minutes
-387.7			>10	429.85-430.15, 430.6-431.0, 431.8-432.7, 433.0-433.6' - Fracture zone (4), rough, undulating, rock fragments <2" in diameter			
			>10	431.2, 431.7' - Bedding plane or mechanical break (2), horizontal and 30 deg, smooth to rough, undulating, intersection at 431.2'			
			>10				
434.0	R48-HQ 5 ft 100%	48	NR			434.0-434.3' - light gray, (N7), very fine grained, mild HCl reaction, strong (R4) Organic Carbonate To Coal Seam 434.3-434.6' - black to greenish black, (N1 to 5GY 2/1), no HCl reaction, laminated, friable	SC-8 collected at 436.35-437.35'
435			NA	436.35' - Bedding plane or mechanical break, horizontal, rough, stepped to undulating, tight			
-392.7			NA	437.35' - Mechanical break			
			>10	438.25' - Bedding plane or mechanical break, horizontal, rough, stepped to undulating, tight			
			0	438.75, 438.9' - Fractures or mechanical break (2), 50 deg and 80 deg, rough, undulating			R48: 13 minutes
439.0			3				
440			>10				



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 13 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS			
-397.7	R49-HQ 5 ft 64%	11	>10	439.0-439.3, 439.5-440.15, 440.7-441.1, 441.9-442.2' - Fracture zone (4), rough, undulating, rock fragments <2" in diameter		Clay (CL) 434.6-436.2' - dark greenish gray, (5GY 4/1), carbonate, varve-like laminated organics, few silica nodules to subhedral quartz up to 1/2" diameter at 435.2' Limestone 436.2-439.0' - dark greenish gray, (5GY 4/1), very fine to fine grained, strong HCl reaction, medium strong to strong (R3 to R4), laminated, varve-like organic laminations, trace limestone casts or secondary carbonate mineralization up to 1" diameter, poorly fossiliferous 439.0-439.7' - yellowish gray, (5Y 7/2), mild HCl reaction, weak to medium strong (R2 to R3), with interbedded carbonate silt lenses, voids <1/16" over 20% of surface, poorly fossiliferous, 1/4" organic peat lens at 439.35' Silt (ML) 439.7-440.2' - medium plasticity, <50% limestone fragments as sand sized fraction, organic peat lens at 440.2' Limestone 440.2-441.25' - medium light gray to yellowish gray, (N6 to 5Y 7/2), mild HCl reaction, strong (R4), voids <1/16" over 30% of rock surface, cavities <1" diameter over 10% of surface, mottled coloration due to secondary mineralization of cavities, organic associated with cavities, with calcite crystals at 440.2-441.25' and 441.27-442.2' 441.25-442.2' - moderate yellowish brown, (10YR 5/4), very weak to weak (R1 to R2), faintly laminated organics No Recovery 442.2-444.0' Limestone 444.0-447.3' - medium light gray, (N6), very fine grained, strong HCl reaction, strong (R4), voids up to 3/32" over 20% of rock surface, cavities up to 9/16" over 1-2% of rock surface and some are filled with quartz crystallization No Recovery 447.3-449.0'	R49: 14 minutes
444.0			>10	444.0-445.5' - Fracture zone, multiple intersecting fractures with rock fragments up to 1-9/16" in diameter			
445			>10	445.1, 445.9' - Fractures (2), 45 deg, rough, undulating, tight			
-402.7	R50-HQ 5 ft 66%	7	3	446.4' - Fracture, 45 deg, rough, undulating, tight		Limestone 440.2-441.25' - medium light gray to yellowish gray, (N6 to 5Y 7/2), mild HCl reaction, strong (R4), voids <1/16" over 30% of rock surface, cavities <1" diameter over 10% of surface, mottled coloration due to secondary mineralization of cavities, organic associated with cavities, with calcite crystals at 440.2-441.25' and 441.27-442.2' 441.25-442.2' - moderate yellowish brown, (10YR 5/4), very weak to weak (R1 to R2), faintly laminated organics No Recovery 442.2-444.0' Limestone 444.0-447.3' - medium light gray, (N6), very fine grained, strong HCl reaction, strong (R4), voids up to 3/32" over 20% of rock surface, cavities up to 9/16" over 1-2% of rock surface and some are filled with quartz crystallization No Recovery 447.3-449.0'	R50: 16 minutes
445			0	446.5' - Mechanical break			
449.0			NR	446.9, 447.0' - Fractures (2), horizontal, rough, undulating, tight			
450	R51-HQ 5 ft 66%	24	3	449.45' - Fracture, 45 deg, rough, undulating, tight		Limestone 440.2-441.25' - medium light gray to yellowish gray, (N6 to 5Y 7/2), mild HCl reaction, strong (R4), voids <1/16" over 30% of rock surface, cavities <1" diameter over 10% of surface, mottled coloration due to secondary mineralization of cavities, organic associated with cavities, with calcite crystals at 440.2-441.25' and 441.27-442.2' 441.25-442.2' - moderate yellowish brown, (10YR 5/4), very weak to weak (R1 to R2), faintly laminated organics No Recovery 442.2-444.0' Limestone 444.0-447.3' - medium light gray, (N6), very fine grained, strong HCl reaction, strong (R4), voids up to 3/32" over 20% of rock surface, cavities up to 9/16" over 1-2% of rock surface and some are filled with quartz crystallization No Recovery 447.3-449.0'	J. Townes begins logging
-407.7			>10	449.7, 449.95' - Fractures (2), horizontal, rough, undulating, tight			
450			>10	450.5' - Fracture, horizontal, rough, undulating, tight			
454.0	R52-HQ 5 ft 82%	28	>10	450.9-451.2' - Fracture zone, rock fragments up to 1-9/16" in diameter		Limestone 440.2-441.25' - medium light gray to yellowish gray, (N6 to 5Y 7/2), mild HCl reaction, strong (R4), voids <1/16" over 30% of rock surface, cavities <1" diameter over 10% of surface, mottled coloration due to secondary mineralization of cavities, organic associated with cavities, with calcite crystals at 440.2-441.25' and 441.27-442.2' 441.25-442.2' - moderate yellowish brown, (10YR 5/4), very weak to weak (R1 to R2), faintly laminated organics No Recovery 442.2-444.0' Limestone 444.0-447.3' - medium light gray, (N6), very fine grained, strong HCl reaction, strong (R4), voids up to 3/32" over 20% of rock surface, cavities up to 9/16" over 1-2% of rock surface and some are filled with quartz crystallization No Recovery 447.3-449.0'	R51: 9 minutes
455			>10	451.6-452.3' - Fracture zone, rock fragments up to 1-9/16" in diameter			
-412.7			NR	454.0-455.5' - Fracture zone, multiple, high angle, intersecting fractures, rock fragments up to 2-3/8" in diameter			
459.0			>10	455.6, 456.0, 456.4, 456.9, 457.0, 457.1' - Fractures (6), horizontal, rough, undulating, tight		Limestone 440.2-441.25' - medium light gray to yellowish gray, (N6 to 5Y 7/2), mild HCl reaction, strong (R4), voids <1/16" over 30% of rock surface, cavities <1" diameter over 10% of surface, mottled coloration due to secondary mineralization of cavities, organic associated with cavities, with calcite crystals at 440.2-441.25' and 441.27-442.2' 441.25-442.2' - moderate yellowish brown, (10YR 5/4), very weak to weak (R1 to R2), faintly laminated organics No Recovery 442.2-444.0' Limestone 444.0-447.3' - medium light gray, (N6), very fine grained, strong HCl reaction, strong (R4), voids up to 3/32" over 20% of rock surface, cavities up to 9/16" over 1-2% of rock surface and some are filled with quartz crystallization No Recovery 447.3-449.0'	R52: 15 minutes
460			>10	456.6-456.7' - Fracture zone, rock fragments up to 3/4" in diameter			
			NR	457.45-457.65' - Fracture zone, rock fragments up to 1-3/16" in diameter			
			>10	459.0-459.3' - Fracture zone, rough, undulating, rock fragments <2" in diameter			



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 14 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS			
-417.7	R53-HQ 5 ft 80%	46	>10	459.9-460.05' - Fracture zone, rough, undulating, rock fragments <1" in diameter		Limestone 449.0-452.3' - light brownish gray to light brown, (5YR 6/1 to 5YR 6/4), very fine to fine grained, strong HCl reaction, strong (R4), carbonate sandy silt lens from 451.6-451.8' is extremely weak rock, voids up to 3/16" over 5% of rock surface and are filled with crystallization, trace organic laminations at 451.5' No Recovery 452.3-454.0'	R53: 14 minutes
			3	460.3-460.75' - Fracture zone, rough, undulating, rock fragments <3" in diameter, 2 vertical fractures from 460.4-460.7'			
			1	460.85, 461.25, 461.95, 462.3' - Bedding plane or mechanical break (4), rough, undulating, tight, open to <1/2"			
			NR	461.5' - Mechanical break			
464.0	R54-HQ 5 ft 78%	0	>10	464.3' - Fractures (3), horizontal and vertical, rough, undulating, tight, three intersecting fractures		454.0-458.1' - light brownish gray to light brown, (5YR 6/1 to 5YR 6/4), very fine to fine grained, strong HCl reaction, strong (R4), voids up to 3/16" over 5% of surface, trace organic laminations at 456.9' No Recovery 458.1-459.0' Limestone 459.0-463.0' - light gray to yellowish gray, (N7 to 5Y 7/2), very fine to fine grained, weak to strong (R2 to R4), voids <1/16" over <10% of rock, cavities <3/4" from 462.0-463.0', trace laminated organics, cavity infilling, crystalline growth of calcite/aragonite, very weak to weak transition from 461.25-461.55' No Recovery 463.0-464.0'	R54: 10 minutes
465			NA	464.6-465.4' - Fracture zone, rock fragments up to 1-3/16" in diameter			
-422.7			NA	465.6-465.9' - Fracture zone, rock fragments up to 3/4" in diameter			
			NA	466.2' - Bedding plane, horizontal, rough, undulating, tight			
			NR	466.5-467.9' - Fracture zone, rock fragments up to 1-9/16" in diameter			
469.0	R55-HQ 5 ft 98%	44	>10	469.0-469.6' - Fracture zone, multiple high angle, intersecting fractures, rock fragments up to 2-3/8" in diameter		464.0-464.9' - light brownish gray to light brown, (5YR 6/1 to 5YR 6/4), very fine to fine grained, strong HCl reaction, medium strong to strong (R3 to R4), trace organic increasing with depth, voids up to 3/32" over 1-2% of rock surface Silt With Limestone Fragments (ML) 464.9-465.9' - fine grained, strong HCl reaction, extremely weak (R0), with limestone fragments, high organic content, strong organic odor Limestone 465.9-466.5' - Same as 464.0-464.9'	R55: 12 minutes
470			3	469.9' - Fracture, horizontal, rough, undulating			
-427.7			2	470.1' - Bedding plane, horizontal, smooth, stepped, intersecting fractures, rock fragments up to 2-3/8" in diameter			
			2	470.2' - Fracture, 30 deg, rough, undulating, tight			
			1	470.5' - Fracture, 45 deg, rough, undulating, tight			
			NR	471.75, 472.0, 472.15, 472.75, 473.1' - Fractures (5), horizontal, rough, undulating, except 45 deg at 472.75'			
474.0	R56-HQ 5 ft 100%	36	3	474.3' - Fracture, horizontal, rough, undulating, tight		466.5-467.9' - Same as 464.9-465.9' No Recovery 467.9-469.0' Limestone 469.0-473.9' - light brownish gray to light brown, (5YR 6/1 to 5YR 6/4), very fine to fine grained, strong HCl reaction, medium strong to strong (R3 to R4), voids up to 3/16" over 20% of rock surface and are fossil molds, moderately fossiliferous, trace organics near top of run No Recovery 473.9-474.0'	Complete drilling at 17:00 on 09/11/07, water level at surface
475			4	474.7' - Fracture, 30 deg, rough, undulating, tight			
-432.7			>10	474.9' - Fracture, horizontal, rough, undulating			
			3	475.3' - Fracture, 30 deg, rough, undulating, tight			
			>10	475.9' - Fracture, horizontal, rough, undulating, high relief at 3/4"			
			1	475.6, 475.9' - Fractures (2), horizontal, rough, undulating, tight			
479.0			>10	476.4, 475.9' - Fracture zone, horizontal, rough, undulating, tight, rock fragments to 3/4"			R56: 15 minutes
480			1				



PROJECT NUMBER:

338884.FL

BORING NUMBER:

AD-02

SHEET 15 OF 15

ROCK CORE LOG

PROJECT : Progress Energy Florida - COLA Investigation, Levy County Site LOCATION : 1723982.5 N, 457716.6 E (NAD83)

ELEVATION : 42.3 ft (NAVD88)

DRILLING CONTRACTOR : Boart Longyear, Huntsville, AL; Driller: A. Anderson

CORING METHOD AND EQUIPMENT : BL300T S/N 1517, mud rotary, HQ tools, HW casing

ORIENTATION : Vertical

WATER LEVELS : 3.0 ft bgs on 9/08/07

START : 9/8/2007

END : 9/12/2007

LOGGER : J. Burkard, R. Bitely, T. Borton, J. Townes

DEPTH BELOW SURFACE AND ELEVATION (ft)	CORE RUN LENGTH AND RECOVERY (%)	DISCONTINUITIES			SYMBOLIC LOG	LITHOLOGY	COMMENTS
		RQD (%)	FRACTURES PER FOOT	DESCRIPTION			
				DEPTH, TYPE, ORIENTATION, ROUGHNESS, PLANARITY, INFILLING MATERIAL AND THICKNESS, SURFACE STAINING, AND TIGHTNESS		ROCK TYPE, COLOR, MINERALOGY, TEXTURE, WEATHERING, HARDNESS, AND ROCK MASS CHARACTERISTICS	SIZE AND DEPTH OF CASING, FLUID LOSS, CORING RATE AND SMOOTHNESS, CAVING ROD DROPS, TEST RESULTS, ETC.
-437.7	R57-HQ 5 ft 96%	37	4	476.75, 477.0, 477.65, 478.0, 478.35' - Fractures (5), horizontal, rough, undulating, tight		Limestone 474.0-479.0' - yellowish gray, (5Y 7/2), very fine to fine grained, mild to strong HCl reaction, medium strong to strong (R3 to R4), voids up to 3/16" over 10% of rock surface and are fossil molds, cavities up to 3/8" diameter over 1-2% of rock surface, moderately fossiliferous, secondary mineralization from 478.0-479.0' 479.0-483.8' - yellowish gray to light gray, (5Y 7/2 to N7), very fine to fine grained, mild to strong HCl reaction, medium strong to strong (R3 to R4), with and extremely weak carbonate sandy silt lens from 481.5-481.8', voids up to 3/8" over 10% of rock surface and are fossil molds, trace organics, moderately fossiliferous No Recovery 483.8-484.0'	R57: 12 minutes
			>10	478.6-478.8' - Fracture zone, rock fragments up to 1-3/16" in diameter			
			3	479.6, 480.15, 480.45, 480.6, 480.95, 481.25' - Fractures (6), horizontal, rough, undulating, tight			
			>10	481.5-481.8' - Fracture zone, rock fragments to 3/4" diameter			
484.0	R58-HQ 5 ft 76%	42	NR	481.9, 482.1, 482.75, 482.95, 483.2, 483.4' - Fractures (6), horizontal, rough, undulating, open to 3/4"		Limestone 484.0-487.8' - light brownish gray, (5YR 6/1), very fine to fine grained, mild to strong HCl reaction, strong (R4), voids up to 3/16" diameter over 20% of rock surface are fossil molds, quartz crystallization at 487.2', 1-9/16" diameter and contains carbonate crystallization No Recovery 487.8-489.0'	SC-9 collected at 485.8- 486.85'
			>10	482.85' - Fracture, vertical, rough, undulating, tight			
485			4	483.55-483.7' - Fracture zone, rock fragments up to 1-3/16" in diameter			
-442.7			2	484.0-484.5' - Fracture zone, rock fragments up to 2" in diameter			
			1	484.85, 485.0, 485.3, 485.4, 485.8, 486.9, 487.0' - Fractures (7), horizontal, rough, undulating, tight			
			NR	487.2' - Fracture, horizontal, rough, undulating, open to 3/4"			
489.0	R59-HQ 5 ft 81%	64	3	489.2' - Fracture, horizontal, rough, undulating, aragonite crystallization		Limestone 489.0-493.05' - light brownish gray, (5YR 6/1), very fine to fine grained, mild to strong HCl reaction, strong (R4), voids up to 3/16" over 10% of rock surface and are fossil molds, cavities up to 1-3/8" over 1% of rock surface are filled with carbonate crystallization and found from 489.0-490.0', moderately fossiliferous No Recovery 493.05-494.0'	R58: 11 minutes
			0	489.45, 489.9' - Fractures (2), horizontal, rough, undulating, tight			
490			>10	491.45-491.6' - Fracture zone, rock fragments up to 1-3/16" in diameter			
-447.7			1	492.4' - Fracture, horizontal, rough, undulating, tight			
	R60-HQ 6 ft 73%	19	NR			Limestone 494.0-498.4' - light brownish gray, (5YR 6/1), very fine to fine grained, mild to strong HCl reaction, medium strong to strong (R3 to R4), carbonate sandy silt, extremely weak rock from 497.3-497.9', voids up to 3/16" over 10% of rock surface and are fossil molds, cavities up to 9/16" diameter over 1% of rock surface and are filled with aragonite crystallization, trace organics No Recovery 498.4-500.0'	R59: 12 minutes
			5	494.2, 494.3, 494.45, 494.75, 495.1, 495.55, 495.9' - Fractures (7), horizontal, rough, undulating, trace brown staining, tight			
			4	495.65' - Fracture, vertical, rough, undulating, tight, intersecting with horizontal fractures at 495.55 and 495.9'			
			4	496.2, 496.45, 496.65' - Fractures (3), horizontal, rough, undulating, tight			
			>10	497.0' - Fracture, 0-90 deg, rough, undulating to stepped, tight			
			1	497.3-497.6' - Fracture zone, rock fragments up to 3/4", soft material			
	500.0		NR	498.15' - Fracture, horizontal, rough, undulating, tight			
500						Bottom of Boring at 500.0 ft bgs on 9/12/2007	R60: 10 minutes, 6' run to 500' below ground surface 9/12/07 at 10:30, total depth at 500.0' below ground surface