



Bank Erosion Hazard Index (BEHI)

Inventory and
prioritization of
eroding streambanks
within the
Choctawhatchee
River Watershed in
Florida using the
Bank Erosion Index
developed by Dr.
David Rosgen and
utilized by multiple
agencies including
the US Fish and
Wildlife Services.

0 2.5 5 10
Miles

Walton County Environmental/Engineering
This GIS data is not a legal representation of
the features depicted; any assumption of the
legal status of this data is hereby disclaimed.
<RESTORE Act - BEHI project>
<7.8.2013>, <MGates>

