

Salt Creek in Mexico Beach, FL







Sedimentation build-up & erosion at the culvert on west-side of Canal Parkway.



Erosion & dilapidated retaining walls. West side of Canal Parkway.



Erosion at culvert on east side of Canal Parkway.



Failing slope & erosion on east side of Canal Parkway.

