






Project begin at State Road 166




Erosion impacts due to SR 166 water runoff



Collapsing areas close to sidewalk and roadway





Collapsing areas encroaching toward roadway




Damage to private property due to erosion





Panoramic of drainage erosion impact to private







Picture view on outfall end of Riverview
Road structure looking East.







Riverview Rd. Box outfall



Looking South on SR 166.
Signal indicating Kelson Ave.



Upstream of Riverview Rd. Box

























